



report date: 2024-03-28

General information

Make	VAUXHALL
Model	COMBO 2000 L1H1 CDTI SPORTIVE
Colour	White
Year of manufacture	2014
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	67.3 mpg
Consumption combined	56.5 mpg
CO2 emission	133 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-08-08
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-23
MOT pass rate	54 %
MOT passed	7
Failed MOT tests	6
Total advice items	6
Total items failed	10

MOT #13	2023-08-24 15:08
MOT test number	583249839403
Result	✓ Passed
Next expiry date	2024-08-23
Advice	Rear Oil leak, but not excessive (8.4.1 (a) (i))

MOT #12	2023-08-24 13:03
MOT test number	939621847203
Result	✗ Failed
Fail	Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Fail	Nearside Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))
Advice	Rear Oil leak, but not excessive (8.4.1 (a) (i))

MOT #11	2022-08-16 09:53
MOT test number	412653310386
Result	✓ Passed
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #10** 2022-08-16 09:53**MOT test number** 611240589952**Result** ✗ Failed**Pass with rectification** Offside Side repeater not working (4.4.1 (a) (ii))**Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))**MOT #9** 2021-08-11 09:16**MOT test number** 712630504888**Result** ✓ Passed**MOT #8** 2021-08-03 08:16**MOT test number** 702315368577**Result** ✗ Failed**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**MOT #7** 2020-01-06 14:27**MOT test number** 944801787000**Result** ✓ Passed**MOT #6** 2020-01-02 10:09**MOT test number** 578575571886**Result** ✗ Failed**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #5** 2019-01-14 11:50**MOT test number** 475824294151**Result** ✓ Passed

**MOT #4** 2019-01-14 11:50**MOT test number** 202362477748**Result** ✗ Failed

Pass with rectification Parking (secondary brake) on a single line braking system has inadequate effort at a wheel (1.3.1 (a) (i))

MOT #3 2018-07-04 16:29**MOT test number** 449937560018**Result** ✓ Passed

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #2 2018-07-03 13:57**MOT test number** 371738251731**Result** ✗ Failed

Fail Nearside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))

Fail Offside Front Macpherson strut pin or bush excessively worn top bearing (5.3.4 (a) (i))

Fail Offside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))

MOT #1 2017-07-25 16:29**MOT test number** 108528673897**Result** ✓ Passed

Advice Oil leak Engine bay.



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
23 August 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	23 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 YD64KMU
Plate since	2019-06-29
Current registration	 YD64KMU
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2014-09-03
Last registration	2023-08-24
Complete history	See info



Registration #1	2014-09-03	8 mi
Registration #2	2017-07-25	44.799 mi
Registration #3	2018-07-03	51.396 mi
Registration #4	2018-07-04	51.397 mi
Registration #5	2019-01-14	52.728 mi
Registration #6	2019-01-14	52.728 mi
Registration #7	2020-01-02	58.597 mi
Registration #8	2020-01-06	58.602 mi
Registration #9	2020-01-06	58.602 mi
Registration #10	2020-01-06	58.602 mi
Registration #11	2020-01-06	58.602 mi
Registration #12	2020-01-06	58.602 mi
Registration #13	2020-01-06	58.602 mi
Registration #14	2020-01-06	58.602 mi
Registration #15	2020-01-06	58.602 mi

More info >



Additional information

Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	263A20005566978 LN9