




report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOURAN SE TDI DSG
Colour	Black
Year of manufacture	2012
Top speed	114 mph
0 - 100 km/h	12.8 seconds
0 - 60 mph	12.8 seconds
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	77 kW / 105 HP / 106 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.1 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg
CO2 emission	134 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-11-07
Pictures	19
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-01-17
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	26
Total items failed	2

MOT #11	2024-01-18 18:03
MOT test number	390792007997
Result	✓ Passed
Next expiry date	2025-01-17

MOT #10	2023-01-06 11:00
MOT test number	945534216791
Result	✓ Passed
Advice	Front Suspension arm pin or bush worn but not resulting in excessive movement Arm's rear pin or bush's (5.3.4 (a) (i))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #9	2022-01-14 14:12
MOT test number	271301832821
Result	✓ Passed

MOT #8	2020-11-13 16:05
MOT test number	587694970230
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge Bald on inside edge (5.2.3 (e))

**MOT #7**

2019-10-03 15:46

MOT test number

702218367475

Result

✓ Passed

Advice

Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened And offside rear (1.1.14 (a) (ii))

MOT #6

2018-11-24 11:29

MOT test number

845375490041

Result

✓ Passed

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice

Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice

Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #5

2017-11-24 14:23

MOT test number

204110125518

Result

✓ Passed

Advice

Child Seat fitted not allowing full inspection of adult belt

Advice

Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice

Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice

Nearside Rear Tyre worn close to the legal limit worn on inside edge (4.1.E.1)

**MOT #4**

2017-11-24 14:23

MOT test number

516067419757

Result**✗ Failed****Pass with rectification** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Tyre worn close to the legal limit worn on inside edge (4.1.E.1)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3**

2016-11-19 11:57

MOT test number

262012053784

Result**✓ Passed****Advice** Nearside Rear Seat belt anchorage prescribed area is distorted but not considered excessive (5.2.6)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Child Seat fitted not allowing full inspection of adult belt**MOT #2**

2015-11-30 09:26

MOT test number

570896646546

Result**✓ Passed****Advice** Rear Tyres wearing uneven on inner edges**MOT #1**

2015-11-30 09:26

MOT test number

712086950255

Result**✗ Failed****Advice** Rear Tyres wearing uneven on inner edges**Pass with rectification** Nearside Headlamp aim too low (1.8)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
17 January 2025

Tax status	Valid until 1 September
Days left	126
MOT expiry date	17 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 BD62SXX
Plate since	2019-06-29
Current registration	 BD62SXX
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-11-28
Last registration	2024-01-18
Complete history	See info



Registration #1	2012-11-28	20 mi
Registration #2	2015-11-30	36.594 mi
Registration #3	2015-11-30	36.594 mi
Registration #4	2016-11-19	53.034 mi
Registration #5	2017-11-24	70.147 mi
Registration #6	2017-11-24	70.147 mi
Registration #7	2018-11-24	85.070 mi
Registration #8	2019-05-20	95.277 mi
Registration #9	2019-05-20	95.277 mi
Registration #10	2019-05-20	95.277 mi
Registration #11	2019-05-20	95.277 mi
Registration #12	2019-05-20	95.277 mi
Registration #13	2019-05-20	95.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1794 mm
Height	1634 mm
Length	4397 mm
Wheel base	2678 mm
Kerb weight	1557 kg
Max. allowed weight	2250 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Number of axles	2
Engine number	CAYCT22302