



PEUGEOT

SVO7WYA

report date: 2024-03-28

General information

Make	PEUGEOT
Model	206 S
Colour	Silver
Year of manufacture	-
Top speed	112 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	133 Nm at 3.250 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	33.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	44.1 mpg





Internet history

Entry 1

Date	2021-09-15
Pictures	17
Listing price	View report



source: autotrader.co.uk

**MOT history****MOT #14**

2021-03-22 16:35

MOT test number

233463093601

Result

✓ Passed

Next expiry date

2022-03-27

- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside screen washer not working
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #13**

2021-03-22 11:35

MOT test number

422512821252

Result

✗ Failed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt insecure (6.1.7 (g) (ii))

Advice Nearside screen washer not working

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Advice Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Fail Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #12

2020-03-25 16:15

MOT test number

714458993253

Result

✓ Passed

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Bearing noise from front further investigation required

Advice Oil leak, but not excessive (8.4.1 (a) (i))



MOT #11

2019-03-27 13:25

MOT test number

505919700545

Result

✓ Passed

- Minor

Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice

Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice

Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice

Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor

Offside Obligatory mirror slightly damaged (3.3 (b) (i))
- Advice

Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice

Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice

Oil leak, but not excessive (8.4.1 (a) (i))
- Advice

Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #10**

2019-03-27 13:25

MOT test number

102339590774

Result

✗ Failed

Pass with rectification Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #9**

2018-03-24 12:50

MOT test number

228662087393

Result

✓ Passed

Advice Nearside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #8**

2017-03-25 12:32

MOT test number

130054490622

Result

✓ Passed

**MOT #7** 2016-03-22 13:10**MOT test number** 781630800209**Result** ✓ Passed**Advice** Offside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #6** 2015-03-28 09:45**MOT test number** 127007085019**Result** ✓ Passed**MOT #5** 2014-08-15 14:26**MOT test number** 919507624216**Result** ✓ Passed**MOT #4** 2013-08-07 13:53**MOT test number** 377519313252**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2012-03-13 10:29**MOT test number** 138363072452**Result** ✓ Passed**Notice** Both front tyres worn**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2011-03-16 09:14**MOT test number** 449905671001**Result** ✓ Passed



MOT #1	2010-06-24 13:53
MOT test number	262225470192
Result	✓ Passed



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2007-03-27
Last registration	2021-03-22
Complete history	See info



Registration #1	2007-03-27	24 mi
Registration #2	2010-06-24	18.582 mi
Registration #3	2011-03-16	19.499 mi
Registration #4	2012-03-13	24.457 mi
Registration #5	2013-08-07	30.186 mi
Registration #6	2014-08-15	37.172 mi
Registration #7	2015-03-28	42.702 mi
Registration #8	2016-03-22	54.086 mi
Registration #9	2016-03-22	54.086 mi
Registration #10	2016-03-22	54.086 mi
Registration #11	2016-03-22	54.086 mi
Registration #12	2016-03-22	54.086 mi
Registration #13	2016-03-22	54.086 mi
Registration #14	2016-03-22	54.086 mi
Registration #15	2016-03-22	54.086 mi
Registration #16	2016-03-22	54.086 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1720 mm
Height	1472 mm
Length	4030 mm
Wheel base	2540 mm
Kerb weight	1139 kg
Max. allowed weight	1640 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number	FE040452031
---------------	-------------