



report date: 2024-03-28

## General information

Make	VOLVO
Model	V50 D DRIVE SE
Colour	Silver
Year of manufacture	2012
Top speed	121 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	6.6 mpg
CO2 emission	99 g/km
CO2 label	A






Internet history

Entry 1

Date	2021-06-24
Pictures	27
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-08-19
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	20
Total items failed	12

MOT #14	2023-07-26 13:41
MOT test number	182049043207
Result	✓ Passed
Next expiry date	2024-08-19
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #13	2022-08-17 15:08
MOT test number	944208767371
Result	✓ Passed
Minor	Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #12	2022-08-16 10:17
MOT test number	762855881725
Result	✗ Failed
Minor	Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Fail	Offside Drive shaft bearing excessively worn drive shaft support bearing noisy (6.1.7 (b) (i))
Fail	Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**MOT #11** 2021-08-20 10:07**MOT test number** 234278000350**Result** ✓ Passed**MOT #10** 2021-03-05 16:30**MOT test number** 606878872967**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9** 2021-03-05 08:55**MOT test number** 178597310621**Result** ✗ Failed

- Fail** Nearside Body component damaged and likely to cause injury wing mirror (6.2.1 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**MOT #8** 2020-02-24 15:30**MOT test number** 232958144927**Result** ✓ Passed**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Nearside Non obligatory mirror damaged**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**MOT #7** 2020-02-24 11:12**MOT test number** 368888115389**Result** ✗ Failed**Advice** Nearside Non obligatory mirror damaged**Fail** Brakes imbalanced across an axle (1.2.1 (b) (i))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Fail** Reversing lamp inoperative (4.6.1 (a))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**MOT #6** 2019-02-22 09:11**MOT test number** 380480680900**Result** ✓ Passed**MOT #5** 2018-02-23 11:02**MOT test number** 889072046677**Result** ✓ Passed



MOT #4	2018-02-22 09:26
MOT test number	474783457838
Result	✗ Failed
Fail	Offside Front wheel bearing rough when rotated (2.5.A.2)
Advice	Nearside Rear Outer Brake pad(s) wearing thin (3.5.1g)
Advice	Offside Rear Outer Brake pad(s) wearing thin (3.5.1g)

MOT #3	2017-03-07 11:33
MOT test number	723275182380
Result	✓ Passed

MOT #2	2016-02-10 12:54
MOT test number	450281734558
Result	✓ Passed

MOT #1	2015-02-26 12:25
MOT test number	489397955009
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
19 August 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	93
<b>MOT expiry date</b>	19 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-03-06
Last registration	2023-07-26
Complete history	<a href="#">See info</a>



Registration #1	2012-03-06	27 mi
Registration #2	2015-02-26	31.385 mi
Registration #3	2016-02-10	40.322 mi
Registration #4	2017-03-07	50.434 mi
Registration #5	2018-02-22	64.193 mi
Registration #6	2018-02-23	64.209 mi
Registration #7	2019-02-22	77.045 mi
Registration #8	2020-02-24	89.856 mi
Registration #9	2020-03-20	95.377 mi
Registration #10	2020-03-20	95.377 mi
Registration #11	2020-03-20	95.377 mi
Registration #12	2020-03-20	95.377 mi
Registration #13	2020-03-20	95.377 mi
Registration #14	2020-03-20	95.377 mi
Registration #15	2020-03-20	95.377 mi
Registration #16	2020-03-20	95.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1433 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	2041867