





## General information

Make	HYUNDAI
Model	SANTA FE CRDI PREMIUM SE
Colour	Black
Year of manufacture	2013
Top speed	118 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed automatic

### Engine & fuel consumption

Power	194 BHP
Max. torque	436 Nm at 2.500 rpm
Engine capacity	2.199 сс
Cylinders	4
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	51.4 mpg
Consumption combined	41.5 mpg
CO2 emission	178 g/km
CO2 label	I







Internet history	
Entry 1	
Date	2021-01-31
Pictures	1
Listing price	View report



source: autoonline.co.uk



## MOT history

MOT expiry date	2024-12-03
MOT pass rate	60 %
MOT passed	9
Failed MOT tests	6
Total advice items	17
Total items failed	16

MOT #15	2023-11-27 12:10
MOT test number	510203905010
Result	✓ Passed
Next expiry date	2024-12-03

MOT #14	2023-11-27 09:10
MOT test number	489257652479
Result	🗙 Failed
Fail Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))	

MOT #13	2022-11-23 15:45
MOT test number	269486318542
Result	✓ Passed

MOT #12	2022-11-23 09:03
MOT test number	776887374634
Result	🗙 Failed
Fail Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	
<b>Fail</b> Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	





MOT #11	2021-12-04 17:09
MOT test number	915162782324
Result	✓ Passed
MOT #10	2021-03-26 09:25
MOT test number	862549163321
Result	✓ Passed

MOT #9		2021-03-25 14:31
MOT te	st number	766662570872
Result		🗙 Failed
Fail	Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	

MOT #8		2020-07-15 12:35
MOT test	number	794891138976
Result		✓ Passed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	





<b>MOT #7</b> 20	20-07-14 11:00
MOT test number	628528957172
Result	🗙 Failed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
<b>Fail</b> Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (i	i))
Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii))	
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))	
<b>Fail</b> Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))	

MOT #6	2019-05-28	3 11:47
MOT test	<b>number</b> 9179408	310881
Result	✓1	Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))	

MOT #5	2019-05-28 08:42
MOT test number	503464593829
Result	🗙 Failed
<b>Fail</b> Offside Suspension arm ball joint excessively worn (5.3.4 (a) (i))	
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
<b>Fail</b> Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))	
Advice Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14	(a) (ii))





MOT #4	2019-05-17 10:26
MOT test number	581466098920
Result	🗙 Failed
<b>Fail</b> Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))	
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)	)
<b>Fail</b> Nearside Position lamp not working (4.2.1 (a))	
<b>Fail</b> Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))	
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Fail Windscreen in an unacceptable condition (3.2 (c) (i))	

MOT #3	2018-05-15 09:37
MOT test number	933370158755
Result	✓ Passed

MOT #2	2017-05-16 11:18
MOT test number	248631020996
Result	✓ Passed
MOT #1	2016-05-18 12:25
MOT test number	794168883563
Result	✓ Passed



Tax & MOT check

✓ Taxed	✓ MOT Expires:
1 September 2024 Tax status	3 December 2024 Valid until 1 September
Days left	125
MOT expiry date	3 December 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-





#### Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	Lamp
Туре	
Damage 2	AMPLI
Damage 2	E E H - S - A
Date	*
Category	AMP.
Туре	

#### Extra HYUNDAI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711





#### Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	
*********	
*******	
*******	
*********	
********	
	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	
Plate since	
Exercised coupledcodings	
Carrier representation	

More info >





#### Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





## Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2013-05-18
Last registration	2023-11-27
Complete history	See info



Registration #1	2013-05-18	24 mi
Registration #2	2016-05-18	23.551 mi
Registration #3	2017-05-16	35.231 mi
Registration #4	2018-05-15	46.548 mi
Registration #5	2019-05-17	56.658 mi
Registration #6	2019-05-28	57.012 mi
Registration #7	2019-05-28	57.014 mi
Registration #8	2020-07-14	66.822 mi
Registration #9	2020-07-15	66.824 mi
Registration #10		11.777 esi
Registration #11		11.777 esi
Registration #12		11.777 esi
Registration #13		11.777 esi
Registration #14		11.777 esi
Registration #15		11.777 esi
Registration #16		11.777 est
Registration #17		
Registration #17		





## Car features

S0225	Air conditioning
\$0295	
50482	
\$0501	
\$0566	
\$0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	96%
Children	89%
Pedestrian	71%
Safety systems	86%
Overall rating	89%
Video	<u>see crash video</u>



Dimensions & weight	
Width	1880 mm
Height	1680 mm
Length	4690 mm
Wheel base	2700 mm
Kerb weight	2001 kg
Max. allowed weight	2600 kg
Additional information	
Fuel tank capacity	64
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 13/13

Number of axles	
-----------------	--

#### **Engine number**

# D4HBDU824233