



report date: 2024-03-28

General information

Make	NISSAN
Model	ALMERA SVE
Colour	Blue
Year of manufacture	2003
Top speed	109 mph
0 - 60 mph	12.5 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	114 BHP
Max. torque	163 Nm at 4.000 rpm
Engine capacity	1.769 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.7 mpg
Consumption extra urban	45.6 mpg
Consumption combined	36.2 mpg
CO2 emission	187 g/km
CO2 label	J





Internet history

Entry 1

Date	2022-06-22
Pictures	24
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-24
MOT pass rate	81 %
MOT passed	17
Failed MOT tests	4
Total advice items	24
Total items failed	11

MOT #21	2023-07-25 12:25
MOT test number	192359734094
Result	✓ Passed
Next expiry date	2024-07-24
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Suspension component mounting prescribed area is corroded but not considered excessive cross number (5.3.6 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #20**

2023-07-24 12:41

MOT test number

798153501326

Result**✗ Failed**

- Fail** Offside Front Service brake excessively binding (1.2.1 (f))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Headlamp light intensity severely reduced (4.1.4 (a))
- Fail** Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))
- Advice** Front Suspension component mounting prescribed area is corroded but not considered excessive cross member (5.3.6 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Offside Front Headlamp has a product on the light source which changes emitted colour to other than white or yellow (4.1.4 (b))

MOT #19

2022-06-21 13:14

MOT test number

390113443587

Result**✓ Passed**

- Advice** Registration plate deteriorated but not likely to be misread Both (0.1 (b))
- Advice** Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security Both inner sill (6.2.2 (d) (i))

MOT #18

2021-07-07 11:49

MOT test number

977146326469

Result**✓ Passed****MOT #17**

2021-07-07 11:49

MOT test number

830085461047

Result**✗ Failed**

- Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))



MOT #16	2020-06-18 08:21
MOT test number	409983029815
Result	✓ Passed
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #15	2020-06-17 08:26
MOT test number	554595760837
Result	✗ Failed
Fail	Exhaust has a major leak of exhaust gases rear box (6.1.2 (a))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Fail	Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Fail	Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #14	2019-06-11 08:46
MOT test number	805115459565
Result	✓ Passed
Advice	Exhaust has a minor leak of exhaust gases rear silencer (6.1.2 (a))

MOT #13	2018-06-19 08:37
MOT test number	167712200392
Result	✓ Passed
Advice	Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Headlamp has a product on the lens but not seriously reducing light output BOTH SIDES TARNISHED (4.1.4 (b))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #12** 2017-06-15 08:00**MOT test number** 439073612726**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit BOTH SIDES (4.1.E.1)**Advice** Exhaust has a minor leak of exhaust gases FRONT PIPE (7.1.2)**MOT #11** 2016-06-22 08:51**MOT test number** 498203388421**Result** ✓ Passed**Advice** Front crossmember corroding**Advice** Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive sills both sides (2.4.A.3)**MOT #10** 2015-06-11 09:36**MOT test number** 347762765108**Result** ✓ Passed**MOT #9** 2014-06-27 09:59**MOT test number** 459438274187**Result** ✓ Passed**MOT #8** 2013-06-17 09:19**MOT test number** 348788063197**Result** ✓ Passed**MOT #7** 2012-06-25 16:13**MOT test number** 627217772195**Result** ✓ Passed

**MOT #6** 2012-06-25 10:18**MOT test number** 169657072108**Result** ✗ Failed**Fail** Nearside Front Shock absorber has a serious fluid leak (2.7.3)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #5** 2011-07-04 14:05**MOT test number** 699155381108**Result** ✓ Passed**MOT #4** 2010-06-02 15:17**MOT test number** 464383950116**Result** ✓ Passed**MOT #3** 2009-06-11 09:00**MOT test number** 990292669112**Result** ✓ Passed**MOT #2** 2008-06-07 09:27**MOT test number** 142409358109**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2007-06-04 15:54**MOT test number** 993755157153**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Offside front tyre worn uneven.



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
24 July 2024

Tax status	Valid until 1 August
Days left	93
MOT expiry date	24 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	LY03OSK
Plate since	2019-03-28
Current registration	LY03OSK
Plate since	2019-03-28

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2003-08-16
Last registration	2023-07-25
Complete history	See info



Registration #1	2003-08-16	12 mi
Registration #2	2007-06-04	16.797 mi
Registration #3	2008-06-07	17.959 mi
Registration #4	2009-06-11	20.470 mi
Registration #5	2010-06-02	22.742 mi
Registration #6	2011-07-04	24.645 mi
Registration #7	2012-06-25	26.392 mi
Registration #8	2012-06-25	26.392 mi
Registration #9	2013-06-17	28.128 mi
Registration #10	2014-06-27	29.728 mi
Registration #11	2015-06-11	30.484 mi
Registration #12	2016-06-22	31.298 mi
Registration #13	2016-06-22	31.298 mi
Registration #14	2016-06-22	31.298 mi
Registration #15	2016-06-22	31.298 mi
Registration #16	2016-06-22	31.298 mi
Registration #17	2016-06-22	31.298 mi
Registration #18	2016-06-22	31.298 mi
Registration #19	2016-06-22	31.298 mi
Registration #20	2016-06-22	31.298 mi
Registration #21	2016-06-22	31.298 mi
Registration #22	2016-06-22	31.298 mi
Registration #23	2016-06-22	31.298 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1706 mm
Height	1448 mm
Length	4184 mm
Wheel base	2535 mm
Kerb weight	1199 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	290994