





report date: 2024-03-28

General information

Make	PEUGEOT
Model	RCZ HDI GT
Colour	Blue
Year of manufacture	2011
Top speed	137 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	163 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	41.5 mpg
Consumption extra urban	62.8 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	Е



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1

Date 2021-08-03

Pictures 56

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



YH61YWC report date: 2024-03-28

MOT history

MOT expiry date	2025-01-02
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	17
Total items failed	13

MOT #15		2024-01-03 15:37
MOT test	number	975733877451
Result		✓ Passed
Next expi	ry date	2025-01-02
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))	
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))	

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #14 2023-12-18 13:05

MOT test number 307311769029

Result X Failed

Fail Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #13 2022-12-05 08:43

MOT test number 186930479700

Result \(\sqrt{Passed} \)

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12 2021-12-16 15:52

MOT test number 327881150771

Result ✓ Passed

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT test number

Result

Fail Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Fail Rear Registration plate inscription illegible (0.1 (b))

Advice Fluid leak, but not excessive (8.4.1 (a) (i))

 MOT #10
 2021-06-17 12:39

 MOT test number
 443029525710

 Result
 ✓ Passed

 Advice
 Oil leak, but not excessive [engine] (8.4.1 (a) (i))

MOT #9 2020-06-18 12:32 **MOT test number** 518578703954 Result ✓ Passed **MOT #8** 2020-06-18 09:01 **MOT** test number 948888265426 Result × Failed Fail Offside Front Headlamp aim too high (4.1.2 (a)) Fail Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

MOT #7	2019-07-03 11:25
MOT test number	347793140280
Result	✓ Passed

CarCheck.co.uk page 5/13



Fail

Advice

YH61YWC report date: 2024-03-28

MOT #6 2018-09-15 10:17 448409433740 **MOT** test number Result ✓ Passed MOT #5 2017-09-09 10:10 **MOT** test number 615933108884 Result ✓ Passed MOT #4 2017-09-09 07:48 829566694201 **MOT test number** Result × Failed Fail Rear Brake pad(s) less than 1.5 mm thick (3.5.1g) Fail Offside Front coil spring broken (2.4.C.1a) Fail Rear brake disc in such a condition that it is seriously weakened (3.5.1i)

MOT #3	2016-08-27 11:28
MOT test number	777099364602
Result	✓ Passed
MOT #2	2015-08-27 14:46
MOT test number	439499119692
Result	✓ Passed
MOT #1	2014-09-02 15:52
MOT test number	377355644480
Result	✓ Passed
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	

Nearside Front Anti-roll bar has excessive play in a ball joint (2.4.G.2)

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 June
Days left	34
MOT expiry date	2 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

Owner history		
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full re		SEOT

	More info	>
Plate changes		
See in this check if this PEUGEOT had different number plates.		
Number of plates		
Current registration	NK NA	
Plate since		
Current registration	NK NK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



YH61YWC report date: 2024-03-28

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courte et info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-09-30
Last registration	2024-01-03
Complete history	See info



Registration #1	2011-09-30	11 mi
Registration #2	2014-09-02	32.602 mi
Registration #3	2015-08-27	50.384 mi
Registration #4	2016-08-27	66.966 mi
Registration #5	2017-09-09	85.015 mi
Registration #6	2017-09-09	85.015 mi
Registration #7	2018-09-15	102.607 mi
Registration #8	2019-07-03	106.487 mi
Registration #9	2020-06-18	111.000 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		11.777 es
Registration #14		71.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.117 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	82%
Children	81%
Pedestrian	53%
Safety systems	83%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	2107 mm
Height	1352 mm
Length	4290 mm
Kerb weight	1445 kg
Max. allowed weight	1825 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4
Number of axles CarCheck.co.uk	2 page 13/13

Engine number

DYXR4007019