



report date: 2024-03-28

General information

Make	KIA
Model	CARENS LS CRDI
Colour	Silver
Year of manufacture	2007
Top speed	116 mph
0 - 60 mph	11.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	305 Nm at 2.500 rpm
Engine capacity	1.991 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	46.3 mpg
CO2 emission	163 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-09-28
Pictures	4
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2021-11-22
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	20
Total items failed	19

MOT #17	2020-11-23 16:37
MOT test number	189695922452
Result	✓ Passed
Next expiry date	2021-11-22
Advice	Offside Front Nail in tyre

MOT #16	2020-11-11 10:15
MOT test number	848258398090
Result	✗ Failed
Fail	Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
Advice	Offside Front Nail in tyre
Fail	Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
Fail	Service brake efficiency below requirements (1.2.2 (a) (i))

MOT #15	2019-06-03 13:04
MOT test number	983733502798
Result	✓ Passed
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
Advice	Front Brake pad(s) wearing thin replace soon (1.1.13 (a) (ii))



MOT #14	2019-05-25 08:23
MOT test number	482433485762
Result	✗ Failed
Fail	Nearside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
Fail	Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Advice	Front Brake pad(s) wearing thin replace soon (1.1.13 (a) (ii))
Fail	Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
Fail	Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
Fail	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #13	2018-06-22 09:56
MOT test number	523189978372
Result	✓ Passed

**MOT #12**

2018-05-31 15:16

MOT test number

629654628053

Result**✗ Failed**

- Fail** Brake pedal has insufficient reserve travel (1.1.2 (a))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front Headlamp aim too low (4.1.2 (a))
- Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Front Headlamp aim too low (4.1.2 (a))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #11

2017-06-02 15:28

MOT test number

489569435232

Result**✓ Passed**

- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #10**

2017-05-26 09:05

MOT test number

284280997292

Result**✗ Failed****Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Front coil spring broken (2.4.C.1a)**Advice** Offside Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Fail** Offside Stop lamp not working (1.2.1b)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Stop lamp not working (1.2.1b)**MOT #9**

2016-05-17 14:56

MOT test number

304969748040

Result**✓ Passed****Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #8**

2016-05-13 15:08

MOT test number

543956429438

Result**✗ Failed****Fail** Nearside Front Brake hose seriously damaged (found during steering lock to lock check) (2.2.D.2b)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Fail** Nearside Headlamp aim too high (1.8)**MOT #7**

2015-05-16 13:18

MOT test number

279136935430

Result**✓ Passed**

**MOT #6** 2014-04-10 14:45**MOT test number** 196370604118**Result** ✓ Passed**Notice** Both rear tyres wearing on inner or outer edges**MOT #5** 2013-04-04 11:59**MOT test number** 818864993008**Result** ✓ Passed**MOT #4** 2012-05-02 17:34**MOT test number** 289713822103**Result** ✓ Passed**MOT #3** 2011-11-09 10:33**MOT test number** 317643411398**Result** ✓ Passed**MOT #2** 2010-11-15 12:47**MOT test number** 740229110385**Result** ✓ Passed**MOT #1** 2010-11-15 11:00**MOT test number** 970749110389**Result** ✗ Failed**Fail** Parking brake lever has no reserve travel (3.1.6b)



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-11-30
Last registration	2020-11-23
Complete history	See info



Registration #1	2007-11-30	19 mi
Registration #2	2010-11-15	18.242 mi
Registration #3	2010-11-15	18.246 mi
Registration #4	2011-11-09	25.618 mi
Registration #5	2012-05-02	28.229 mi
Registration #6	2013-04-04	37.711 mi
Registration #7	2014-04-10	49.177 mi
Registration #8	2015-05-16	58.040 mi
Registration #9	2016-05-13	65.136 mi
Registration #10	2016-05-17	65.137 mi
Registration #11	2016-05-20	65.137 mi
Registration #12	2016-05-20	65.137 mi
Registration #13	2016-05-20	65.137 mi
Registration #14	2016-05-20	65.137 mi
Registration #15	2016-05-20	65.137 mi
Registration #16	2016-05-20	65.137 mi
Registration #17	2016-05-20	65.137 mi
Registration #18	2016-05-20	65.137 mi
Registration #19	2016-05-20	65.137 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1720 mm
Length	4545 mm
Wheel base	2700 mm
Kerb weight	1657 kg
Max. allowed weight	2255 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	D4EA7H27840