



report date: 2024-03-28

General information

Make	KIA
Model	RIO DOMINO
Colour	White
Year of manufacture	2011
Top speed	108 mph
0 - 60 mph	11.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	96 BHP
Max. torque	125 Nm at 4.700 rpm
Engine capacity	1.399 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.9 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-02-01
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-04-07
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	50
Total items failed	3

MOT #152023-04-06 08:14

MOT test number705828177207

Result✓ Passed

Next expiry date2024-04-07

- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush starting to lift from the arm (5.3.4 (a) (i))
- Advice** Nearside Rear Nail in tyre
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front headlight broken
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #14**

2023-04-05 13:51

**MOT test number**

987885194289

**Result****✗ Failed**

- Advice** Nearside Rear Nail in tyre
- Advice** Nearside Front headlight broken
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- MAJOR** Front Windscreen washer not working (3.5 (a))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor** Nearside Rear Tyre obviously under inflated (5.2.3 (l))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush starting to lift from the arm (5.3.4 (a) (i))

**MOT #13**

2022-03-16 15:55

**MOT test number**

732801742101

**Result****✓ Passed**

- Minor** Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #12**

2021-04-08 13:35

**MOT test number**

357917913287

**Result****✓ Passed**

- Advice** Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))

**MOT #11** 2020-07-06 10:22**MOT test number** 329454180516**Result** ✓ Passed**MOT #10** 2020-07-06 10:22**MOT test number** 712682667951**Result** ✗ Failed**Pass with rectification** Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))**Pass with rectification** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**MOT #9** 2020-06-29 16:04**MOT test number** 131539372901**Result** ✗ Failed**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement lower arm front bush (5.3.4 (a) (i))**Advice** Central Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**MAJOR** Electronic stability control warning lamp indicates a fault (7.12 (e))**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement lower arm front bush (5.3.4 (a) (i))**MAJOR** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**MAJOR** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**MAJOR** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #8** 2019-02-16 09:19**MOT test number** 633512777898**Result** ✓ Passed**MOT #7** 2018-05-25 16:15**MOT test number** 148384953412**Result** ✓ Passed

- Advice** Rear Tyre slightly damaged/cracking or perishing Both rear tyres (5.2.3 (d) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn on edges (5.2.3 (e))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Front Tyre slightly damaged/cracking or perishing Both front tyres (5.2.3 (d) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on edges (5.2.3 (e))
- Advice** Spare tyre defective

**MOT #6** 2018-05-25 11:40**MOT test number** 847114378728**Result** ✗ Failed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn on edges (5.2.3 (e))
- MAJOR** Windscreen washer not working (3.5 (a))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Front Tyre slightly damaged/cracking or perishing Both front tyres (5.2.3 (d) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on edges (5.2.3 (e))
- Advice** Spare tyre defective
- MAJOR** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Rear Tyre slightly damaged/cracking or perishing Both rear tyres (5.2.3 (d) (i))

**MOT #5** 2017-05-17 13:05**MOT test number** 268278493335**Result** ✓ Passed**MOT #4** 2016-05-26 13:48**MOT test number** 737876570561**Result** ✓ Passed**Advice** Both Exhaust Flexi and Mid section Hangers corroded and nearly broken off.**MOT #3** 2015-05-26 10:46**MOT test number** 465506445104**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2014-05-22 09:30**MOT test number** 557052244130**Result** ✓ Passed**MOT #1** 2014-05-19 11:35**MOT test number** 238539134431**Result** ✗ Failed**Fail** Nearside Front Suspension arm ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.4.G.2)



Tax & MOT check

✓

Taxed

Tax due:  
1 April 2025

✗

MOT

Expired:  
7 April 2024

Tax status	Valid until 1 April
Days left	337
MOT expiry date	7 April 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	YR11XKG
Plate since	2024-03-28
Current registration	YR11XKG
Plate since	2024-03-28

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-05-28
Last registration	2023-04-06
Complete history	<a href="#">See info</a>



Registration #1	2011-05-28	28 mi
Registration #2	2014-05-19	17.059 mi
Registration #3	2014-05-22	17.094 mi
Registration #4	2015-05-26	25.448 mi
Registration #5	2016-05-26	36.359 mi
Registration #6	2017-05-17	43.292 mi
Registration #7	2018-05-25	51.786 mi
Registration #8	2018-05-25	51.786 mi
Registration #9	2019-02-16	58.128 mi
Registration #10	2019-05-28	58.128 mi
Registration #11	2019-05-28	58.128 mi
Registration #12	2019-05-28	58.128 mi
Registration #13	2019-05-28	58.128 mi
Registration #14	2019-05-28	58.128 mi
Registration #15	2019-05-28	58.128 mi
Registration #16	2019-05-28	58.128 mi
Registration #17	2019-05-28	58.128 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1695 mm
Height	1470 mm
Length	3990 mm
Wheel base	2500 mm
Kerb weight	1244 kg
Max. allowed weight	1580 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	G4EEAH382395