



RENAULT



report date: 2024-03-28

General information

Make	RENAULT
Model	MASTER LH35 DCI H/R P/V
Colour	White
Year of manufacture	2010
Top speed	82 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	310 Nm at 2.500 rpm
Engine capacity	2.298 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.4 mpg
Consumption extra urban	38.6 mpg
Consumption combined	34.8 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-11-10
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-11-14
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	17
Total items failed	18

MOT #16	2023-11-15 15:06
MOT test number	546217346563
Result	✓ Passed
Next expiry date	2024-11-14
Advice	Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
Minor	Offside Rear Position lamp has a product on the lens or light source which obviously reduces light intensity (4.2.3 (b) (i))
Minor	Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))

MOT #15	2023-11-14 09:47
MOT test number	855570964344
Result	✗ Failed
Fail	Brake pipe excessively corroded both main pipes from master cylinder to abs unit (1.1.11 (c))
Advice	Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
Minor	Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))
Minor	Offside Rear Position lamp has a product on the lens or light source which obviously reduces light intensity (4.2.3 (b) (i))

**MOT #14** 2022-11-11 15:50**MOT test number** 580646892354**Result** ✓ Passed**Advice** Nearside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Rear lamp lens slightly dull**MOT #13** 2021-11-13 09:14**MOT test number** 638152311811**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #12** 2020-07-23 09:44**MOT test number** 466306604630**Result** ✓ Passed**MOT #11** 2019-07-10 11:41**MOT test number** 896290717579**Result** ✓ Passed**MOT #10** 2018-08-02 08:33**MOT test number** 716338919584**Result** ✓ Passed**MOT #9** 2018-08-02 08:33**MOT test number** 164884952641**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))**Pass with rectification** Offside Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))



MOT #8	2017-07-14 12:27
MOT test number	689690283559
Result	✓ Passed

MOT #7	2017-07-14 07:57
MOT test number	278497892541
Result	✗ Failed
<div><div>Fail</div> Nearside Rear position lamp(s) not working (1.1.A.3b)</div>	
<div><div>Fail</div> Offside Rear fog lamp not working (1.3.2b)</div>	
<div><div>Fail</div> Offside Front Anti-roll bar has excessive play in a pin/bush (2.4.G.2)</div>	

MOT #6	2016-07-27 09:57
MOT test number	949302488412
Result	✓ Passed

**MOT #5**

2016-07-26 08:06

MOT test number

802594863429

Result**✗ Failed**

- Fail** Offside Headlamp aim too high (1.8)
- Fail** Offside Rear Inner Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Fail** Nearside Obligatory mirror seriously damaged, affecting the rear view (8.1.2a)
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Fail** Nearside Front position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Headlamp aim too high (1.8)
- Fail** Offside Front Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)
- Fail** Offside Rear brake disc in such a condition that it is seriously weakened (3.5.1i)
- Fail** Offside Registration plate lamp not working (1.1.C.1d)
- Fail** Offside Front position lamp(s) not working (1.1.A.3b)

MOT #4

2015-08-08 08:20

MOT test number

485930425260

Result**✓ Passed**

- Advice** Centre Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

MOT #3

2014-10-14 10:45

MOT test number

135757984281

Result**✓ Passed**

- Notice** Both front wipers split
- Notice** Slight play in o/s/f wheel bearing



MOT #2	2014-10-14 09:26
MOT test number	669427584223
Result	✗ Failed
Fail	Nearside Front Headlamp not working on dipped beam (1.7.5a)
Notice	Both front wipers split
Fail	Offside Side repeater not working (1.4.A.2c)
Notice	Slight play in o/s/f wheel bearing

MOT #1	2013-10-11 10:53
MOT test number	826084283256
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
14 November 2024

Tax status	Valid until 1 January
------------	-----------------------

Days left	247
-----------	-----

MOT expiry date	14 November 2024
-----------------	------------------

Full MOT history	See MOT history
------------------	---------------------------------



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2020-01-01
Current registration	XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-10-14
Last registration	2023-11-15
Complete history	See info



Registration #1	2010-10-14	15 mi
Registration #2	2013-10-11	62.989 mi
Registration #3	2014-10-14	80.700 mi
Registration #4	2014-10-14	80.700 mi
Registration #5	2015-08-08	82.391 mi
Registration #6	2016-07-26	103.239 mi
Registration #7	2016-07-27	103.253 mi
Registration #8	2017-07-14	130.098 mi
Registration #9	2017-07-14	130.098 mi
Registration #10	2018-05-29	151.277 mi
Registration #11	2018-05-29	151.277 mi
Registration #12	2018-05-29	151.277 mi
Registration #13	2018-05-29	151.277 mi
Registration #14	2018-05-29	151.277 mi
Registration #15	2018-05-29	151.277 mi
Registration #16	2018-05-29	151.277 mi
Registration #17	2018-05-29	151.277 mi
Registration #18	2018-05-29	151.277 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Additional information

Fuel tank capacity	105 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	C007369