





report date: 2024-03-28

General information

Make	FORD
Model	B-MAX ZETEC
Colour	Black
Year of manufacture	2014
Top speed	109 mph
0 - 100 km/h	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 kW / 101 HP / 99 BHP
Max. torque	170 Nm at 1.400 rpm
Engine capacity	998 сс
Cylinders	3
Fuel type	Petrol
Consumption city	42.8 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-08-21

Pictures 38

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-08-17
MOT pass rate	58 %
MOT passed	7
Failed MOT tests	5
Total advice items	21
Total items failed	1

MOT #12	2023-08-17 10:00
MOT test number	419757809453
Result	✓ Passed
Next expiry date	2024-08-17

MOT #11	2023-08-15 10:17	
MOT test number	838459475951	
Result	X Failed	
DANGEROUS Nearside Front Tyre has ply or cords damaged 195-55-16 (5.2.3 (d)	(ii))	
Advice Exhaust has a minor leak of exhaust gases front flexi (6.1.2 (a))		
Advice Offside Front Tyre slightly damaged/cracking or perishing 195-55-16 (5.2.3 (d) (ii))		
MAJOR Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2	? (c))	
Advice Offside Front Tyre worn close to legal limit/worn on edge 195-55-16 - heavily crack and perished - 1.6mm (5.2.3 (e))		

MOT #10		2022-08-04 12:13
MOT test	number	201435970474
Result		✓ Passed
Advice	Central stabliser bush splitting	
Advice	Nearside Front scuffed tyre age cracking	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #9 2022-08-04 10:00

MOT test number 937865360331

Result X Failed

MAJOR Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Advice Central Front Items removed from driver's view prior to test screen obstructions larger than 40mm

Advice Nearside Front scuffed tyre age cracking

MAJOR Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Advice Central stabliser bush splitting

MOT #8 2021-08-03 14:10

MOT test number 961560902295

Result

Passed

MOT #7 2021-08-03 07:57

MOT test number 171171035695

Result X Failed

MAJOR Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

DANGEROUS Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MAJOR Front Brake disc significantly and obviously worn (1.1.14 (a) (i))

MOT #6 2020-08-18 11:23

MOT test number 862382777949

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 4/12



report date: 2024-03-28

✓ Passed

MOT #5 2019-04-18 10:56

MOT test number 794686166696

MOT #4 2019-04-18 10:18

MOT test number 681136925243

Result X Failed

MAJOR Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))

DANGEROUS Stop lamp(s) all not working (4.3.1 (a) (iii))

MOT #3 2018-03-27 15:22

MOT test number 662645185153

Result \rightarrow Passed

MOT #2 2018-03-27 12:15

MOT test number 382343682720

Result X Failed

Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Result

MOT #1 2017-03-27 10:46

MOT test number 781881983737

, 61991353, 6,

Advice Offside Rear Lower Shock absorber has a light misting of oil (2.7.3)

Advice Front Inner Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 February
Days left	279
MOT expiry date	17 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

•		
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is		ave?

	More info	>
Plate changes		
See in this check if this FORD had different number plates.		
Number of plates		,
Current registration	UK SIE	
Plate since		
Current registration	OK SIE	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-03-27
Last registration	2023-08-17
Complete history	See info



Registration #1	2014-03-27	22 mi
Registration #2	2017-03-27	23.063 mi
Registration #3	2018-03-27	36.496 mi
Registration #4	2018-03-27	36.496 mi
Registration #5	2019-04-18	49.980 mi
Registration #6	2019-04-18	49.980 mi
Registration #7	2020-08-18	60.598 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		D.777 es
Registration #13		11.777 mi

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	92%
Children	84%
Pedestrian	67%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	2067 mm
Height	1604 mm
Length	4077 mm
Wheel base	2489 mm
Kerb weight	1760 kg
Max. allowed weight	1760 kg

Additional information

Fuel tank capacity	48 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/1

Number of axles2Engine numberES23713