



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TIGUAN SPORT TDI 4MOTION
Colour	Black
Year of manufacture	2009
Top speed	116 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.1 mpg
Consumption extra urban	47.9 mpg
Consumption combined	39.2 mpg
CO2 emission	182 g/km
CO2 label	I





MOT history

MOT expiry date	2024-05-03
MOT pass rate	93 %
MOT passed	13
Failed MOT tests	1
Total advice items	35
Total items failed	1

MOT #14	2023-05-04 11:42
---------	------------------

MOT test number	345783914972
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-05-03
------------------	------------

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #13**

2022-02-19 12:27

MOT test number

253085062254

Result

✓ Passed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice Nearside Rear Nail in tyre

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #12

2021-03-06 08:56

MOT test number

599078305055

Result

✓ Passed

Advice Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Seat belt buckle slightly damaged (7.1.2 (d))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Seat belt buckle slightly damaged (7.1.2 (d))

Advice Nearside rear shock absorber sleeve deteriorated.

**MOT #11**

2021-02-27 15:05

MOT test number

651788208380

Result**✗ Failed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Seat belt buckle slightly damaged (7.1.2 (d))
- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside rear shock absorber sleeve deteriorated.
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Seat belt buckle slightly damaged (7.1.2 (d))
- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Offside rear side glass broken.

MOT #10

2020-03-03 08:51

MOT test number

195514085936

Result**✓ Passed**

- Advice** Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #9

2019-05-22 10:39

MOT test number

932315226838

Result**✓ Passed****MOT #8**

2018-05-25 12:38

MOT test number

564224459256

Result**✓ Passed**

**MOT #7** 2017-05-26 15:52**MOT test number** 146627741349**Result** ✓ Passed**MOT #6** 2016-08-16 15:45**MOT test number** 515589053443**Result** ✓ Passed**MOT #5** 2016-01-16 11:06**MOT test number** 879630733882**Result** ✓ Passed**MOT #4** 2015-03-13 11:51**MOT test number** 146692475440**Result** ✓ Passed**MOT #3** 2014-03-11 09:50**MOT test number** 318390874030**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Slight corrosion on both rear brake discs**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #2** 2013-03-22 13:20**MOT test number** 899221683031**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Engine covers fitted obscuring some components in the engine bay



MOT #1	2012-01-06 10:04
MOT test number	405576902071
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
3 May 2024

Tax status	Valid until 1 January
Days left	247
MOT expiry date	3 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 SY58XMS
Plate since	2019-06-29
Current registration	 SY58XMS
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-01-15
Last registration	2023-05-04
Complete history	See info



Registration #1	2009-01-15	6 mi
Registration #2	2012-01-06	28.065 mi
Registration #3	2013-03-22	35.499 mi
Registration #4	2014-03-11	46.254 mi
Registration #5	2015-03-13	59.209 mi
Registration #6	2016-01-16	71.962 mi
Registration #7	2016-08-16	74.466 mi
Registration #8	2017-05-26	82.487 mi
Registration #9	2018-05-29	95.277 mi
Registration #10	2019-05-29	108.277 mi
Registration #11	2020-05-29	121.277 mi
Registration #12	2021-05-29	134.277 mi
Registration #13	2022-05-29	147.277 mi
Registration #14	2023-05-04	160.277 mi
Registration #15	2023-05-04	173.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1809 mm
Height	1686 mm
Length	4427 mm
Wheel base	2604 mm
Kerb weight	1590 kg
Max. allowed weight	2240 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles

2

Engine number

CBA 222136
