



report date: 2024-03-29

General information

Make	VOLVO
Model	S60 D4 SE LUX NAV
Colour	White
Year of manufacture	-
Top speed	143 mph
0 - 60 mph	7.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	188 BHP
Max. torque	400 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	62.8 mpg
Consumption extra urban	78.5 mpg
Consumption combined	72.4 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-03-18
Pictures	17
Listing price	<a href="#">View report</a>



source: yesauto.com

**MOT history**

<b>MOT #7</b>	2022-04-12 13:11
<b>MOT test number</b>	465577975984
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2023-04-11
<b>Advice</b>	Rear Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))
<b>Advice</b>	Front Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))
<b>Advice</b>	Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement both sides radius arms (5.3.4 (a) (i))

<b>MOT #6</b>	2021-11-08 16:06
<b>MOT test number</b>	832340941262
<b>Result</b>	✓ Passed
<b>Minor</b>	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
<b>Advice</b>	Road wheel slightly distorted (5.2.2 (c) (i))

<b>MOT #5</b>	2021-11-08 16:06
<b>MOT test number</b>	444569432805
<b>Result</b>	✗ Failed
<b>Pass with rectification</b>	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
<b>Minor</b>	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
<b>Pass with rectification</b>	Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))
<b>Advice</b>	Road wheel slightly distorted (5.2.2 (c) (i))

**MOT #4** 2020-11-03 11:07**MOT test number** 769650734300**Result** ✓ Passed**Advice** Rear Tyre worn close to legal limit/worn on edge Both. (5.2.3 (e))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Front Tyre worn close to legal limit/worn on edge Both. (5.2.3 (e))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #3** 2019-10-21 07:52**MOT test number** 469994172197**Result** ✓ Passed**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #2** 2018-09-05 08:35**MOT test number** 712307323093**Result** ✓ Passed**MOT #1** 2018-09-04 11:05**MOT test number** 480208159614**Result** ✗ Failed**DANGEROUS** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >





Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2015-09-14
Last registration	2022-04-12
Complete history	<a href="#">See info</a>



Registration #1	2015-09-14	18 mi
Registration #2	2018-09-04	61.458 mi
Registration #3	2018-09-05	61.463 mi
Registration #4	2019-10-21	80.022 mi
Registration #5	2020-11-03	93.994 mi
Registration #6	2021-05-20	101.277 mi
Registration #7	2021-05-20	101.277 mi
Registration #8	2021-05-20	101.277 mi
Registration #9	2022-04-12	101.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

★★★★★

Video

[see crash video](#)



Dimensions & weight

Width	2097 mm
Height	1484 mm
Length	4635 mm
Wheel base	2776 mm
Kerb weight	1589 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	1357405