



PEUGEOT




report date: 2024-03-28

General information

Make	PEUGEOT
Model	207 SW SPORT
Colour	Black
Year of manufacture	2009
Top speed	124 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	56.5 mpg
Consumption combined	44.8 mpg
CO2 emission	150 g/km
CO2 label	F





MOT history

MOT expiry date	2025-03-29
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	42
Total items failed	10

MOT #18	2024-03-27 12:58
---------	------------------

MOT test number	417855835710
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2025-03-29
------------------	------------

- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear Suspension component mounting prescribed area is corroded but not considered excessive both sides (5.3.6 (a) (i))
- Advice** Front tyres worn edges
- Advice** Rear Exhaust has a minor leak of exhaust gases joint (6.1.2 (a))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Front brake discs corroded

**MOT #17**

2023-03-17 10:26

MOT test number

350046824677

Result

✓ Passed

- Advice** Front Inner Brake disc worn, but not excessively face (1.1.14 (a) (i))
- Advice** Offside Front Inner c.v. boot clip is missing
- Advice** Offside Front Inner Oil leak, but not excessive driveshaft oil seal (8.4.1 (a) (i))
- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #16

2023-03-13 12:14

MOT test number

667870706854

Result

✗ Failed

- Advice** Offside Front Inner Oil leak, but not excessive driveshaft oil seal (8.4.1 (a) (i))
- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Fail** Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Front Inner Brake disc worn, but not excessively face (1.1.14 (a) (i))
- Fail** Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #15

2022-03-29 12:08

MOT test number

947352328902

Result

✓ Passed

- Advice** Seepage from o/s front inner CV gaiter
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Front brake discs corroded

**MOT #14** 2021-03-30 13:22**MOT test number** 848223719486**Result** ✓ Passed**MOT #13** 2021-03-30 13:22**MOT test number** 898884631674**Result** ✗ Failed**Pass with rectification** Offside Front Windscreen wiper not working (3.4 (a))**MOT #12** 2019-12-30 12:45**MOT test number** 937969152900**Result** ✓ Passed**MOT #11** 2019-12-23 16:05**MOT test number** 119454513108**Result** ✗ Failed**Advice** Coolant leak**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Minor** Nearside Rear Brake hose slightly chafed (1.1.12 (b) (i))**MOT #10** 2019-01-09 12:28**MOT test number** 377675187232**Result** ✓ Passed**Advice** Nearside Front Play in steering rack inner joint(s)**Advice** Front Anti-roll bar linkage ball joint has slight play both sides (5.3.4 (a) (i))

**MOT #9** 2019-01-05 15:25**MOT test number** 379812548852**Result** ✗ Failed**Fail** Nearside Front Service brake excessively fluctuating (1.2.1 (e))**Advice** Front Anti-roll bar linkage ball joint has slight play both sides (5.3.4 (a) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))**Fail** Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**Advice** Nearside Front Play in steering rack inner joint(s)**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))**MOT #8** 2017-12-29 11:18**MOT test number** 372156732527**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened inner face (3.5.1i)**Advice** Nearside Front Tyre worn close to the legal limit 195/55/16 V (4.1.E.1)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened inner face (3.5.1i)**MOT #7** 2017-12-29 09:48**MOT test number** 515606307346**Result** ✗ Failed**Fail** Nearside Stop lamp not working (1.2.1b)**Fail** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' article from mirror (8.3.1e)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened inner face (3.5.1i)**Advice** Nearside Front Tyre worn close to the legal limit 195/55/16 V (4.1.E.1)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened inner face (3.5.1i)

**MOT #6** 2017-01-03 16:16**MOT test number** 576412256473**Result** ✓ Passed**MOT #5** 2016-12-31 09:34**MOT test number** 546998973442**Result** ✗ Failed

Fail Exhaust system not adequately supported CENTRE AND REAR BRACKETS HAVE CORRODED AWAY.
(7.1.1)

MOT #4 2015-12-30 10:22**MOT test number** 734755713961**Result** ✓ Passed

Advice N/s/r tyre perished

MOT #3 2015-01-02 15:37**MOT test number** 599602805064**Result** ✓ Passed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2 2014-01-07 15:59**MOT test number** 136027804076**Result** ✓ Passed

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Notice Child seat fitted not allowing full inspection of adult belt



MOT #1	2012-12-29 09:57
MOT test number	908324262352
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
29 March 2025

Tax status	Valid until 1 March
Days left	306
MOT expiry date	29 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-11-13
Last registration	2024-03-27
Complete history	See info



Registration #1	2009-11-13	26 mi
Registration #2	2012-12-29	35.699 mi
Registration #3	2014-01-07	28.150 mi
Registration #4	2015-01-02	31.200 mi
Registration #5	2015-12-30	32.623 mi
Registration #6	2016-12-31	34.533 mi
Registration #7	2017-01-03	34.534 mi
Registration #8	2017-12-29	36.693 mi
Registration #9	2017-12-29	36.693 mi
Registration #10	2019-01-05	46.917 mi
Registration #11	2019-01-05	46.917 mi
Registration #12	2019-01-05	46.917 mi
Registration #13	2019-01-05	46.917 mi
Registration #14	2019-01-05	46.917 mi
Registration #15	2019-01-05	46.917 mi
Registration #16	2019-01-05	46.917 mi
Registration #17	2019-01-05	46.917 mi
Registration #18	2019-01-05	46.917 mi
Registration #19	2019-01-05	46.917 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1920 mm
Height	1555 mm
Length	4156 mm
Wheel base	2540 mm
Kerb weight	1302 kg
Max. allowed weight	1705 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	FHBC0379295