



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	CLK CLK220 CDI AVANTGARDE
Colour	Silver
Year of manufacture	2005
Top speed	137 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	148 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	2.148 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.1 mpg
Consumption extra urban	54.3 mpg
Consumption combined	43.5 mpg
CO2 emission	183 g/km
CO2 label	I






Internet history

Entry 1

Date	2021-10-23
Pictures	24
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-12
MOT pass rate	67 %
MOT passed	16
Failed MOT tests	8
Total advice items	60
Total items failed	10

MOT #242023-12-13 17:43

MOT test number633233711272

Result✓ Passed

Next expiry date2024-12-12

- AdviceFront shock absorbers slightly corroded.
- AdviceNearside Front Nail in tyre
- AdviceNearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- AdviceOffside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- AdviceNearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- AdviceNearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- AdviceFront Brake disc worn, pitted or scored, but not seriously weakened both discs. (1.1.14 (a) (ii))
- AdviceSlight surface corrosion to various under-side components not affecting it's strength or driveability.
- AdviceFront Brake pad(s) wearing thin (1.1.13 (a) (ii))
- AdviceNearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- AdviceCentral Brake pipe corroded, covered in grease or other material both pipes. (1.1.11 (c))
- AdviceOffside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- AdviceSide skirts/ sill covers and under-trays fitted not allowing full inspection of some under-side components.
- AdviceRear Brake disc worn, pitted or scored, but not seriously weakened both discs. (1.1.14 (a) (ii))

**MOT #23**

2023-12-04 16:55

MOT test number

788334456189

Result**✗ Failed****Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both discs. (1.1.14 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Slight surface corrosion to various under-side components not affecting it's strength or driveability.**Advice** Central Brake pipe corroded, covered in grease or other material both pipes. (1.1.11 (c))**MAJOR** Brake performance unable to be tested O/S/R brake pipe leaking !!! (1.2.1 (g))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Nail in tyre**MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both discs. (1.1.14 (a) (ii))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Side skirts/ sill covers and under-trays fitted not allowing full inspection of some under-side components.**DANGEROUS** Offside Rear Brake pipe leaking on a hydraulic braking system (1.1.11 (b) (ii))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Front shock absorbers slightly corroded.**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Rear Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))

**MOT #22**

2022-10-14 17:04

MOT test number

424246558251

Result

✓ Passed

- Advice** Offside Front Shock absorbers has slight external damage to the casing (5.3.2 (b))
- Advice** Rear surface slightly corroded
- Advice** Front Brake pipe corroded, covered in grease or other material both sides (1.1.11 (c))

MOT #21

2021-09-04 10:46

MOT test number

105202611312

Result

✓ Passed

- Minor** Headlamp lens slightly defective both (4.1.1 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Rear Nail in tyre

MOT #20

2021-08-24 15:19

MOT test number

698995306579

Result

✗ Failed

- DANGEROUS** Offside Rear Inner Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- MAJOR** Exhaust has a major leak of exhaust gases (6.1.2 (a))
- Minor** Headlamp lens slightly defective both (4.1.1 (b) (i))
- Advice** Nearside Rear Nail in tyre
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Fuel cap/sealing device missing (6.1.3 (b) (i))

**MOT #19** 2020-08-22 07:49**MOT test number** 607150741214**Result** ✓ Passed**Advice** Front Headlamp has a product on the lens but not seriously reducing light output both sides (4.1.4 (b))**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))**Advice** Rear Exhaust has a minor leak of exhaust gases badly corroded (6.1.2 (a))**MOT #18** 2019-10-04 13:47**MOT test number** 762338268140**Result** ✓ Passed**MOT #17** 2018-11-22 13:36**MOT test number** 771735388001**Result** ✓ Passed**MOT #16** 2017-11-28 12:00**MOT test number** 391809783541**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #15** 2017-11-28 09:43**MOT test number** 597212891381**Result** ✗ Failed

- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear Tyre worn close to the legal limit 245/40/17 (4.1.E.1)
- Fail** Nearside front brake binding (3.7.B.1)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #14 2017-01-04 14:09**MOT test number** 219627717664**Result** ✓ Passed**MOT #13** 2017-01-04 14:09**MOT test number** 266659939232**Result** ✗ Failed

- Pass with rectification** Nearside Front Suspension arm has excessive play in a pin/bush (2.4.G.2)
- Pass with rectification** Offside Front brake caliper has restricted free movement (3.5.1k)
- Pass with rectification** Offside Front Suspension arm has excessive play in a pin/bush (2.4.G.2)

MOT #12 2015-07-15 10:38**MOT test number** 675236695124**Result** ✓ Passed

**MOT #11** 2015-07-15 10:38**MOT test number** 439866495145**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp not working on main beam (1.7.5a)**MOT #10** 2014-07-16 10:41**MOT test number** 567327894140**Result** ✓ Passed**MOT #9** 2013-07-19 15:49**MOT test number** 448460903291**Result** ✓ Passed**MOT #8** 2012-07-16 16:59**MOT test number** 617758892119**Result** ✓ Passed**MOT #7** 2012-07-13 16:40**MOT test number** 478805592154**Result** ✗ Failed**Fail** Offside Front Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2011-07-18 12:13**MOT test number** 286879291109**Result** ✓ Passed

**MOT #5** 2011-07-18 12:13**MOT test number** 219049091487**Result** ✗ Failed**Pass with rectification** Offside Rear Direction indicators incorrect colour (1.4.A.2f)**Pass with rectification** Nearside Rear Direction indicators incorrect colour (1.4.A.2f)**Pass with rectification** Parking brake lever has no reserve travel (3.1.6b)**MOT #4** 2010-07-21 09:39**MOT test number** 302562800237**Result** ✓ Passed**MOT #3** 2009-11-09 12:39**MOT test number** 632653619353**Result** ✗ Failed**Pass with rectification** Registration plate character(s) incorrectly spaced (6.3.4a)**MOT #2** 2009-11-09 12:39**MOT test number** 133513219394**Result** ✓ Passed**MOT #1** 2008-10-16 15:46**MOT test number** 352110798235**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
12 December 2024

Tax status	Valid until 1 December
Days left	217
MOT expiry date	12 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2023-03-29
Current registration	 XXXXXX
Plate since	2023-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2005-09-27
Last registration	2023-12-13
Complete history	See info



Registration #1	2005-09-27	18 mi
Registration #2	2008-10-16	29.822 mi
Registration #3	2009-11-09	37.192 mi
Registration #4	2010-07-21	39.215 mi
Registration #5	2011-07-18	49.707 mi
Registration #6	2012-07-13	54.444 mi
Registration #7	2012-07-16	54.444 mi
Registration #8	2013-07-19	59.215 mi
Registration #9	2014-07-16	61.719 mi
Registration #10	2015-07-15	63.902 mi
Registration #11	2017-01-04	68.438 mi
Registration #12	2017-01-04	68.438 mi
Registration #13	2019-05-29	75.277 mi
Registration #14	2019-05-29	75.277 mi
Registration #15	2019-05-29	75.277 mi
Registration #16	2019-05-29	75.277 mi
Registration #17	2019-05-29	75.277 mi
Registration #18	2019-05-29	75.277 mi
Registration #19	2019-05-29	75.277 mi
Registration #20	2019-05-29	75.277 mi
Registration #21	2019-05-29	75.277 mi
Registration #22	2019-05-29	75.277 mi
Registration #23	2019-05-29	75.277 mi

More info >



Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2715 mm
Kerb weight	1595 kg
Max. allowed weight	2030 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	64696630482923