



TOYOTA




report date: 2024-03-28

General information

Make	TOYOTA
Model	COROLLA VVTI T SPIRIT
Colour	Silver
Year of manufacture	2005
Top speed	109 mph
0 - 60 mph	11.8 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	109 BHP
Max. torque	150 Nm at 3.800 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.6 mpg
Consumption extra urban	44.1 mpg
Consumption combined	35.7 mpg
CO2 emission	190 g/km
CO2 label	J





Internet history

Entry 2

Date	2023-09-30
Pictures	8
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-07-14
Pictures	1
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-10-28
MOT pass rate	84 %
MOT passed	16
Failed MOT tests	3
Total advice items	30
Total items failed	7

MOT #19 2023-10-05 09:23

MOT test number 163629713923

Result ✓ Passed

Next expiry date 2024-10-28

Advice Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge EDGE (5.2.3 (e))

Advice Power steering pipe/hose slightly corroded (2.1.5 (g) (i))

MOT #18 2022-10-18 10:05

MOT test number 396367066024

Result ✓ Passed

Advice Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

Advice Power steering pipe/hose slightly corroded (2.1.5 (g) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #17 2021-10-26 13:52

MOT test number 278725125445

Result ✓ Passed

**MOT #16**

2021-10-26 12:23

MOT test number

700625323336

Result**✗ Failed**

- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Minor** Offside Front Position lamp light intensity obviously reduced (4.2.3 (a) (i))
- Advice** Rear Brake pad(s) wearing thin BOTH SIDES (1.1.13 (a) (ii))
- Fail** Offside Rear Service brake excessively fluctuating (1.2.1 (e))
- Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Front Brake pad(s) wearing thin BOTH SIDES (1.1.13 (a) (ii))
- Fail** Brake performance not tested (1.2.1 (g))

MOT #15

2020-10-28 11:22

MOT test number

934093963114

Result**✓ Passed**

- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Minor** Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Oil leak, but not excessive transmission (8.4.1 (a) (i))

**MOT #14**

2019-10-22 16:10

MOT test number

957543607008

Result

✓ Passed

- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Oil leak, but not excessive Transmission (8.4.1 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Oil leak, but not excessive Engine oil Filter (8.4.1 (a) (i))
- Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))

MOT #13

2018-10-11 14:42

MOT test number

233683756478

Result

✓ Passed

- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #12

2017-10-24 13:37

MOT test number

168781002692

Result

✓ Passed

MOT #11

2016-10-24 11:00

MOT test number

662980237809

Result

✓ Passed

**MOT #10** 2016-10-24 11:00**MOT test number** 113439257384**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**MOT #9** 2015-10-14 07:18**MOT test number** 538479823643**Result** ✓ Passed**Advice** Sill covers fitted**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** N/s/f tyre showing signs of age related cracking**MOT #8** 2015-10-14 07:18**MOT test number** 349201257955**Result** ✗ Failed**Advice** Sill covers fitted**Pass with rectification** Nearside Headlamp aim too high (1.8)**Advice** N/s/f tyre showing signs of age related cracking**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Headlamp aim too high (1.8)**MOT #7** 2014-10-25 12:39**MOT test number** 328568994217**Result** ✓ Passed**MOT #6** 2013-10-24 12:46**MOT test number** 465487193227**Result** ✓ Passed



MOT #5	2012-10-24 15:56
MOT test number	967278192243
Result	✓ Passed
MOT #4	2011-10-24 15:35
MOT test number	167227791284
Result	✓ Passed
Advice	Offside Front Shock absorber has a light misting of oil (2.7.3)
MOT #3	2010-10-23 16:08
MOT test number	331256390279
Result	✓ Passed
MOT #2	2009-10-28 13:30
MOT test number	623151809300
Result	✓ Passed
MOT #1	2008-10-29 14:29
MOT test number	831513908338
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
28 October 2024

Tax status	Valid until 1 November
Days left	187
MOT expiry date	28 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history


Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-02-10
Last registration	2023-10-05
Complete history	See info



Registration #1	2005-02-10	8 mi
Registration #2	2008-10-29	30.217 mi
Registration #3	2009-10-28	41.643 mi
Registration #4	2010-10-23	54.554 mi
Registration #5	2012-10-24	78.282 mi
Registration #6	2013-10-24	89.687 mi
Registration #7	2014-10-25	101.934 mi
Registration #8	2015-10-14	110.376 mi
Registration #9	2015-10-14	110.376 mi
Registration #10	2016-10-24	112.681 mi
Registration #11	2016-10-24	112.681 mi
Registration #12	2016-10-24	112.681 mi
Registration #13	2016-10-24	112.681 mi
Registration #14	2016-10-24	112.681 mi
Registration #15	2016-10-24	112.681 mi
Registration #16	2016-10-24	112.681 mi
Registration #17	2016-10-24	112.681 mi
Registration #18	2016-10-24	112.681 mi
Registration #19	2016-10-24	112.681 mi
Registration #20	2016-10-24	112.681 mi
Registration #21	2016-10-24	112.681 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1710 mm
Height	1475 mm
Length	4180 mm
Wheel base	2600 mm
Kerb weight	1255 kg
Max. allowed weight	1670 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	3ZZU625053