





General information

Make	MERCEDES
Model	ML ML 280 CDI EDITION S
Colour	Black
Year of manufacture	2007
Top speed	127 mph
0 - 60 mph	9.8 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	188 BHP
Max. torque	440 Nm at 2.800 rpm
Engine capacity	2.987 сс
Cylinders	6
Fuel type	Diesel
Consumption city	21.9 mpg
Consumption extra urban	35.3 mpg
Consumption combined	28.8 mpg
CO2 emission	254 g/km
CO2 label	L







2021-07-19
0
View report
2021-07-18
0
View report

source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-10
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	16
Total items failed	10

MOT #17		2023-08-01 08:16
MOT test	number	149557714034
Result		✓ Passed
Next expir	ry date	2024-08-10
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deterio	prated (6.1.7 (g) (i))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Minor	Offside Front Outer Drive shaft joint constant velocity boot severely deteriora	ated (6.1.7 (g) (i))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	

MOT #16		2022-07-30 08:02
MOT test	number	141813906982
Result		✓ Passed
Minor	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated	(6.1.7 (g) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	All four lower arm shock bushes perishing.	





MOT #15	2021-08-11 14:50
MOT test number	929091547363
Result	✓ Passed
MOT #14	2021-08-04 15:38
MOT test number	159273786659
Result	× Failed
Fail Indicator switch inoperative N/S and O/S (4.4.2 (a) (ii))
FailRear fog lamp not working (4.5.1 (a) (ii))	
Fail Offside Rear Coil spring fractured or broke	en (5.3.1 (b) (i))
Fail Supplementary restraint system warning	amp indicates a fault (7.1.6 (a))
Fail Hazard warning switch inoperative (4.4.2)	(a) (ii))
Fail Nearside Headlamp not working on dipper	d beam (4.1.1 (a) (ii))
Fail Windscreen wiper not working (3.4 (a))	

MOT #13	2020-10-29 13:57
MOT test number	376374252494
Result	✓ Passed
MOT #12	2019-04-15 15:38

MOT test number	763486392112
Result	✓ Passed

MOT #11	2018-01-10 13:42
MOT test number	250952247019
Result	✓ Passed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	





MOT #10	2018-01-08 14:36
MOT test number	926780983581
Result	× Failed
Advice Nearside Rear T	yre worn close to the legal limit (4.1.E.1)
Fail Nearside Front Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)	
Fail Parking brake: effic	iency below requirements (3.7.B.7)
MOT #9	2017-01-03 17:32
MOT test number	575636745752
Result	✓ Passed
MOT #8	2017-01-03 17:32
MOT test number	911425594174
Result	× Failed
Pass with rectification	Offside Front position lamp(s) not working (1.1.A.3b)
MOT #7	2016-02-17 16:22
MOT test number	350278867525
Result	✓ Passed
МОТ #6	2015-02-11 18:14
MOT test number	815172645003
Result	✓ Passed
Advice Nearside Front T	yre worn close to the legal limit (4.1.E.1)
Advice Offside Front Ty	re worn close to the legal limit (4.1.E.1)





MOT #5	2014-02-18 09:11
MOT test number	488769444039
Result	✓ Passed
NoticeOil leakAdviceOffside Rear Tyre worn close to the legal limit (4.1.E.1)	
MOT #4	2012-12-27 14:55
MOT test number	176402262367
Result	✓ Passed
MOT #3	2011-12-07 12:11

MOT test	number	539111841359
Result		✓ Passed
Notice	Both front tyres wearing on outer edges	

MOT #2	2011-02-24 16:53
MOT test number	938425351006
Result	✓ Passed
MOT #1	2010 12 12 14.52

MOT #1	2010-12-13 14:52
MOT test number	982717840365
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due: 1 August 2024	✓ MOT Expires: 10 August 2024
Tax status	Valid until 1 August
Days left	95
MOT expiry date	10 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-





Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	VAMPLE
Date	
Category	AMP
Туре	

Extra MERCEDES salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second s	
	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-12-27
Last registration	2023-08-01
Complete history	See info



Registration #1	2007-12-27	17 mi
Registration #2	2010-12-13	48.112 mi
Registration #3	2011-02-24	48.956 mi
Registration #4	2011-12-07	56.727 mi
Registration #5	2012-12-27	66.290 mi
Registration #6	2014-02-18	79.973 mi
Registration #7	2015-02-11	87.308 mi
Registration #8	2016-02-17	91.133 mi
Registration #9	2017-01-03	95.643 mi
Registration #10	2017-01-03	95.643 mi
Registration #11		11.777 esi
Registration #12		11.777 esi
Registration #13		11.777 esi
Registration #14		11.777 esi
Registration #15		11.777 est
Registration #16		11.777 esi
Registration #17		11.777 mi
Registration #18		11.777 est
Registration #19		10.200 est





Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1911 mm
Height	1884 mm
Length	4780 mm
Wheel base	2915 mm
Kerb weight	2185 kg
Additional information	
Fuel tank capacity	95 I
	95 l Direct Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Direct Injection
Fuel tank capacity Fuel delivery Number of doors	Direct Injection 5