



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	CADDY C20 PLUS SDI
Colour	Purple
Year of manufacture	2009
Top speed	88 mph
0 - 60 mph	20.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	140 Nm at 2.200 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.1 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-03
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-15
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	23
Total items failed	3

MOT #16	2024-03-12 09:21
MOT test number	610831644825
Result	✓ Passed
Next expiry date	2025-03-15

MOT #15	2023-02-24 09:58
MOT test number	903352715458
Result	✓ Passed

MOT #14	2022-03-16 13:56
MOT test number	397828207165
Result	✓ Passed

MOT #13	2021-01-04 16:33
MOT test number	840377641828
Result	✓ Passed

**MOT #12**

2021-01-04 13:09

MOT test number

722344473000

Result**✗ Failed****DANGEROUS** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Nearside Rear Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))**DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #11**

2019-12-23 17:22

MOT test number

298454034896

Result**✓ Passed****Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Oil leak, but not excessive Gearbox (8.4.1 (a) (i))**MOT #10**

2019-12-23 12:18

MOT test number

861172108211

Result**✗ Failed****Advice** Oil leak, but not excessive Gearbox (8.4.1 (a) (i))**MAJOR** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MAJOR** Offside Front Tyre not fitted in accordance with side wall instructions (5.2.3 (i))**MAJOR** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #9** 2018-12-05 09:55**MOT test number** 992016684571**Result** ✓ Passed**Minor** Offside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Power steering close to minimum mark (2.1.5 (b) (i))**Minor** Nearside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #8** 2017-12-16 12:26**MOT test number** 297896096732**Result** ✓ Passed**Advice** Offside Front Upper Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**MOT #7** 2016-06-29 13:50**MOT test number** 583544223097**Result** ✓ Passed**MOT #6** 2015-07-11 09:33**MOT test number** 457772095101**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2014-07-03 13:20**MOT test number** 225454984155**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Nearside rear tyre perished

**MOT #4** 2014-06-17 14:22**MOT test number** 575008664113**Result** ✓ Passed**MOT #3** 2014-06-17 11:16**MOT test number** 248138864433**Result** ✗ Failed

- Fail** Rear Exhaust has a major leak of exhaust gases (7.1.2)
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #2 2013-07-12 13:23**MOT test number** 849493793143**Result** ✓ Passed

- Notice** Nearside rear tyre outer sidewall scrubbed from kerbing

MOT #1 2012-07-04 12:41**MOT test number** 629456882150**Result** ✓ Passed

- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
15 March 2025

Tax status	Valid until 1 March
-------------------	---------------------

Days left	305
------------------	-----

MOT expiry date	15 March 2025
------------------------	---------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2020-06-29
Current registration	 XXXXXX
Plate since	2020-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-07-27
Last registration	2024-03-12
Complete history	See info



Registration #1	2009-07-27	25 mi
Registration #2	2012-07-04	15.014 mi
Registration #3	2013-07-12	21.900 mi
Registration #4	2014-06-17	32.129 mi
Registration #5	2014-06-17	32.129 mi
Registration #6	2014-07-03	32.652 mi
Registration #7	2015-07-11	42.129 mi
Registration #8	2016-06-29	52.389 mi
Registration #9	2017-12-16	65.972 mi
Registration #10	2018-06-29	75.377 mi
Registration #11	2018-06-29	75.377 mi
Registration #12	2018-06-29	75.377 mi
Registration #13	2018-06-29	75.377 mi
Registration #14	2018-06-29	75.377 mi
Registration #15	2018-06-29	75.377 mi
Registration #16	2018-06-29	75.377 mi
Registration #17	2018-06-29	75.377 mi
Registration #18	2018-06-29	75.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	2062 mm
Height	1833 mm
Length	4405 mm
Kerb weight	1465 kg
Max. allowed weight	2232 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2

Number of axles

2

Engine number

BST0094691