





report date: 2024-03-29

## General information

Make	HYUNDAI
Model	IX35 CRDI PREMIUM
Colour	Red
Year of manufacture	2011
Top speed	108 mph
0 - 60 mph	12.4 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 1.250 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/12



report date: 2024-03-29

# Internet history

## Entry 1

Date	2021-01-31	
Pictures	1	
Listing price	<u>View report</u>	



source: autoonline.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

# MOT history

MOT expiry date	2025-01-28
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	15
Total items failed	3

MOT #13	2024-01-11 16:34
MOT test number	977965887189
Result	✓ Passed
Next expiry date	2025-01-28
Advice Rear wiper blade split	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Low fuel warning lamp on	

MOT #12	2024-01-10 10:23
MOT test number	788089883276
Result	<b>×</b> Failed
Advice Rear wiper blade split	
Fail Parking brake efficiency below requirements (1.4.2 (a) (i))	
Advice Low fuel warning lamp on	
Fail Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))	
Minor Nearside Registration plate lamp insecure (4.7.1 (c) (i))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Engine oil low	

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT test number

678112058990

Result

Minor
(b) (i))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT test number

Result

Result

Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor

(b) (i))

Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #9

MOT test number

693180154537

Result

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

 MOT #8
 2021-01-29 15:27

 MOT test number
 454484347117

 Result
 ✓ Passed

 MOT #7
 2019-07-15 12:36

 MOT test number
 346789509656

 Result
 ✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #6	2018-07-11 13:23
MOT test number	487429856773
Result	<b>✓</b> Passed
MOT #5	2017-11-06 09:53
MOT test number	361500050884
Result	✓ Passed
MOT #4	2017-03-31 08:35
MOT test number	690304611965
Result	✓ Passed
MOT #3	2016-04-04 09:32
MOT test number	637352040167
Result	✓ Passed
MOT #2	2015-03-05 09:42
MOT test number	157404765430
Result	✓ Passed
MOT #1	2014-02-13 13:03
MOT test number	248564744019
Result	<b>✓</b> Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

## Tax & MOT check



Tax status	Valid until 1 May
Days left	2
MOT expiry date	28 January 2025
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

## Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

## Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

$\sim$		ier	11-15			
- ( )	w/r	ıρr	nı	СТ	nπ	۷
$\sim$	V V I				OI.	٧

For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		
***************************************		
	More info >	
Plate changes		
See in this check if this HYUNDAI had different number plates.		
Number of plates		
Current registration	UK SIE	
Plate since		
Current registration	UK UK	
Plate since		
	More info >	

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courts at info	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-02-24
Last registration	2024-01-11
Complete history	See info



Registration #1	2011-02-24	10 mi
Registration #2	2014-02-13	21.730 mi
Registration #3	2015-03-05	27.226 mi
Registration #4	2016-04-04	33.124 mi
Registration #5	2017-03-31	41.223 mi
Registration #6	2017-11-06	46.673 mi
Registration #7	2018-07-11	52.282 mi
Registration #8	2019-07-15	59.840 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es

More info >

CarCheck.co.uk page 11/12



ND60VSG report date: 2024-03-29

Car features

50225	Air conditionin
50295	
50482	
60501	
60566	
60567	
60569	

# Safety ratings

NCAP rating	****
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	see crash video



# Dimensions & weight

Width	1820 mm
Height	1670 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1537 kg
Max. allowed weight	1940 kg

## Additional information

Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats	5	
Engine number Carcheck.co.uk	D4FDBZ019926	page 12/12