





report date: 2024-03-28

General information

| Make | FORD |
|---------------------|-------------------|
| Model | FIESTA ST-LINE |
| Colour | White |
| Year of manufacture | 2018 |
| Top speed | 111 mph |
| 0 - 60 mph | 12.4 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| Power | 73.5 kW / 100 HP / 99 BHP |
|-------------------------|---------------------------|
| Max. torque | 170 Nm at 1.500 rpm |
| Engine capacity | 998 cc |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption city | 40.9 mpg |
| Consumption extra urban | 67.3 mpg |
| Consumption combined | 54.3 mpg |
| CO2 emission | 118 g/km |
| CO2 label | С |



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 2

| Date | 2021-07-28 |
|---------------|-------------|
| Pictures | 1 |
| Listing price | View report |



source: autoonline.co.uk

Entry 1

| Date | 2021-07-17 | |
|---------------|--------------------|--|
| Pictures | 1 | |
| Listing price | <u>View report</u> | |



source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT history

| MOT expiry date | 2025-04-18 |
|--------------------|------------|
| MOT pass rate | 67 % |
| MOT passed | 4 |
| Failed MOT tests | 2 |
| Total advice items | 4 |
| Total items failed | 3 |

| MOT #6 | | 2024-04-19 09:47 |
|--|--|------------------|
| MOT test | number | 674576243471 |
| Result | | ✓ Passed |
| Next expiry date 2025-04 | | 2025-04-18 |
| Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | | |
| Advice | Offside Front Tyre has a cut but not deep enough to reach the ply or cords (| 5.2.3 (d) (i)) |

| MOT #5 | | 2024-04-18 10:48 |
|---|--------|------------------|
| MOT test i | number | 114275405357 |
| Result | | X Failed |
| Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | | |
| Advice Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i)) | | |
| Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i)) | | |

| MOT #4 | 2023-04-05 09:56 |
|-----------------|------------------|
| MOT test number | 142965113677 |
| Result | ✓ Passed |
| | |
| MOT #3 | 2022-03-31 13:28 |
| MOT test number | 679068382054 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #2 2021-03-22 14:58

MOT test number 201864652666

MOT #1 2021-03-16 10:14

MOT test number 111004200207

Result X Failed

Fail Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

Fail Offside Front Tyre has a tear, caused by separation or partial failure of its structure inner sidewall split (5.2.3 (d) (ii))

CarCheck.co.uk page 4/11



ML18SWX report date: 2024-03-28

Tax & MOT check



| Tax status | Valid until 1 August |
|------------------|----------------------|
| Days left | 95 |
| MOT expiry date | 18 April 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|-------------------------------|------------|
| Band | G |
| First licence fee (12 months) | £ 210,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history

| For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is | | ve? |
|---|-----------|-----|
| *************************************** | | |
| *************************************** | | |
| *************************************** | | |
| | | |
| | | |
| | | |
| | | |
| | More info | > |
| Plate changes | | |
| See in this check if this FORD had different number plates. | | |
| Number of plates | | , |
| Current registration | NK NE | |
| Plate since | | |
| Current registration | UK NE | |
| Plate since | | |
| | More info | > |

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 9 |
| First mileage registration | 2018-03-29 |
| Last registration | 2024-04-19 |
| Complete history | See info |



| Registration #1 | 2018-03-29 | 22 mi |
|-----------------|------------|-----------|
| Registration #2 | 2021-03-16 | 19.876 mi |
| Registration #3 | 2021-03-22 | 20.050 mi |
| Registration #4 | | 11.777 es |
| Registration #5 | | 11.777 es |
| Registration #6 | | 11.777 es |
| Registration #7 | | 11.777 es |
| Registration #8 | | 11.777 es |
| Registration #9 | | 11.777 es |

More info >

CarCheck.co.uk page 10/11



ML18SWX report date: 2024-03-28

Car features

| S0225 | Air conditionin |
|-------|-----------------|
| 50295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| 60567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 87% |
| Children | 84% |
| Pedestrian | 64% |
| Safety systems | 60% |
| Overall rating | 76% |
| Video | see crash video |



Dimensions & weight

| Width | 1978 mm |
|---------------------|---------|
| Height | 1468 mm |
| Length | 3969 mm |
| Wheel base | 2493 mm |
| Kerb weight | 1221 kg |
| Max. allowed weight | 1660 kg |

Additional information

| Fuel tank capacity | 42 I | |
|-----------------------------------|------------------|-----------|
| Fuel delivery | Direct Injection | |
| Number of doors | 3 | |
| Number of seats CarCheck.co.uk | 5 p | age 11/11 |

Number of axles2Engine numberHE41591