





report date: 2024-03-28

## General information

Make	BMW
Model	530 530D SPORT
Colour	Black
Year of manufacture	2004
Top speed	151 mph
0 - 60 mph	7.3 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	215 BHP
Max. torque	500 Nm at 2.000 rpm
Engine capacity	2.993 сс
Cylinders	6
Fuel type	Diesel
Consumption city	26.2 mpg
Consumption extra urban	46.3 mpg
Consumption combined	36.2 mpg
CO2 emission	208 g/km
CO2 label	K



CarCheck.co.uk page 1/15



# Internet history


## Entry 1

Date 2021-09-15

Pictures 17

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/15



MOT history

MOT expiry date	2024-10-04
MOT pass rate	70 %
MOT passed	16
Failed MOT tests	7
Total advice items	28
Total items failed	9

MOT #23		2023-10-05 12:11
MOT test	number	667989564716
Result		✓ Passed
Next expiry date 2024-10-		2024-10-04
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #22	2022-09-15	10:22
MOT test	number 56290943	32644
Result	<b>√</b> P	assed
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice	Central Front Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice Central Front Inner Prop shaft flexible coupling slightly deteriorated Signs of bolt movement in rubber coupling (6.1.7 (d) (i))		1

MOT #21	2021-10-05 07:34
MOT test number	662542563506
Result	✓ Passed

CarCheck.co.uk page 3/15



MOT #20 2020-11-25 09:20

**MOT test number** 971041081162

**Result** ✓ Passed

**Advice** Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement wishbone (5.3.4 (a) (i))

MOT #19 2020-11-24 12:37

MOT test number 230631504367

**Result** X Failed

**Advice** Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement wishbone (5.3.4 (a) (i))

MAJOR Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

**MOT #18** 2019-12-04 15:36

MOT test number 937324722917

Result 

Passed

**MOT #17** 2019-11-22 10:11

MOT test number 367475328012

Result X Failed

MAJOR Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

MAJOR Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

CarCheck.co.uk page 4/15



LY54EOF

report date: 2024-03-28

**MOT #16** 2018-11-29 10:26 **MOT** test number 867461595847 Result ✓ Passed **Advice** Engine cover fitted Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) Advice Offside Play in steering rack inner joint(s) Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Minor Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i)) **Advice** Under trays fitted

**MOT #15** 2018-11-27 12:50 **MOT** test number 217842474548 Result × Failed **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Minor Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i)) **Advice** Engine cover fitted **MAJOR** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a)) Advice Under trays fitted Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) Advice **Advice** Offside Play in steering rack inner joint(s)

MOT #14	2017-11-23 11:20
MOT test number	311347753365
Result	✓ Passed

CarCheck.co.uk page 5/15



**MOT #13** 2017-11-20 10:59

**MOT test number** 592411842372

**Result** X Failed

Fail Supplementary Restraint System warning lamp indicates a fault (5.4.2)

MOT #12 2016-11-14 17:23

MOT test number 363994119054

Result 

Passed

**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #11** 2016-11-14 10:29

**MOT test number** 671018530294

Result X Failed

Fail Nearside Rear position lamp(s) not working (1.1.A.3b)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)

Fail Nearside Stop lamp not working (1.2.1b)

MOT #10 2015-12-03 08:43

**MOT test number** 556855592822

CarCheck.co.uk page 6/15



MOT #9 2015-12-02 11:43

**MOT test number** 621061971230

Result X Failed

Fail Nearside Front coil spring broken (2.4.C.1a)

Advice Nearside Front Anti-roll bar ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Fail Supplementary Restraint System warning lamp indicates a fault (5.4.2)

**Fail** Offside Front coil spring broken (2.4.C.1a)

**Advice** Offside Front Anti-roll bar ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

MOT #8 2014-11-28 12:25

**MOT test number** 168122234380

**Result** ✓ Passed

MOT #7 2013-11-30 11:23

MOT test number 435344533459

**Result** ✓ Passed

**MOT #6** 2013-11-30 09:10

MOT test number 545084033387

**Result** X Failed

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)

**MOT #5** 2012-12-01 10:24

**MOT test number** 449686832354

CarCheck.co.uk page 7/15



MOT #4	2011-11-12 09:58
MOT test number	467096111476
Result	<b>✓</b> Passed
MOT #3	2010-11-27 09:57
MOT test number	400591730300
Result	<b>✓</b> Passed
MOT #2	2009-11-30 15:15
MOT test number	110434439337
Result	✓ Passed
MOT #1	2008-11-25 14:22
MOT test number	472750638460
Result	✓ Passed

CarCheck.co.uk page 8/15



### Tax & MOT check



Tax status	Valid until 1 February
Days left	279
MOT expiry date	4 October 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 9/15



### Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



### Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 11/15



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report J		ve?
*******		
************		
	More info	>
Plate changes  See in this check if this BMW had different number plates.		
Number of plates		,
Current registration	NK NEW	
Plate since		
Current registration	NK Nie	
Plate since		
	More info	>

CarCheck.co.uk page 12/15



### Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 13/15



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2004-11-25
Last registration	2023-10-05
Complete history	See info



Registration #1	2004-11-25	29 mi
Registration #2	2008-11-25	34.500 mi
Registration #3	2009-11-30	39.922 mi
Registration #4	2010-11-27	45.519 mi
Registration #5	2011-11-12	51.063 mi
Registration #6	2012-12-01	56.177 mi
Registration #7	2013-11-30	60.061 mi
Registration #8	2013-11-30	60.061 mi
Registration #9	2014-11-28	63.244 mi
Registration #10	2015-12-02	65.987 mi
Registration #11	2015-12-03	65.987 mi
Registration #12	2016-11-14	69.183 mi
Registration #13	2016-11-14	69.183 mi
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		91.777 esi
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		11.777 es
Registration #23		
registration #25		
Registration #24		1.77
		1.77 4



## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1846 mm
Height	1468 mm
Length	4841 mm
Wheel base	2888 mm
Kerb weight	1670 kg
Max. allowed weight	2170 kg

# Additional information

Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	4
Number of seats CarCheck.co.uk	5 page 15/15

Number of axles 2

Engine number 37295820