



HYUNDAI




report date: 2024-03-28

General information

| | |
|---------------------|----------------------------|
| Make | HYUNDAI |
| Model | I30 CRDI ACTIVE BLUE DRIVE |
| Colour | Silver |
| Year of manufacture | 2014 |
| Top speed | 115 mph |
| 0 - 60 mph | 11.5 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 108 BHP |
| Max. torque | 260 Nm at 2.750 rpm |
| Engine capacity | 1.582 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 68.9 mpg |
| Consumption extra urban | 80.7 mpg |
| Consumption combined | 76.3 mpg |
| CO2 emission | 97 g/km |
| CO2 label | A |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-05-20 |
| Pictures | 7 |
| Listing price | View report |



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-03-29 |
| MOT pass rate | 88 % |
| MOT passed | 7 |
| Failed MOT tests | 1 |
| Total advice items | 30 |
| Total items failed | 3 |

| | |
|------------------|------------------|
| MOT #8 | 2024-03-26 10:00 |
| MOT test number | 787565734347 |
| Result | ✓ Passed |
| Next expiry date | 2025-03-29 |

| | |
|-----------------|---|
| MOT #7 | 2023-03-20 10:07 |
| MOT test number | 481421303857 |
| Result | ✓ Passed |
| Advice | Front Brake disc worn, but not excessively (1.1.14 (a) (i)) |
| Advice | Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) |
| Advice | Front Service brake binding but not excessively (1.2.1 (f)) |

| | |
|-----------------|--|
| MOT #6 | 2022-03-30 12:04 |
| MOT test number | 326586128126 |
| Result | ✓ Passed |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |

**MOT #5** 2020-09-11 08:36**MOT test number** 906883292889**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))
- Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #4 2019-09-11 13:32**MOT test number** 553465025096**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Child Seat fitted not allowing full inspection of adult belt
- Advice** Engine cover and undertrays fitted
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Items removed from driver's view prior to test
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #3**

2019-09-10 12:38

MOT test number

573692466695

Result**✗ Failed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Rear fog lamp tell-tale not working (4.9.1 (a) (ii))
- Advice** Child Seat fitted not allowing full inspection of adult belt
- Advice** Engine cover and undertrays fitted
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Brake hydraulic reservoir close to minimum mark (1.1.10 (d) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Rear fog lamp not working (4.5.1 (a) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Items removed from driver's view prior to test
- Advice** TPMS light on
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Offside Front Tyre obviously under inflated (5.2.3 (l))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))

MOT #2

2018-09-11 14:13

MOT test number

793069783776

Result**✓ Passed**



| | |
|-----------------|------------------|
| MOT #1 | 2017-09-11 12:19 |
| MOT test number | 174378745387 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
29 March 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 April |
| Days left | 337 |
| MOT expiry date | 29 March 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|----------------|
| Vehicle class | 49 |
| Band | A |
| Single payment (12 months) | £ 0,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | Not applicable |



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | EJ64ACX |
| Plate since | 2024-03-28 |
| Current registration | EJ64ACX |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

| | | |
|-------------------|----------|----------|
| Finance company | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type | REDACTED | REDACTED |
| Agreement term | REDACTED | REDACTED |
| Agreement number | REDACTED | REDACTED |
| Contact info | REDACTED | REDACTED |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 10 |
| First mileage registration | 2014-11-07 |
| Last registration | 2024-03-26 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2014-11-07 | 11 mi |
| Registration #2 | 2017-09-11 | 44.859 mi |
| Registration #3 | 2018-09-11 | 60.911 mi |
| Registration #4 | 2019-09-10 | 74.216 mi |
| Registration #5 | 2019-09-11 | 74.223 mi |
| Registration #6 | 2019-09-11 | 74.223 mi |
| Registration #7 | 2019-09-11 | 74.223 mi |
| Registration #8 | 2019-09-11 | 74.223 mi |
| Registration #9 | 2019-09-11 | 74.223 mi |
| Registration #10 | 2019-09-11 | 74.223 mi |

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 90% |
| Children | 90% |
| Pedestrian | 67% |
| Safety systems | 86% |
| Overall rating | 85% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1780 mm |
| Height | 1470 mm |
| Length | 4300 mm |
| Wheel base | 2650 mm |
| Kerb weight | 1360 kg |
| Max. allowed weight | 1810 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 53 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|---------------|--------------|
| Engine number | D4FBEZ611665 |
|---------------|--------------|