



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	RAV4 VVT-I EXCEL AWD TSS
Colour	Black
Year of manufacture	2017
Top speed	112 mph
0 - 60 mph	8.4 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	155 BHP
Max. torque	210 Nm at 4.800 rpm
Engine capacity	2.494 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	55.4 mpg
Consumption extra urban	57.6 mpg
Consumption combined	55.4 mpg
CO2 emission	118 g/km
CO2 label	C





Internet history

Entry 2

Date	2021-12-18
Pictures	42
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-12-18
Pictures	0
Listing price	View report

source: [heycar.co.uk](#)



MOT history

MOT expiry date	2024-09-30
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	9
Total items failed	3

MOT #7	2023-09-29 12:26
MOT test number	912173655911
Result	✓ Passed
Next expiry date	2024-09-30

MOT #6	2022-09-08 08:33
MOT test number	895261396355
Result	✓ Passed

MOT #5	2021-09-22 12:31
MOT test number	965689922682
Result	✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #4** 2021-09-22 12:31**MOT test number** 578724855375**Result** ✗ Failed**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #3** 2020-09-24 13:36**MOT test number** 626208138635**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Nearside Front Windscreen damaged but not adversely affecting driver's view chip/crack (3.2 (a) (i))**MOT #2** 2020-09-24 13:36**MOT test number** 545312718086**Result** ✗ Failed**Minor** Nearside Front Windscreen damaged but not adversely affecting driver's view chip/crack (3.2 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Pass with rectification** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**MOT #1** 2020-03-30 20:52**MOT test number** 499945327086**Result** ✓ Passed**Advice** COVID-19 6 MONTH EXTENSION



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
30 September 2024

Tax status	Valid until 1 December
Days left	216
MOT expiry date	30 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	C
Single payment (12 months)	£ 25,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 26,25,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-03-31
Last registration	2023-09-29
Complete history	See info



Registration #1	2017-03-31	19 mi
Registration #2	2020-09-24	26.450 mi
Registration #3	2020-09-24	26.450 mi
Registration #4	2021-09-22	29.203 mi
Registration #5	2021-09-22	29.203 mi
Registration #6	2022-09-29	31.277 mi
Registration #7	2022-09-29	31.277 mi
Registration #8	2023-09-29	31.277 mi
Registration #9	2023-09-29	31.277 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	82%
Pedestrian	66%
Safety systems	66%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1845 mm
Height	1675 mm
Length	4605 mm
Wheel base	2660 mm
Kerb weight	1785 kg
Max. allowed weight	2270 kg

Additional information

Fuel tank capacity	56 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number

2AR1615430