



report date: 2024-03-28

General information

Make	CITROEN
Model	DS4 HDI DSPORT
Colour	Silver
Year of manufacture	2012
Top speed	132 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg
CO2 emission	134 g/km
CO2 label	E





Internet history

Entry 3

Date	2022-11-14
Pictures	0
Listing price	View report

source: [carcraft.co.uk](#)

Entry 2

Date	2021-08-29
Pictures	1
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-08-28
Pictures	1
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-11-16
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	40
Total items failed	5

MOT #16	2023-11-17 14:10
MOT test number	925766694716
Result	✓ Passed
Next expiry date	2024-11-16

**MOT #15**

2023-11-16 08:59

MOT test number

556671180461

Result**✗ Failed**

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- MAJOR** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- MAJOR** Headlamp aim unable to be tested both dip beams not working (4.1.2 (b))
- Advice** Nearside Front Suspension component ball joint has slight play (5.3.4 (a) (i))
- MAJOR** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- MAJOR** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- MAJOR** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Offside Front Suspension component ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Rear Nail in tyre
- Advice** Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Minor** Offside Rear Tyre obviously under inflated (5.2.3 (l))

MOT #14

2022-11-09 11:52

MOT test number

313459487989

Result**✓ Passed**

**MOT #13** 2020-11-30 15:38**MOT test number** 439947004271**Result** ✓ Passed**MOT #12** 2019-11-07 14:44**MOT test number** 361112370406**Result** ✓ Passed**MOT #11** 2019-04-25 15:11**MOT test number** 979776151608**Result** ✓ Passed**MOT #10** 2019-04-24 10:00**MOT test number** 847773648020**Result** ✗ Failed**MAJOR** Offside Front Headlamp aim too low (4.1.2 (a))**Advice** Nearside Front Inner Brake disc worn, but not excessively (1.1.14 (a) (i))**MAJOR** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MAJOR** Nearside Front Outer Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Offside Front Inner Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #9** 2018-09-18 13:40**MOT test number** 804123772688**Result** ✓ Passed

**MOT #8** 2018-09-18 08:47**MOT test number** 730994361844**Result** ✗ Failed**MAJOR** Offside Headlamp aim so that beam "kick up" is not visible on the screen (4.1.2 (a))**DANGEROUS** Nearside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))**MAJOR** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #7** 2017-09-21 13:47**MOT test number** 537441269874**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit 3mm (4.1.E.1)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened both discs corroded and worn (3.5.1i)**Advice** Nearside Front Tyre worn close to the legal limit 3mm (4.1.E.1)**MOT #6** 2017-09-21 10:08**MOT test number** 636749090529**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (1.8)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit 3mm (4.1.E.1)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened both discs corroded and worn (3.5.1i)**Advice** Nearside Front Tyre worn close to the legal limit 3mm (4.1.E.1)**Fail** Windscreen wiper does not clear the windscreen effectively both wipers torn (8.2.2)

**MOT #5** 2016-09-20 11:13**MOT test number** 614220587096**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2016-09-20 08:25**MOT test number** 769601480872**Result** ✗ Failed**Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2015-09-19 11:59**MOT test number** 693131000359**Result** ✓ Passed**Advice** N/s/r tyre on 3m and misshapen**MOT #2** 2015-09-19 11:59**MOT test number** 125143964261**Result** ✗ Failed**Advice** N/s/r tyre on 3m and misshapen**Pass with rectification** Offside Rear Registration plate lamp not working (1.1.C.1d)**MOT #1** 2014-09-16 15:16**MOT test number** 355759054294**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
16 November 2024

Tax status	Valid until 1 April
Days left	338
MOT expiry date	16 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2012-03-30
Last registration	2023-11-17
Complete history	See info



Registration #1	2012-03-30	15 mi
Registration #2	2014-09-16	21.872 mi
Registration #3	2015-09-19	34.691 mi
Registration #4	2015-09-19	34.691 mi
Registration #5	2016-09-20	45.414 mi
Registration #6	2016-09-20	45.414 mi
Registration #7	2017-09-21	52.921 mi
Registration #8	2017-09-21	52.921 mi
Registration #9	2018-09-18	63.700 mi
Registration #10	2018-09-18	63.700 mi
Registration #11	2019-09-19	75.277 mi
Registration #12	2019-09-19	75.277 mi
Registration #13	2020-09-20	86.854 mi
Registration #14	2020-09-20	86.854 mi
Registration #15	2021-09-21	98.431 mi
Registration #16	2021-09-21	98.431 mi
Registration #17	2022-09-22	110.008 mi
Registration #18	2022-09-22	110.008 mi
Registration #19	2023-11-17	121.585 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	80%
Pedestrian	43%
Safety systems	97%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1523 mm
Length	4275 mm
Wheel base	2612 mm
Kerb weight	1320 kg
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	DYYF4097689