




report date: 2024-03-29

General information

Make	NISSAN
Model	PRIMERA FLARE
Colour	Blue
Year of manufacture	2005
Top speed	117 mph
0 - 60 mph	11.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	163 Nm at 4.000 rpm
Engine capacity	1.769 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	46.3 mpg
Consumption combined	38.2 mpg
CO2 emission	177 g/km
CO2 label	I






Internet history

Entry 1

Date	2022-02-07
Pictures	42
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2025-02-07
MOT pass rate	67 %
MOT passed	18
Failed MOT tests	9
Total advice items	57
Total items failed	15

MOT #27 2024-02-05 13:18

MOT test number 672454185743

Result ✓ Passed

Next expiry date 2025-02-07

**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement  
Rear bush beginning to crack (5.3.4 (a) (i))

**Advice** Rear Sub-frame is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

MOT #26 2024-02-05 13:18

MOT test number 237866016320

Result ✗ Failed

**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement  
Rear bush beginning to crack (5.3.4 (a) (i))

**Advice** Rear Sub-frame is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))

**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #25**

2023-02-06 08:08

**MOT test number**

270049813219

**Result**

✓ Passed

**Advice** Front Exhaust mounting defective (6.1.2 (a))**Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #24**

2022-02-08 17:24

**MOT test number**

780566647654

**Result**

✓ Passed

**Advice** Nearside Rear Inner Integral body structure is corroded but structural rigidity is not significantly reduced sill (6.1.1 (c) (i))**Advice** Offside Rear Inner Integral body structure is corroded but structural rigidity is not significantly reduced sill (6.1.1 (c) (i))**MOT #23**

2022-02-02 11:29

**MOT test number**

110403909722

**Result**

✓ Passed

**Advice** Nearside Rear Inner Integral body structure is corroded but structural rigidity is not significantly reduced Inner sill has corrosion. (6.1.1 (c) (i))**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge Worn on inner edge. (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge Worn close to limit. (5.2.3 (e))**Advice** Offside Front Brake pipe corroded, covered in grease or other material Covered in grease. (1.1.11 (c))**Advice** Offside Rear Inner Integral body structure is corroded but structural rigidity is not significantly reduced Inner sill has corrosion. (6.1.1 (c) (i))**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge Worn on inner edge. (5.2.3 (e))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material Covered in grease. (1.1.11 (c))

**MOT #22**

2021-11-24 17:22

**MOT test number**

108659855807

**Result**

✓ Passed

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Both front tyres wearing on inner edges**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Covers fitted to outer sills**MOT #21**

2021-11-23 08:30

**MOT test number**

355924739911

**Result**

✗ Failed

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Both front tyres wearing on inner edges**Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Covers fitted to outer sills**Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))**MOT #20**

2020-11-24 08:35

**MOT test number**

651017330976

**Result**

✓ Passed

**Advice** Covers fitted to outersills**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #19**

2020-11-23 10:18

**MOT test number**

678000477904

**Result****✗ Failed****Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Covers fitted to outersills**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #18**

2019-04-18 07:27

**MOT test number**

754327491471

**Result****✓ Passed****Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Exhaust system deteriorated**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Outer-sill covers fitted**Advice** Engine undertray fitted**MOT #17**

2018-04-03 10:10

**MOT test number**

306341558799

**Result****✓ Passed****MOT #16**

2018-04-03 09:02

**MOT test number**

196581827113

**Result****✗ Failed****Advice** Exhaust heat-shield loose**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #15** 2017-04-20 15:49**MOT test number** 989854878000**Result** ✓ Passed**Advice** Exhaust heat shield insecure**MOT #14** 2017-04-20 07:38**MOT test number** 625381214460**Result** ✗ Failed**Advice** Rear brakes dragging on, recommend attention**Fail** Offside front brake binding (3.7.B.1)**Advice** Front brake discs corroded**Advice** Exhaust heat shield insecure**MOT #13** 2016-04-25 10:14**MOT test number** 452908440152**Result** ✓ Passed**MOT #12** 2016-04-23 08:06**MOT test number** 944159541594**Result** ✗ Failed**Fail** Offside Front Mechanical brake component has restricted free movement (3.5.1k)**Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #11** 2015-04-21 09:31**MOT test number** 475271615181**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #10** 2014-04-03 14:54**MOT test number** 115313994404**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #9** 2013-03-19 15:31**MOT test number** 987148673007**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #8** 2012-04-02 11:48**MOT test number** 548703092006**Result** ✓ Passed**Advice** Offside Track rod end ball joint has slight play (2.2.B.1f)**Notice** Uneven tyre wear n/s/r**MOT #7** 2012-04-02 11:48**MOT test number** 586383992076**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (1.8)**Advice** Offside Track rod end ball joint has slight play (2.2.B.1f)**Notice** Uneven tyre wear n/s/r**MOT #6** 2011-03-22 09:41**MOT test number** 917801481087**Result** ✓ Passed**Notice** Front discs and pads corroded and worn - recheck in 6000m/s



**MOT #5** 2011-03-22 09:41**MOT test number** 206671381013**Result** ✗ Failed**Notice** Front discs and pads corroded and worn - recheck in 6000m/s**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #4** 2010-03-16 09:20**MOT test number** 164675670026**Result** ✓ Passed**Advice** Brake disc slightly scored (3.5.1h)**MOT #3** 2009-04-01 18:00**MOT test number** 473041599093**Result** ✓ Passed**MOT #2** 2009-04-01 11:09**MOT test number** 564601999025**Result** ✗ Failed**Fail** Brake disc excessively pitted (3.5.1h)**Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #12008-04-07 17:14

MOT test number852148598000

Result

✓ Passed

Advice

Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

Advice

Rear brake disc slightly pitted (3.5.1h)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
7 February 2025

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	277
<b>MOT expiry date</b>	7 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-




Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	27
First mileage registration	2005-04-06
Last registration	2024-02-05
Complete history	<a href="#">See info</a>



Registration #1	2005-04-06	25 mi
Registration #2	2008-04-07	23.146 mi
Registration #3	2009-04-01	27.031 mi
Registration #4	2009-04-01	27.033 mi
Registration #5	2010-03-16	30.644 mi
Registration #6	2011-03-22	34.106 mi
Registration #7	2012-04-02	36.977 mi
Registration #8	2013-03-19	42.244 mi
Registration #9	2014-04-03	44.613 mi
Registration #10	2015-04-21	45.596 mi
Registration #11	2016-04-23	50.313 mi
Registration #12	2016-04-25	50.318 mi
Registration #13	2017-04-20	54.825 mi
Registration #14	2017-04-20	54.825 mi
Registration #15	2018-04-20	55.317 mi
Registration #16	2018-04-20	55.317 mi
Registration #17	2018-04-20	55.317 mi
Registration #18	2018-04-20	55.317 mi
Registration #19	2018-04-20	55.317 mi
Registration #20	2018-04-20	55.317 mi
Registration #21	2018-04-20	55.317 mi
Registration #22	2018-04-20	55.317 mi
Registration #23	2018-04-20	55.317 mi
Registration #24	2018-04-20	55.317 mi
Registration #25	2018-04-20	55.317 mi
Registration #26	2018-04-20	55.317 mi



More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1998 mm
Height	1482 mm
Length	4567 mm
Wheel base	2680 mm
Kerb weight	1361 kg
Max. allowed weight	1810 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	423268