




report date: 2024-03-29

General information

Make	VOLVO
Model	XC90 D5 ACTIVE AWD
Colour	Black
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	182 BHP
Max. torque	400 Nm at 2.750 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	25.4 mpg
Consumption extra urban	40.4 mpg
Consumption combined	33.2 mpg
CO2 emission	224 g/km
CO2 label	K





MOT history

MOT expiry date	2024-05-12
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	11
Total items failed	3

MOT #12	2023-05-11 11:59
MOT test number	920981048690
Result	✓ Passed
Next expiry date	2024-05-12
Advice	Rear Direction indicator slightly discoloured (4.4.3 (a))

MOT #11	2022-04-27 12:38
MOT test number	241178853506
Result	✓ Passed
Advice	Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #10	2021-05-10 14:24
MOT test number	512755056240
Result	✓ Passed

MOT #9	2020-05-13 14:50
MOT test number	582418863962
Result	✓ Passed

**MOT #8** 2020-05-13 10:23**MOT test number** 671008964454**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm 235/60R18 (5.2.3 (e))**MOT #7** 2018-10-30 09:00**MOT test number** 317586516952**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2017-11-02 12:49**MOT test number** 725909251844**Result** ✓ Passed**MOT #5** 2016-10-06 13:52**MOT test number** 730360190500**Result** ✓ Passed**MOT #4** 2016-10-06 07:50**MOT test number** 196653799151**Result** ✗ Failed**Advice** Both rear tyres worn**Fail** Offside Front position lamp(s) not working (1.1.A.3b)



MOT #3	2015-10-06 07:39
MOT test number	421029408589
Result	✓ Passed

MOT #2	2014-10-01 10:04
MOT test number	865904974253
Result	✓ Passed

Notice Both front tyres worn on edges

MOT #1	2013-09-24 12:25
MOT test number	848397363278
Result	✓ Passed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
12 May 2024

Tax status	Valid until 1 June
Days left	34
MOT expiry date	12 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2010-10-16
Last registration	2023-05-11
Complete history	See info



Registration #1	2010-10-16	19 mi
Registration #2	2013-09-24	26.941 mi
Registration #3	2014-10-01	33.867 mi
Registration #4	2015-10-06	40.833 mi
Registration #5	2016-10-06	47.782 mi
Registration #6	2016-10-06	47.782 mi
Registration #7	2017-11-02	55.062 mi
Registration #8	2018-05-22	62.332 mi
Registration #9	2019-05-22	69.602 mi
Registration #10	2020-05-22	76.872 mi
Registration #11	2021-05-22	84.142 mi
Registration #12	2022-05-22	91.412 mi
Registration #13	2023-05-11	98.682 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1898 mm
Height	1784 mm
Length	4798 mm
Wheel base	2857 mm
Kerb weight	2130 kg
Max. allowed weight	2750 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number

784551