



HONDA



report date: 2024-03-28

General information

Make	HONDA
Model	ACCORD I-DTEC ES GT
Colour	Black
Year of manufacture	2012
Top speed	129 mph
0 - 60 mph	10.3 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	148 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	33.2 mpg
Consumption extra urban	53.3 mpg
Consumption combined	44.1 mpg
CO2 emission	159 g/km
CO2 label	G






Internet history

Entry 2


Date	2022-01-18
Pictures	12
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2021-08-28
Pictures	12
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)



MOT history

MOT expiry date	2024-06-25
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	52
Total items failed	2

MOT #16	2023-06-26 10:10
MOT test number	729761914255
Result	✓ Passed
Next expiry date	2024-06-25

MOT #15	2023-06-16 12:02
MOT test number	677193436884
Result	✗ Failed
MAJOR	Nearside Headlamp aim unable to be tested not working (4.1.2 (b))
MAJOR	Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt both (5.3.4 (b) (ii))
MAJOR	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #14**

2022-06-09 10:35

**MOT test number**

401300103457

**Result**

✓ Passed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Under trays obstruct the ability to see a majority of underside components
- Minor** Windscreen wiper blade defective both sides slightly smeary (3.4 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Windscreen damaged but not adversely affecting driver's view chip (3.2 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13**

2021-05-27 10:12

**MOT test number**

113325766659

**Result**

✓ Passed

- Advice** Nearside Front Upper Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Vehicles internal headlight adjuster altered to recheck lights
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Upper Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Items removed from driver's view prior to test

**MOT #12**

2021-05-27 09:58

**MOT test number**

737994500642

**Result****✗ Failed**

- MAJOR** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Nearside Front Upper Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Vehicles internal headlight adjuster altered to recheck lights
- MAJOR** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Offside Front Upper Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Items removed from driver's view prior to test
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11**

2020-06-19 13:44

**MOT test number**

417159003323

**Result****✓ Passed**

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2 mm (5.2.3 (e))
- Advice** Offside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor** Nearside Front Tyre obviously under inflated and perished (5.2.3 (l))
- Advice** Rear Anti-roll bar pin or bush worn but not resulting in excessive movement ( d ) bushes (5.3.4 (a) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #10**

2020-06-16 13:37

**MOT test number**

850194503250

**Result****✗ Failed**

**Advice** Rear Anti-roll bar pin or bush worn but not resulting in excessive movement ( d ) bushes (5.3.4 (a) (i))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))

**Advice** Nearside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MAJOR** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MAJOR** Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Minor** Nearside Front Tyre obviously under inflated and perished (5.2.3 (l))

**DANGEROUS** Offside Front Inner Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2 mm (5.2.3 (e))

**MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**Advice** Offside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MAJOR** Nearside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

**MOT #9**

2019-07-29 18:45

**MOT test number**

837795009381

**Result****✓ Passed**

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #8** 2019-07-29 15:31**MOT test number** 119791263733**Result** ✗ Failed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))**MAJOR** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #7** 2019-06-08 10:10**MOT test number** 734389034430**Result** ✓ Passed**MOT #6** 2018-05-15 15:20**MOT test number** 976648357685**Result** ✓ Passed**MOT #5** 2017-06-12 09:36**MOT test number** 484301422273**Result** ✓ Passed**MOT #4** 2017-05-09 09:46**MOT test number** 568262871010**Result** ✓ Passed



MOT #3	2016-10-26 10:38
MOT test number	295773761470
Result	✓ Passed

MOT #2	2016-10-26 10:38
MOT test number	461157461337
Result	✗ Failed
Pass with rectification	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Pass with rectification	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #1	2015-11-18 12:12
MOT test number	508071729647
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
25 June 2024

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	34
<b>MOT expiry date</b>	25 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history


Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2012-11-28
Last registration	2023-06-26
Complete history	<a href="#">See info</a>



Registration #1	2012-11-28	15 mi
Registration #2	2015-11-18	32.888 mi
Registration #3	2016-10-26	39.296 mi
Registration #4	2016-10-26	39.296 mi
Registration #5	2017-05-09	42.027 mi
Registration #6	2017-06-12	42.239 mi
Registration #7	2018-05-15	45.335 mi
Registration #8	2019-06-08	48.032 mi
Registration #9	2019-07-29	49.067 mi
Registration #10	2019-07-29	49.069 mi
Registration #11	2019-06-26	50.000 mi
Registration #12	2019-06-26	50.000 mi
Registration #13	2019-06-26	50.000 mi
Registration #14	2019-06-26	50.000 mi
Registration #15	2019-06-26	50.000 mi
Registration #16	2019-06-26	50.000 mi
Registration #17	2019-06-26	50.000 mi
Registration #18	2019-06-26	50.000 mi
Registration #19	2019-06-26	50.000 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	86%
Children	79%
Pedestrian	54%
Safety systems	86%
Overall rating	78%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1840 mm
Height	1440 mm
Length	4725 mm
Wheel base	2705 mm
Kerb weight	1700 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number	N22B13501347