



report date: 2024-03-29

General information

Make	VAUXHALL
Model	COMBO 2000 CDTI
Colour	White
Year of manufacture	2007
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	240 Nm at 2.300 rpm
Engine capacity	1.686 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	64.2 mpg
Consumption combined	54.3 mpg



LABEL UNKNOWN



MOT history

MOT expiry date	2022-09-14
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	39
Total items failed	18

MOT #17	2021-09-12 14:36
MOT test number	453841530605
Result	✓ Passed
Next expiry date	2022-09-14
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front vehicle has damage to sill
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Play in steering rack inner joint(s)
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #16**

2021-09-10 09:14

**MOT test number**

450295737888

**Result****✗ Failed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Play in steering rack inner joint(s)
- Fail** Offside Front Side repeater incorrect colour (4.4.3 (a))
- Fail** Front Bumper insecure (6.1.4 (a) (i))
- Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Offside Front Side repeater lens defective such that the emitted light is adversely affected (4.4.1 (b) (ii))
- Advice** Offside Front vehicle has damage to sill
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))

**MOT #15**

2020-08-28 11:35

**MOT test number**

107223223965

**Result****✓ Passed**

- Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14** 2020-08-27 13:35**MOT test number** 203076707428**Result** ✗ Failed**Fail** Rear Exhaust system insecure (6.1.2 (a))**Fail** Nearside Rear Outer Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Offside Rear Brake pipe excessively corroded to hub (1.1.11 (c))**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13** 2019-09-13 09:14**MOT test number** 648692113259**Result** ✓ Passed**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #12** 2018-09-15 08:11**MOT test number** 196682339195**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #11** 2017-07-29 08:16**MOT test number** 739594568655**Result** ✓ Passed



MOT #102016-07-05 13:43

MOT test number896863689571

Result

✓ Passed

- Advice

Coolant leak engine
- Advice

Offside Rear Brake pipe slightly corroded axle flexi to o/s/r caliper flexi (3.6.B.2c)
- Advice

Nearside Rear Tyre worn close to the legal limit bold inner edge (4.1.E.1)
- Advice

Front Brake pad(s) wearing thin both (3.5.1g)
- Advice

Gearbox mounting defective gearbox to subframe
- Advice

Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice

Offside Front Shock absorber has a light misting of oil (2.7.3)
- Advice

Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)

**MOT #9**

2016-07-05 08:33

**MOT test number**

810801466329

**Result****✗ Failed**

- Advice** Front Brake pad(s) wearing thin both (3.5.1g)
- Fail** Offside Rear Registration plate lamp not working (1.1.C.1d)
- Advice** Gearbox mounting defective gearbox to subframe
- Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)
- Fail** Windscreen washer provides insufficient washer liquid (8.2.3)
- Advice** Coolant leak engine
- Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)
- Advice** Offside Rear Brake pipe slightly corroded axle flexi to o/s/r caliper flexi (3.6.B.2c)
- Advice** Nearside Rear Tyre worn close to the legal limit bold inner edge (4.1.E.1)

**MOT #8**

2015-07-27 11:09

**MOT test number**

437158705257

**Result****✓ Passed**

- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Steering system slightly tight (2.2.D.1)

**MOT #7** 2015-07-25 12:10**MOT test number** 455396605290**Result** ✗ Failed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear coil spring broken (2.4.C.1a)**Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Steering system slightly tight (2.2.D.1)**Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**MOT #6** 2014-07-23 16:24**MOT test number** 326034404406**Result** ✓ Passed**MOT #5** 2014-07-23 09:15**MOT test number** 665623804255**Result** ✗ Failed**Fail** Nearside Front Headlamp not working on dipped beam (1.7.5a)**Fail** Rear Registration plate lamp not working (1.1.C.1d)**Fail** Offside Front Headlamp not working on dipped beam (1.7.5a)**MOT #4** 2013-07-05 15:42**MOT test number** 279096883466**Result** ✓ Passed



MOT #3	2012-07-30 15:23
MOT test number	179062412275
Result	✓ Passed
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #2	2011-05-19 11:51
MOT test number	887989531118
Result	✓ Passed

MOT #1	2010-05-13 09:38
MOT test number	421503530191
Result	✓ Passed





Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 <b>FP07LBU</b>
Plate since	2024-03-29
Current registration	 <b>FP07LBU</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-05-22
Last registration	2021-09-12
Complete history	<a href="#">See info</a>



Registration #1	2007-05-22	19 mi
Registration #2	2010-05-13	17.521 mi
Registration #3	2011-05-19	28.332 mi
Registration #4	2012-07-30	39.555 mi
Registration #5	2013-07-05	51.287 mi
Registration #6	2014-07-23	64.251 mi
Registration #7	2014-07-23	64.251 mi
Registration #8	2015-07-25	75.807 mi
Registration #9	2015-07-27	75.811 mi
Registration #10	2016-05-22	85.217 mi
Registration #11	2016-05-22	85.217 mi
Registration #12	2016-05-22	85.217 mi
Registration #13	2016-05-22	85.217 mi
Registration #14	2016-05-22	85.217 mi
Registration #15	2016-05-22	85.217 mi
Registration #16	2016-05-22	85.217 mi
Registration #17	2016-05-22	85.217 mi
Registration #18	2016-05-22	85.217 mi

More info >



Dimensions & weight

Width	1892 mm
Height	1801 mm
Length	4323 mm
Kerb weight	1453 kg
Max. allowed weight	1995 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	01536760