





report date: 2024-03-29

General information

Make	MINI
Model	MINI (R60) COOPER S
Colour	Black
Year of manufacture	2011
Top speed	133 mph
0 - 60 mph	7.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	190 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Petrol
Consumption combined	44.8 mpg
CO2 emission	143 g/km
CO2 label	F



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 2

Date 2022-12-14

Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date	2021-06-30
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/13



WG61HDD report date: 2024-03-29

MOT history

MOT ovnimy data	2024 11 10
MOT expiry date	2024-11-10
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	21
Total items failed	5

MOT #14	2023-11-11 13:52
MOT test number	851831298807
Result	✓ Passed
Next expiry date	2024-11-10
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Front side repeater cover missing	

MOT #13		2023-11-11 13:52
MOT test number		255530142537
Result		X Failed
Advice Offside Front sid	e repeater cover missing	
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))	
Advice Offside Rear Tyre	e worn close to legal limit/worn on edge (5.2.3 (e))	
Pass with rectification	Offside Front Direction indicator not working (4.4.1 (a) (ii))	

MOT #12		2022-11-10 14:29
MOT test	number	542567325322
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT test number

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #10 2021-10-25 08:38

MOT test number 424246165240

Result ✓ Passed

MOT #9

MOT test number

975847599779

Result

✓ Passed

MOT #8 2020-10-26 10:35

MOT test number 380699356601

Result X Failed

Fail Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

 MOT #7
 2019-11-08 16:01

 MOT test number
 817843682805

 Result
 ✓ Passed

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT test number

Result

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

 MOT #5
 2018-11-09 17:35

 MOT test number
 354270515154

 Result
 ✓ Passed

MOT #4 2018-01-25 09:48

MOT test number 327091427997

Result ✓ Passed

MOT #3 2016-12-15 11:51

MOT test number 886915062221

Result \(\sqrt{Passed} \)

Advice Under-trays fitted.

Advice O/s/r tyre worn badly on inside edge & has nail in tread.

MOT #2 2015-09-21 15:58

MOT test number 783543503257

Result ✓ Passed

Advice Under-Trays Fitted

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #1		2015-01-09 10:06
MOT test	number	986699705050
Result		✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice	Under-trays fitted obscuring some underside components	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	10 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

_		
Owne	 	
	ΙСΤ	nrv
	 IJL	

e when mistery	
For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report <u>l</u>	
MARKET STATE OF THE STATE OF TH	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	,
Current registration	OK ONE
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-12-30
Last registration	2023-11-11
Complete history	See info



Registration #1	2011-12-30	25 mi
Registration #2	2015-01-09	14.557 mi
Registration #3	2015-09-21	16.919 mi
Registration #4	2016-12-15	25.661 mi
Registration #5	2018-01-25	31.400 mi
Registration #6	2018-11-09	35.406 mi
Registration #7	2019-11-07	43.575 mi
Registration #8	2019-11-08	43.575 mi
Registration #9	2020-10-26	50.736 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.177 mi

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
60482	
0501	
0566	
0567	
60569	

Safety ratings

NCAP rating	****
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1577 mm
Length	4097 mm
Kerb weight	1310 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	47
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Engine number CarCheck.co.uk	A431I943 page 13/13