





report date: 2024-03-28

General information

Make	CITROEN	
Model	BERLINGO BLUEHDI FLAIR M	
Colour	White	
Year of manufacture	2019	
Top speed	109 mph	
0 - 60 mph	12.9 seconds	
Gearbox	5 speed Manual	

Engine & fuel consumption

Power	101 BHP	
Max. torque	250 Nm at 1.750 rpm	
Engine capacity	1.500 cc	
Cylinders	4	
Fuel type	Diesel	
Consumption city	58.9 mpg	
Consumption extra urban	68.9 mpg	
Consumption combined	64.2 mpg	
CO2 emission	112 g/km	
CO2 label	С	



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 2

Date 2021-07-09

Pictures 26

Listing price <u>View report</u>









source: heycar.co.uk

Entry 1

Date	2021-05-26
Pictures	10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT history

MOT expiry date	2024-06-26
MOT pass rate	67 %
MOT passed	2
Failed MOT tests	1
Total advice items	10
Total items failed	0

MOT #3	2023-06-23 10:56
MOT test number	303132068895
Result	✓ Passed
Next expiry date	2024-06-26
Advice Tyre slightly damaged/cracking or perishing X4 (5.2.3 (d) (ii))	

MOT #2		022 06 14 10:40
MOT #2		022-06-14 10:40
MOT test	number	723835548832
Result		✓ Passed
Advice	Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords	(5.2.3 (d) (i))
Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))		
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #1 2022-06-13 13:14

MOT test number 862539430961

Advice

Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice

Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MAJOR

Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MAJOR Windscreen washer provides insufficient washer liquid (3.5 (a))

MAJOR Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords in tread (5.2.3 (d) (i))

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	26 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
First licence fee (12 months)	£ 210,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history	
For how long did the current and previous owner(s) have this CITROEN? How many owne have? Check it in the premium report and see all owner registrations. Download the full respectively.	

	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	
Current registration	ZIE ZIK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



LO19BYZ report date: 2024-03-28

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



LO19BYZ report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2019-06-27
Last registration	2023-06-23
Complete history	See info



Registration #1	2019-06-27	9 mi
Registration #2		0.77 66
Registration #3		9.77 sc
Registration #4		11.777 es
Registration #5		11.777 no
Designation #6		

Registration #6

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Safety ratings

NCAP rating	****
Adult	91%
Children	81%
Pedestrian	58%
Safety systems	68%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	2107 mm
Height	1849 mm
Length	4753 mm
Wheel base	2975 mm
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Q3BE0216038

CarCheck.co.uk page 11/11