



report date: 2024-03-28

General information

Make	VOLVO
Model	V50 S S40
Colour	Black
Year of manufacture	2009
Top speed	115 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	150 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.2 mpg
CO2 emission	169 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-08-11
Pictures	16
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-13
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	20
Total items failed	8

MOT #16	2023-11-02 15:50
MOT test number	780147682111
Result	✓ Passed
Next expiry date	2024-11-13
Advice	Offside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))
Advice	Nearside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))

MOT #15	2023-10-24 09:57
MOT test number	576007379842
Result	✗ Failed
MAJOR	Offside Front Inner Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))
Advice	Offside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))
DANGEROUS	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
MAJOR	Offside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Nearside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))
MAJOR	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Minor	Offside Front Tyre obviously under inflated (5.2.3 (l))

**MOT #14** 2022-11-01 10:39**MOT test number** 841391246020**Result** ✓ Passed**MOT #13** 2021-10-26 11:15**MOT test number** 363965421049**Result** ✓ Passed**Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning sidelight (4.2.1 (a) (i))**Advice** Nearside Front headlamp light intensity low**MOT #12** 2020-11-03 09:09**MOT test number** 602240461603**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**MOT #11** 2019-10-29 09:01**MOT test number** 880946178700**Result** ✓ Passed**MOT #10** 2018-10-30 10:59**MOT test number** 967889145704**Result** ✓ Passed**MOT #9** 2017-11-14 12:01**MOT test number** 272277829156**Result** ✓ Passed

**MOT #8**

2017-11-08 16:08

MOT test number

528135891163

Result**✗ Failed**

- Fail** Offside Stop lamp not working (1.2.1b)
- Fail** Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement rear (2.4.G.2)
- Fail** Nearside Rear position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement rear (2.4.G.2)
- Fail** Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)

MOT #7

2017-02-22 13:06

MOT test number

461711500410

Result**✓ Passed**

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #6

2016-02-10 13:44

MOT test number

114220356178

Result**✓ Passed**

- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #5

2015-02-20 14:12

MOT test number

308891055016

Result**✓ Passed**

**MOT #4** 2014-02-12 16:03**MOT test number** 346413044041**Result** ✓ Passed**MOT #3** 2014-02-12 14:06**MOT test number** 479133844067**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #2** 2013-02-06 14:09**MOT test number** 715607533087**Result** ✓ Passed**MOT #1** 2012-02-29 16:26**MOT test number** 165580162475**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
13 November 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	13 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-03-05
Last registration	2023-11-02
Complete history	See info



Registration #1	2009-03-05	21 mi
Registration #2	2012-02-29	40.200 mi
Registration #3	2013-02-06	50.464 mi
Registration #4	2014-02-12	64.322 mi
Registration #5	2014-02-12	64.322 mi
Registration #6	2015-02-20	77.327 mi
Registration #7	2016-02-10	86.750 mi
Registration #8	2017-02-22	97.356 mi
Registration #9	2017-11-08	103.720 mi
Registration #10	2018-05-20	111.277 mi
Registration #11	2018-05-20	111.277 mi
Registration #12	2018-05-20	111.277 mi
Registration #13	2018-05-20	111.277 mi
Registration #14	2018-05-20	111.277 mi
Registration #15	2018-05-20	111.277 mi
Registration #16	2018-05-20	111.277 mi
Registration #17	2018-05-20	111.277 mi
Registration #18	2018-05-20	111.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1322 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	180553