



report date: 2024-03-29

General information

Make	KIA
Model	CARENS CRDI 2
Colour	Silver
Year of manufacture	2011
Top speed	111 mph
0 - 60 mph	12.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	126 BHP
Max. torque	260 Nm at 1.900 rpm
Engine capacity	1.582 cc
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	54.3 mpg
Consumption combined	49.6 mpg
CO2 emission	146 g/km
CO2 label	F







Internet history

Entry 1

Date	2021-11-09
Pictures	12
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-01-16
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	46
Total items failed	9

MOT #15	2024-01-15 12:54
---------	------------------

MOT test number	242791573370
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2025-01-16
------------------	------------

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement forward bush (5.3.4 (a) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge & cracking (5.2.3 (e))
- Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
- Advice** Parking brake lever travel
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge & cracking (5.2.3 (e))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement forward bush (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

**MOT #14**

2024-01-15 10:30

**MOT test number**

324695678000

**Result****✗ Failed**

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge & cracking (5.2.3 (e))
- Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
- Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Side repeater incorrect colour (4.4.3 (a))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement forward bush (5.3.4 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge & cracking (5.2.3 (e))
- Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement forward bush (5.3.4 (a) (i))
- Advice** Parking brake lever travel

**MOT #13**

2023-01-17 16:55

**MOT test number**

549195173602

**Result****✓ Passed**

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Inside edge (5.2.3 (e))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #12** 2023-01-11 14:08**MOT test number** 371833014798**Result** ✗ Failed**Fail** Offside Front Service brake excessively binding (1.2.1 (f))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Brake pedal has insufficient reserve travel (1.1.2 (a))**Fail** Offside Headlamp light intensity severely reduced (4.1.4 (a))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Inside edge (5.2.3 (e))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #11** 2022-01-13 16:17**MOT test number** 586164626882**Result** ✓ Passed**MOT #10** 2021-04-29 15:26**MOT test number** 346139751922**Result** ✓ Passed**MOT #9** 2020-03-23 12:18**MOT test number** 872235797800**Result** ✓ Passed**Advice** Engine covers fitted

**MOT #8** 2019-09-17 10:19**MOT test number** 868073453103**Result** ✓ Passed

**Advice** Brake disc worn, pitted or scored, but not seriously weakened Both Front discs lipped (1.1.14 (a) (ii))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Low tread and perishing (5.2.3 (e))

**Minor** Windscreen damaged but not adversely affecting driver's view Small chip in screen (3.2 (a) (i))

**Advice** Brake disc worn, pitted or scored, but not seriously weakened Both Rear discs lipped (1.1.14 (a) (ii))

**Advice** Slight corrosion on exhaust brackets

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge Low tread and perishing (5.2.3 (e))

**MOT #7** 2018-09-19 13:58**MOT test number** 547764198836**Result** ✓ Passed

**Advice** Offside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))

**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge worn on edges (5.2.3 (e))

**Advice** Rear Passenger seat(s) missing at time of test 3rd row

**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge worn on edges (5.2.3 (e))

**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #6** 2017-08-24 08:09**MOT test number** 208807933457**Result** ✓ Passed

- Advice** Nearside Front wiper split on ends but still clearing screen
- Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Rear, rear seats folded down, unable to check seatbelt operation/condition
- Advice** Offside Front wiper split on ends but still clearing screen

**MOT #5** 2016-08-24 11:09**MOT test number** 724353257723**Result** ✓ Passed

- Advice** Rear Passenger seat(s) missing at time of test
- Advice** Vehicles internal headlight adjuster altered to recheck lights
- Advice** Engine covers fitted
- Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #4** 2015-09-16 14:14**MOT test number** 105078417948**Result** ✓ Passed**MOT #3** 2014-09-15 12:51**MOT test number** 268758854256**Result** ✓ Passed**MOT #2** 2014-04-30 15:16**MOT test number** 335180224181**Result** ✓ Passed



MOT #1	2014-04-30 15:16
MOT test number	387100524127
Result	✗ Failed
Pass with rectification (8.2.2)	Nearside Front Windscreen wiper does not clear the windscreen effectively
Pass with rectification	Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
16 January 2025

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	246
<b>MOT expiry date</b>	16 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	<b>PK11THX</b>
Plate since	2024-03-29
Current registration	<b>PK11THX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-06-21
Last registration	2024-01-15
Complete history	<a href="#">See info</a>



Registration #1	2011-06-21	8 mi
Registration #2	2014-04-30	11.771 mi
Registration #3	2014-09-15	13.020 mi
Registration #4	2015-09-16	23.154 mi
Registration #5	2016-08-24	33.052 mi
Registration #6	2017-08-24	41.148 mi
Registration #7	2018-09-19	48.115 mi
Registration #8	2019-09-17	54.909 mi
Registration #9	2020-09-17	61.703 mi
Registration #10	2021-09-17	68.497 mi
Registration #11	2022-09-17	75.291 mi
Registration #12	2023-09-17	82.085 mi
Registration #13	2024-01-15	88.879 mi
Registration #14	2024-01-15	95.673 mi
Registration #15	2024-01-15	102.467 mi
Registration #16	2024-01-15	109.261 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1700 mm
Length	4545 mm
Wheel base	2700 mm
Kerb weight	1715 kg
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

<b>Number of axles</b>	2
<b>Engine number</b>	D4FBBH700617