





report date: 2024-03-29

General information

Make	BMW
Model	640 640I M SPORT GRAN COUPE
Colour	Black
Year of manufacture	2015
Top speed	155 mph
0 - 60 mph	5.4 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	315 BHP
Max. torque	450 Nm at 1.300 rpm
Engine capacity	2.979 сс
Cylinders	6
Fuel type	Petrol
Consumption city	25.9 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.2 mpg
CO2 emission	182 g/km
CO2 label	I



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 2

Date 2022-06-21

Pictures 11

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2022-01-07	
-----------------	--

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



AK65FYU report date: 2024-03-29

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2025-01-18
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	11
Total items failed	2

MOT #8	2024-01-19 17:37
MOT test number	851655407634
Result	✓ Passed
Next expiry date	2025-01-18

MOT #7		2023-04-12 11:04
MOT test	number	274651507375
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #6	2022-03-18 13:28
MOT test number	744248541616
Result	✓ Passed

MOT #5	2021-04-17 14:01
MOT test number	640718015284
Result	✓ Passed

CarCheck.co.uk page 3/11



Advice

AK65FYU

report date: 2024-03-29

MOT #4 2020-11-18 12:23 **MOT** test number 505085061921 ✓ Passed Result **Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement shock mount rubber (5.3.4 (a) (i)) **Advice** Offside Front Tyre slightly damaged tread slightly damaged (5.2.3 (d) (ii)) **Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement shock mount rubber (5.3.4 (a) (i)) **Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt Offside Front Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e)) Advice

MOT #3

MOT test number

Result

Advice Offside Front Shock gaiter split/adrift

2019-10-31 16:56

324994720619

✓ Passed

Offside Front shock absorber bellows split. shock still working as it should.

MOT test number

Result

Pass with rectification

Offside Headlamp aim too high (4.1.2 (a))

Pass with rectification

Nearside Headlamp aim too high (4.1.2 (a))

Advice

Offside Front Shock gaiter split/adrift

MOT #1

MOT test number

Result

Advice

Offside Rear Child Seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 4/11



AK65FYU report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 January
Days left	246
MOT expiry date	18 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	T
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



AK65FYU report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

_	
Owner	history
OWITCE	ilistoi y

For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report	
THE STATE OF THE S	

	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	
Current registration	UK NIK
Plate since	
Current registration	NK NK
Plate since	mn.n.n
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-11-27
Last registration	2024-01-19
Complete history	See info



Registration #1	2015-11-27	22 mi
Registration #2	2018-10-29	24.683 mi
Registration #3	2019-10-31	31.036 mi
Registration #4	2019-10-31	31.036 mi
Registration #5	2020-11-18	34.423 mi
Registration #6	2021-04-17	34.785 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		9.70 es
Registration #10		11.777 es
Registration #11		19.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
S0567	
S0569	

Dimensions & weight

Width	1894 mm
Height	1392 mm
Length	5007 mm
Wheel base	2855 mm
Kerb weight	1750 kg
Max. allowed weight	2360 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	03229393

CarCheck.co.uk page 11/11