



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	LAND CRUISER D-4D INVINCIBLE
Colour	Black
Year of manufacture	2007
Top speed	109 mph
0 - 60 mph	11.2 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	171 BHP
Max. torque	410 Nm at 1.800 rpm
Engine capacity	2.982 cc
Cylinders	4
Fuel type	Diesel
Consumption city	24.4 mpg
Consumption extra urban	37.7 mpg
Consumption combined	31.4 mpg
CO2 emission	238 g/km
CO2 label	L





Internet history

Entry 1

Date	2022-03-22
Pictures	17
Listing price	<a href="#">View report</a>



source: yesauto.com





MOT history

MOT expiry date	2024-07-19
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	25
Total items failed	12

MOT #18	2023-07-20 17:13
MOT test number	885806359404
Result	✓ Passed
Next expiry date	2024-07-19
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #17	2022-05-19 13:09
MOT test number	416488042911
Result	✓ Passed

**MOT #16**

2022-05-13 07:33

**MOT test number**

171516119404

**Result****✗ Failed**

- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Minor** Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view stone chip (3.2 (a) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing also wearing on outer edge (5.2.3 (d) (ii))
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Offside Front Upper Brake pipe excessively corroded above brake flexi (have marked the pipe) (1.1.11 (c))

**MOT #15**

2021-07-15 13:36

**MOT test number**

537021118372

**Result****✓ Passed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge 265/65/17 (5.2.3 (e))

**MOT #14**

2020-07-02 09:12

**MOT test number**

416104569075

**Result****✓ Passed**

- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Front Brake pad(s) wearing thin Pad material crumbling away. (1.1.13 (a) (ii))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))



<b>MOT #13</b>	2019-07-12 10:41
<b>MOT test number</b>	686810689246
<b>Result</b>	✓ Passed
<b>Advice</b>	Under trays and engine covers fitted obscuring full view of inspection.

<b>MOT #12</b>	2019-07-04 10:04
<b>MOT test number</b>	351636176154
<b>Result</b>	✗ Failed
<b>Fail</b>	Offside Front Service brake excessively binding (1.2.1 (f))
<b>Fail</b>	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
<b>Advice</b>	Nearside Rear parking brake low
<b>Fail</b>	Nearside Front Position lamp not working (4.2.1 (a) (ii))
<b>Advice</b>	Under trays and engine covers fitted obscuring full view of inspection.
<b>Fail</b>	Nearside Rear Brake drum contaminated (1.1.14 (b))

<b>MOT #11</b>	2018-06-06 15:06
<b>MOT test number</b>	754169740557
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Rear Tyre worn close to legal limit/worn on edge on the limit (5.2.3 (e))
<b>Advice</b>	Under trays and engine covers fitted obscuring full view of inspection.

**MOT #10** 2018-06-06 13:16**MOT test number** 794008993791**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge on the limit (5.2.3 (e))**Advice** Under trays and engine covers fitted obscuring full view of inspection.**Fail** Nearside Parking brake inoperative on one side (1.4.1 (a))**Fail** Offside Front Service brake excessively binding (1.2.1 (f))**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #9** 2017-06-26 12:39**MOT test number** 918262720890**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Under trays and engine covers fitted obscuring full view of inspection.**MOT #8** 2016-06-28 13:23**MOT test number** 864089010419**Result** ✓ Passed**MOT #7** 2015-09-23 15:03**MOT test number** 857519839508**Result** ✓ Passed

**MOT #6** 2014-10-10 13:46**MOT test number** 345123084251**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #5** 2013-09-16 11:59**MOT test number** 485549953237**Result** ✓ Passed**MOT #4** 2012-09-13 12:22**MOT test number** 778597652271**Result** ✓ Passed**MOT #3** 2011-10-25 11:48**MOT test number** 968668591217**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #2** 2011-10-25 11:18**MOT test number** 506538991240**Result** ✗ Failed**Fail** Nearside Rear fog lamp insecure (1.3.2a)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #1** 2010-11-09 12:04**MOT test number** 422703510475**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 July 2024

✓  
**MOT**  
  
Expires:  
19 July 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	19 July 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-11-26
Last registration	2023-07-20
Complete history	<a href="#">See info</a>



Registration #1	2007-11-26	26 mi
Registration #2	2010-11-09	37.882 mi
Registration #3	2011-10-25	49.820 mi
Registration #4	2011-10-25	49.820 mi
Registration #5	2012-09-13	54.080 mi
Registration #6	2013-09-16	58.176 mi
Registration #7	2014-10-10	63.833 mi
Registration #8	2015-09-23	67.524 mi
Registration #9	2016-06-28	69.711 mi
Registration #10	2017-06-26	80.469 mi
Registration #11	2018-06-26	91.227 mi
Registration #12	2019-06-26	101.985 mi
Registration #13	2020-06-26	112.743 mi
Registration #14	2021-06-26	123.501 mi
Registration #15	2022-06-26	134.259 mi
Registration #16	2023-06-26	145.017 mi
Registration #17	2024-06-26	155.775 mi
Registration #18	2025-06-26	166.533 mi
Registration #19	2026-06-26	177.291 mi
Registration #20	2027-06-26	188.049 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1875 mm
Height	1905 mm
Length	4850 mm
Wheel base	2790 mm
Max. allowed weight	2850 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	8
Number of axles	2
Engine number	1KD1617275