



report date: 2024-03-29

General information

Make	KIA
Model	SORENTO CRDI KX-3 ISG
Colour	Grey
Year of manufacture	-
Top speed	127 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	197 BHP
Max. torque	441 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	39.8 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg





## Internet history

### Entry 3

Date	2021-06-26
Pictures	13
Listing price	<a href="#">View report</a>



source: [heycar.co.uk](#)

### Entry 2


Date	2021-06-13
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)

### Entry 1

Date	2021-06-08
Pictures	16
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



MOT history

MOT #8	2023-09-05 12:50
MOT test number	748607389323
Result	✓ Passed
Next expiry date	2024-09-04

MOT #7	2023-08-22 09:12
MOT test number	612246782367
Result	✗ Failed
DANGEROUS	Nearside Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
DANGEROUS	Nearside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
MAJOR	Central Rear Seat belt missing seat belt stork (7.1.2 (a))
DANGEROUS	Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
DANGEROUS	Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
DANGEROUS	Offside Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
MAJOR	Central Rear Seat belt missing (7.1.2 (a))
DANGEROUS	Offside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
DANGEROUS	Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
DANGEROUS	Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**MOT #6**

2023-06-30 13:08

**MOT test number**

454367531992

**Result**

✓ Passed

- Advice** Differances in tread depths may affect awd system
- Advice** Brake disc worn, but not excessively brake discs all round badly worn/lipped (1.1.14 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing in poor condition, cuts in tread but cords not evident atm (5.2.3 (d) (ii))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement debonding (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn too 1.9mm (DANGEROUS) (5.2.3 (e))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement debonding (5.3.4 (a) (i))

**MOT #5**

2023-06-30 12:18

**MOT test number**

454362185532

**Result**

✗ Failed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing in poor condition, cuts in tread but cords not evident atm (5.2.3 (d) (ii))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement debonding (5.3.4 (a) (i))
- DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm 235/60r18 (5.2.3 (e))
- Advice** Brake disc worn, but not excessively brake discs all round badly worn/lipped (1.1.14 (a) (i))
- DANGEROUS** Nearside Rear Tyre has ply or cords exposed cut exposing cords (5.2.3 (d) (ii))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement debonding (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn too 1.9mm (DANGEROUS) (5.2.3 (e))

**MOT #4**

2022-06-25 11:16

**MOT test number**

486214350931

**Result**

✓ Passed

**MOT #3** 2021-06-19 08:27**MOT test number** 795026738906**Result** ✓ Passed**MOT #2** 2021-01-21 16:18**MOT test number** 627583309409**Result** ✓ Passed

- Advice** Rear Tyre slightly damaged/cracking or perishing both side (5.2.3 (d) (ii))
- Advice** Both side rear tyres worn on inner side edges, close to expose cord
- Advice** Child Seat fitted not allowing full inspection of adult belt both side rear and centre
- Advice** Rear Tyre worn close to legal limit/worn on edge both side 3mm (5.2.3 (e))
- Advice** Rear Brake pad(s) wearing thin both side (1.1.13 (a) (ii))

**MOT #1** 2019-07-24 12:10**MOT test number** 556900928291**Result** ✓ Passed

- Advice** Rear Tyre slightly damaged/cracking or perishing both rear (5.2.3 (d) (ii))
- Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >





Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2016-07-29
Last registration	2023-09-05
Complete history	<a href="#">See info</a>



Registration #1	2016-07-29	15 mi
Registration #2	2019-07-24	33.649 mi
Registration #3	2021-01-21	51.555 mi
Registration #4	2023-09-05	56.606 mi
Registration #5		
Registration #6	2021-06-19	56.606 mi
Registration #7		
Registration #8		
Registration #9		
Registration #10		
Registration #11		
Registration #12		

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	83%
Pedestrian	67%
Safety systems	71%
Overall rating	80%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1890 mm
Height	1690 mm
Length	4800 mm
Wheel base	2780 mm
Kerb weight	1932 kg
Max. allowed weight	2590 kg

Additional information

Fuel tank capacity	71 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

<b>Number of axles</b>	2
<b>Engine number</b>	D4HBGH263767