



report date: 2024-03-28

General information

Make	VAUXHALL
Model	VECTRA VVT EXCLUSIV
Colour	Black
Year of manufacture	2008
Top speed	126 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	167 Nm at 3.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	39.2 mpg
CO2 emission	173 g/km
CO2 label	H





Internet history

Entry 2

Date	2021-10-31
Pictures	50
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-10-30
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-14
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	30
Total items failed	5

MOT #20	2023-11-02 14:42
MOT test number	424557993057
Result	✓ Passed
Next expiry date	2024-11-14
Advice	Nearside Front Play in steering rack inner joint(s)

MOT #19	2023-10-28 08:26
MOT test number	807253728921
Result	✗ Failed
Advice	Nearside Front Play in steering rack inner joint(s)
MAJOR	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #18	2022-10-24 09:59
MOT test number	715623882910
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin Both sides (1.1.13 (a) (ii))
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #17** 2021-10-30 11:51**MOT test number** 714246316112**Result** ✓ Passed**MOT #16** 2020-10-23 15:33**MOT test number** 167891655565**Result** ✓ Passed**MOT #15** 2020-10-21 09:02**MOT test number** 393235501630**Result** ✗ Failed**MAJOR** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**MAJOR** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**MAJOR** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**MOT #14** 2019-10-16 15:32**MOT test number** 877117666043**Result** ✓ Passed**Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

**MOT #13** 2019-10-16 10:09**MOT test number** 508517251743**Result** ✗ Failed**DANGEROUS** Offside Rear Tyre tread depth below requirements of 1.6mm 215/55/16/93w (5.2.3 (e))**MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**MAJOR** Rear Exhaust has a major leak of exhaust gases silencer has hole in top of silencer (6.1.2 (a))**Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**MOT #12** 2018-11-15 14:46**MOT test number** 993643365529**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge On 3mm, age cracking (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Rear Valve stem slightly damaged Slightly perished (5.2.3 (j))



MOT #11	2018-11-07 10:56
MOT test number	261907288058
Result	✗ Failed
MAJOR	Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
MAJOR	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Offside Rear Valve stem slightly damaged Slightly perished (5.2.3 (j))
MAJOR	Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
MAJOR	Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge On 3mm, age cracking (5.2.3 (e))
MAJOR	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #10	2017-10-25 15:41
MOT test number	979369744039
Result	✓ Passed

MOT #9	2017-10-25 10:22
MOT test number	291364679849
Result	✗ Failed
Fail	Offside Front Upper Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)
Fail	Nearside Front Upper Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

MOT #8	2016-10-25 08:30
MOT test number	179717665830
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #7** 2015-11-03 09:19**MOT test number** 148442312999**Result** ✓ Passed**MOT #6** 2014-11-03 09:29**MOT test number** 238067704326**Result** ✓ Passed**MOT #5** 2013-10-30 09:32**MOT test number** 307473103398**Result** ✓ Passed**MOT #4** 2013-10-30 09:32**MOT test number** 815503903338**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)**MOT #3** 2012-10-17 09:14**MOT test number** 215091292265**Result** ✓ Passed**MOT #2** 2012-10-16 09:40**MOT test number** 116550192219**Result** ✗ Failed**Fail** Nearside Rear coil spring incomplete (2.4.C.1a)**Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**MOT #1** 2011-10-12 11:39**MOT test number** 639275881247**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
14 November 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	14 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	YE58HRG
Plate since	2019-06-29
Current registration	YE58HRG
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-11-05
Last registration	2023-11-02
Complete history	See info



Registration #1	2008-11-05	29 mi
Registration #2	2011-10-12	29.737 mi
Registration #3	2012-10-16	39.911 mi
Registration #4	2012-10-17	39.911 mi
Registration #5	2013-10-30	49.900 mi
Registration #6	2014-11-03	59.376 mi
Registration #7	2015-11-03	67.715 mi
Registration #8	2016-10-25	75.987 mi
Registration #9	2017-10-25	82.867 mi
Registration #10	2017-10-25	82.867 mi
Registration #11	2018-11-07	86.578 mi
Registration #12	2019-10-25	90.289 mi
Registration #13	2020-10-25	94.000 mi
Registration #14	2021-10-25	97.711 mi
Registration #15	2022-10-25	101.422 mi
Registration #16	2023-10-25	105.133 mi
Registration #17	2023-10-25	105.133 mi
Registration #18	2023-10-25	105.133 mi
Registration #19	2023-10-25	105.133 mi
Registration #20	2023-10-25	105.133 mi
Registration #21	2023-10-25	105.133 mi
Registration #22	2023-10-25	105.133 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4596 mm
Wheel base	2700 mm
Kerb weight	1350 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	20KV4564