



report date: 2024-03-29

General information

Make	VOLVO
Model	V70 D5 S
Colour	Blue
Year of manufacture	2003
Top speed	130 mph
0 - 60 mph	9.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	163 BHP
Max. torque	340 Nm at 3.000 rpm
Engine capacity	2.401 cc
Cylinders	5
Fuel type	Diesel
Consumption city	32.5 mpg
Consumption extra urban	54.3 mpg
Consumption combined	43.5 mpg
CO2 emission	171 g/km
CO2 label	H





## MOT history

MOT expiry date	2021-03-22
MOT pass rate	63 %
MOT passed	15
Failed MOT tests	9
Total advice items	19
Total items failed	25

MOT #24	2020-03-05 12:33
MOT test number	847232906692
Result	✓ Passed
Next expiry date	2021-03-22
Advice	Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))

MOT #23	2020-03-03 12:22
MOT test number	703616088339
Result	✗ Failed
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Advice	Front axle tyres different size from rear axle tyres
Minor	Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #22**

2020-02-24 13:50

**MOT test number**

873649915451

**Result**

✗ Failed

- Fail** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Fail** Position lamp not working both front (4.2.1 (a) (ii))
- Fail** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Front Brake hose damaged and likely to fail (1.1.12 (a))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #21**

2019-02-25 13:33

**MOT test number**

506382355854

**Result**

✓ Passed

**MOT #20**

2018-03-12 16:12

**MOT test number**

653043929874

**Result**

✓ Passed

**MOT #19** 2018-03-07 14:39**MOT test number** 349644837417**Result** ✗ Failed**Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Rear Shock absorber has a serious fluid leak (2.7.3)**Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)**Fail** Front Shock absorber has a serious fluid leak (2.7.3)**MOT #18** 2017-03-01 18:23**MOT test number** 297890618846**Result** ✓ Passed**MOT #17** 2017-03-01 14:33**MOT test number** 289137888837**Result** ✗ Failed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Registration plate deteriorated but not likely to be misread (6.3.1d)**Fail** Rear parking brake recording little or no effort (3.7.B.6a)**MOT #16** 2016-03-07 14:34**MOT test number** 477182074765**Result** ✓ Passed**MOT #15** 2015-03-09 16:12**MOT test number** 356558265078**Result** ✓ Passed

**MOT #14** 2015-03-09 16:12**MOT test number** 298668965045**Result** ✗ Failed**Pass with rectification** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)**MOT #13** 2014-03-21 11:29**MOT test number** 237510984096**Result** ✓ Passed**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #12** 2014-03-11 10:35**MOT test number** 187340074064**Result** ✗ Failed**Fail** Nearside Front Brake hose excessively deteriorated (3.6.B.4d)**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Offside Front Brake hose slightly deteriorated (3.6.B.4d)**MOT #11** 2013-03-20 15:27**MOT test number** 199069673420**Result** ✓ Passed**Notice** Osf inner rack end

**MOT #10** 2013-03-19 17:29**MOT test number** 169398173412**Result** ✗ Failed**Fail** Offside Rear Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Notice** Osf inner rack end**Fail** Nearside Front Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)**MOT #9** 2012-03-07 18:15**MOT test number** 376967662011**Result** ✓ Passed**MOT #8** 2012-03-06 14:31**MOT test number** 108676462086**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Inner Front Drag link end ball joint has excessive play (2.2.B.1f)**MOT #7** 2011-03-10 13:36**MOT test number** 809549661086**Result** ✓ Passed

**MOT #6** 2011-03-09 10:17**MOT test number** 566028661091**Result** ✗ Failed**Fail** Exhaust system not adequately supported (7.1.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #5** 2010-03-01 13:42**MOT test number** 140960860091**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2009-03-18 13:18**MOT test number** 263147079072**Result** ✓ Passed**Advice** Offside Rear brake disc slightly scored (3.5.1h)**MOT #3** 2008-03-18 13:41**MOT test number** 101558178439**Result** ✓ Passed**MOT #2** 2007-03-23 10:03**MOT test number** 570702987043**Result** ✓ Passed



MOT #12006-03-23 12:07

MOT test number693552086017

Result

✓ Passed

Advice

Nearside Rear rear brake juddering slightly (3.7.A.5b)

Notice

Nail in tyre

Notice

Slight play at front wishbone front bushes.

Notice

Slight play at offside front wheel.





Tax & MOT check

✕  
Untaxed

Tax expired:  
3 December 2020

✕  
MOT

Expired:  
22 March 2021

Tax status	Expired at 3 December 2020
Days left	1243 days too late
MOT expiry date	22 March 2021
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2003-03-07
Last registration	2020-03-05
Complete history	<a href="#">See info</a>



Registration #1	2003-03-07	25 mi
Registration #2	2006-03-23	28.077 mi
Registration #3	2007-03-23	37.834 mi
Registration #4	2008-03-18	49.304 mi
Registration #5	2009-03-18	62.131 mi
Registration #6	2010-03-01	73.954 mi
Registration #7	2011-03-09	87.630 mi
Registration #8	2011-03-10	87.632 mi
Registration #9	2012-03-06	97.567 mi
Registration #10	2012-03-07	97.567 mi
Registration #11	2013-03-19	109.775 mi
Registration #12	2013-03-20	109.777 mi
Registration #13	2013-03-20	109.777 mi
Registration #14	2013-03-20	109.777 mi
Registration #15	2013-03-20	109.777 mi
Registration #16	2013-03-20	109.777 mi
Registration #17	2013-03-20	109.777 mi
Registration #18	2013-03-20	109.777 mi
Registration #19	2013-03-20	109.777 mi
Registration #20	2013-03-20	109.777 mi
Registration #21	2013-03-20	109.777 mi
Registration #22	2013-03-20	109.777 mi
Registration #23	2013-03-20	109.777 mi
Registration #24	2013-03-20	109.777 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1804 mm
Height	1428 mm
Length	4576 mm
Wheel base	2715 mm
Max. allowed weight	2030 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of axles	2
Engine number	136847