





report date: 2024-03-29

### General information

Make	FIAT
Model	PUNTO TWINAIR
Colour	Black
Year of manufacture	-
Top speed	107 mph
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	85 BHP
Max. torque	145 Nm at 2.000 rpm
Cylinders	2
Fuel type	Petrol
Consumption city	57.7 mpg
Consumption extra urban	74.3 mpg
Consumption combined	67.3 mpg



CarCheck.co.uk page 1/11



## Internet history

Entry	1

Date	2021-09-02
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT #10	2023-02-18 12:43
MOT test number	365594949053
Result	✓ Passed
Next expiry date	2024-02-17
Advice Offside Rear Shock absorbers has slight external damage to the casing	(5.3.2 (b))
Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice Nearside Rear Shock absorbers has slight external damage to the casin	g (5.3.2 (b))
Minor Nearside Front Anti-roll bar linkage ball joint dust cover severely deterior	rated (5.3.4 (b) (i))
Advice Nearside Front Direction indicator slightly discoloured (4.4.3 (a))	
Advice Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))	

MOT #9		2022-02-09 11:14
MOT test	number	893678576223
Result		✓ Passed
Advice	Front Service brake fluctuating, but not excessively (1.2.1 (e))	
Advice	Rear suspension sub frame/suspension components surface corroded	
Advice	Front suspension sub frame/suspension components surface corroded	
Advice	Offside rear tyre tread depth starting to wear low	

MOT #8	2021-01-28 13:28
MOT test number	930229453784
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/11



NU13RLZ

report date: 2024-03-29

MOT test number

Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**MOT** #6 2020-01-23 13:04 **MOT** test number 914667218365 Result ✓ Passed **MOT** #5 2019-02-09 14:41 **MOT** test number 450752160752 Result Passed **Advice** Engine has a slight oil leak Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b)) **Advice Advice** N/s/f brake pad sensor wire broken

MOT #4 2019-02-09 09:21 **MOT** test number 278334123793 Result × Failed Fail Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii)) Advice Engine has a slight oil leak Advice N/s/f brake pad sensor wire broken Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b)) Advice **Advice** N/s/f day time running light not working

CarCheck.co.uk page 4/11



MOT #3 2017-11-04 11:46

**MOT test number** 889713950967

**Result** ✓ Passed

Advice PLASTIC UNDER TRAYS FITTED

Advice Nearside Rear Rear position lamp(s) has light sources not illuminating, but not more than 50%

(1.1.A.3b)

MOT #2 2016-11-25 10:56

**MOT test number** 714637883661

**Result** 
✓ Passed

**Advice** Front Number plate has crack in it. Can still read characters

**MOT #1** 2016-11-25 10:09

MOT test number 181867258172

Result X Failed

**Advice** Front Number plate has crack in it. Can still read characters

**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Fail Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

CarCheck.co.uk page 5/11



#### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



## Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report is	
manage of the same	
***************************************	
***************************************	
*********	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Account moduloution	SUE.
Correct registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-06-29
Last registration	2023-02-18
Complete history	See info



2013-06-29	27 mi
2016-11-25	32.076 mi
2016-11-25	32.076 mi
2017-11-04	42.722 mi
2019-02-09	66.478 mi
2019-02-09	66.478 mi
	91.777 es
	11.777 es
	2016-11-25 2016-11-25 2017-11-04 2019-02-09

More info >

CarCheck.co.uk page 10/11



## Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1075 kg
Max. allowed weight	1635 kg

## Additional information

Fuel tank capacity	45 I	
Fuel delivery	Multi-Point Injection	
Number of doors	3	
Number of seats CarCheck.co.uk	5	page 11/11

Number of axles2Engine number0075847