



EK07UGD

report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	CADDY C20 SWB VAN 104TDI
Colour	White
Year of manufacture	2007
Top speed	103 mph
0 - 60 mph	13.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	103 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel





MOT history

MOT expiry date	2024-04-27
MOT pass rate	64 %
MOT passed	14
Failed MOT tests	8
Total advice items	48
Total items failed	21

MOT #22	2024-04-27 12:12
MOT test number	137327667244
Result	✓ Passed
Next expiry date	2025-04-27
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #21	2023-04-28 14:25
MOT test number	258268301443
Result	✓ Passed
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear wishbone arm bush (5.3.4 (a) (i))
Advice	Nearside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear wishbone arm bush (5.3.4 (a) (i))

**MOT #20**

2023-04-28 13:04

**MOT test number**

118068187608

**Result**

✗ Failed

**Pass with rectification** Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))**Fail** Central Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement  
Rear wishbone arm bush (5.3.4 (a) (i))**Advice** Central Front Oil leak, but not excessive (8.4.1 (a) (i))**Pass with rectification** Offside Front Headlamp aim too low (4.1.2 (a))**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the  
ingress of dirt (6.1.7 (g) (ii))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement  
Rear wishbone arm bush (5.3.4 (a) (i))**Advice** Nearside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))**Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))**MOT #19**

2022-02-03 11:42

**MOT test number**

963298243145

**Result**

✓ Passed

**MOT #18**

2021-02-06 16:05

**MOT test number**

877722605950

**Result**

✓ Passed

**Advice** Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #17** 2021-02-06 16:05**MOT test number** 609604930304**Result** ✗ Failed

- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))

**MOT #16** 2019-10-02 11:58**MOT test number** 370343107307**Result** ✓ Passed**MOT #15** 2019-09-30 11:50**MOT test number** 895315258312**Result** ✗ Failed

- Fail** Offside Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))

**MOT #14** 2018-07-24 15:03**MOT test number** 713866213698**Result** ✓ Passed

- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Minor** Suspension arm ball joint dust cover severely deteriorated both sides (5.3.4 (b) (i))
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))

**MOT #13**

2018-07-23 08:30

**MOT test number**

880358373935

**Result**

✗ Failed

**Advice**

Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**Advice**

Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**Fail**

Offside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Advice**

Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))

**Fail**

Exhaust emissions test aborted because smoke levels are significantly in excess of the specified limit values (8.2.2.2 (f))

**Fail**

Nearside Headlamp aim too far to the right (4.1.2 (a))

**Minor**

Suspension arm ball joint dust cover severely deteriorated both sides (5.3.4 (b) (i))

**Fail**

Offside Front Inner Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**Fail**

Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt both sides x2 (5.3.4 (b) (ii))

**Fail**

Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**MOT #12**

2017-07-24 12:42

**MOT test number**

616606239380

**Result**

✓ Passed

**Advice**

Both rear tyre slightly low pressures

**Advice**

Engine mounting deteriorated, but not resulting in excessive movement o/s/f and n/s/f ,engine has play,may require to attention (6.1.D.1a)

**Advice**

Oil leak

**Advice**

Exhaust has slightly black smoke,may require to attention

**Advice**

Front brake disc worn, pitted or scored, but not seriously weakened both sides have slightly lipped (3.5.1i)

**MOT #11**

2017-07-22 13:37

**MOT test number**

775651191044

**Result****✗ Failed****Advice** Both rear tyre slightly low pressures**Fail** Nearside Rear rear brake binding (3.7.B.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened both sides have slightly lipped (3.5.1i)**Advice** Exhaust has slightly black smoke,may require to attention**Advice** Engine mounting deteriorated, but not resulting in excessive movement o/s/f and n/s/f ,engine has play,may require to attention (6.1.D.1a)**Advice** Oil leak**MOT #10**

2016-07-23 12:19

**MOT test number**

629155415693

**Result****✓ Passed****Advice** Offside n/s/f tyre inner edge slight worn,outer road wheel has slight dent**Advice** Nearside o/s/f tyre inner edge wearing worn,may require to attention**MOT #9**

2016-07-18 08:16

**MOT test number**

529109484158

**Result****✗ Failed****Advice** Offside n/s/f tyre inner edge slight worn,outer road wheel has slight dent**Fail** Offside Front Anti-roll bar has excessive play in a pin/bush d bush (2.4.G.2)**Advice** Nearside o/s/f tyre inner edge wearing worn,may require to attention**Fail** Nearside Rear Anti-roll bar has excessive play in a pin/bush d bush (2.4.G.2)

**MOT #8** 2015-07-17 08:54**MOT test number** 797188295189**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #7** 2015-07-07 14:03**MOT test number** 945968585184**Result** ✗ Failed**Fail** Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Headlamp insecure (1.7.3)**Fail** Nearside Headlamp aim too low (1.8)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Headlamp aim too low (1.8)**MOT #6** 2014-06-19 10:04**MOT test number** 875320174195**Result** ✓ Passed**Advice** Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2013-06-25 12:32**MOT test number** 278496473417**Result** ✓ Passed

**MOT #4** 2011-07-14 08:28**MOT test number** 658045291101**Result** ✓ Passed**Notice** O/side door mirror cracked**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2011-07-14 08:28**MOT test number** 646935991105**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** O/side door mirror cracked**Pass with rectification** Registration plate lamp not working (1.1.C.1d)**MOT #2** 2010-03-02 10:42**MOT test number** 994231060006**Result** ✓ Passed**MOT #1** 2007-04-03 16:43**MOT test number** 650313497051**Result** ✓ Passed





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
27 April 2024

<b>Tax status</b>	Valid until 1 April
-------------------	---------------------

<b>Days left</b>	338
------------------	-----

<b>MOT expiry date</b>	27 April 2024
------------------------	---------------

<b>Full MOT history</b>	<a href="#">See MOT history</a>
-------------------------	---------------------------------



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>EK07UGD</b>
Plate since	2019-06-29
Current registration	 <b>EK07UGD</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-03-31
Last registration	2024-04-27
Complete history	<a href="#">See info</a>



Registration #1	2007-03-31	11 mi
Registration #2	2007-04-03	73 mi
Registration #3	2010-03-02	66.632 mi
Registration #4	2011-07-14	83.258 mi
Registration #5	2013-06-25	100.072 mi
Registration #6	2014-06-19	109.362 mi
Registration #7	2015-07-07	120.156 mi
Registration #8	2015-07-17	120.779 mi
Registration #9	2016-07-18	140.898 mi
Registration #10	2016-07-23	141.076 mi
Registration #11	2017-07-22	159.991 mi
Registration #12	2018-06-20	161.277 mi
Registration #13	2019-06-20	161.277 mi
Registration #14	2020-06-20	161.277 mi
Registration #15	2021-06-20	161.277 mi
Registration #16	2022-06-20	161.277 mi
Registration #17	2023-06-20	161.277 mi
Registration #18	2024-06-20	161.277 mi
Registration #19	2025-06-20	161.277 mi
Registration #20	2026-06-20	161.277 mi
Registration #21	2027-06-20	161.277 mi
Registration #22	2028-06-20	161.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	2062 mm
Length	4405 mm

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Engine number	BLS 258417