





report date: 2024-03-28

#### General information

Make	BMW
Model	120 120D SE
Colour	Silver
Year of manufacture	2007
Top speed	140 mph
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	174 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	1.995 сс
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	62.8 mpg
Consumption combined	51.4 mpg
CO2 emission	145 g/km
CO2 label	F



CarCheck.co.uk page 1/15



## Internet history

#### Entry 1

Date 2021-06-09


Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/15



MOT history

MOT expiry date	2022-05-05
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	45
Total items failed	9

MOT #19		2021-05-06 16:34
MOT test	number	346604757026
Result		✓ Passed
Next expi	ry date	2022-05-05
Advice	Front Brake hose slightly deteriorated BOTH SIDES (1.1.12 (b) (ii))	
Advice	Offside Front Inner Tyre slightly damaged (5.2.3 (d) (ii))	
Advice	Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	

MOT #18	2021-05-04 15:21
MOT test number	439139576162
Result	<b>×</b> Failed
Advice Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice Front Brake hose slightly deteriorated BOTH SIDES (1.1.12 (b) (ii))	
Fail Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))	
Advice Offside Front Inner Tyre slightly damaged (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/15



**MOT #17** 2020-08-04 09:17

**MOT test number** 962124266934

**Result** ✓ Passed

**Advice** Front Brake hose slightly deteriorated both perishing (1.1.12 (b) (ii))

**Advice** Oil level on minimum and small chips in screen

**Advice** Rear Brake pipe corroded, covered in grease or other material both corroding (1.1.11 (c))

**MOT #16** 2019-08-06 14:19

MOT test number 120782223681

**Result** 
✓ Passed

**Advice** Front Brake hose slightly deteriorated both are perishing (1.1.12 (b) (ii))

**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #15** 2019-08-06 09:20

MOT test number 467438426950

**Result** ★ Failed

**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Front Brake hose slightly deteriorated both are perishing (1.1.12 (b) (ii))

**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Minor Offside Rear Tyre obviously under inflated also has a nail in tyre (5.2.3 (I))

**Advice** No coolant in bottle and warning light on dash

CarCheck.co.uk page 4/15



**MOT #14** 2018-08-03 14:08

**MOT test number** 564340176176

**Result** ✓ Passed

Advice Rear Brake pad(s) wearing thin both pads low needs inspection as cannot determine inner ones clearly (1.1.13 (a) (ii))

Minor Front Brake hose slightly damaged both perishing (1.1.12 (b) (i))

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both worn with lip at top of discs (1.1.14 (a) (ii))

Advice Oil level on minimum strong advise

**Advice** Offside Front Tyre worn close to legal limit/worn on edge wearing on inside edge (5.2.3 (e))

**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources reg bulb not working (4.7.1 (b) (i))

**Advice** Front Inner Brake pad(s) wearing thin very low but as disc is lipped cant be 100% sure strong advise to have an inspection done to find out (1.1.13 (a) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge wearing slightly on edges (5.2.3 (e))

**Advice** Nearside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i))

Minor Windscreen damaged but not adversely affecting driver's view small chip in windscreen (3.2 (a) (i))

CarCheck.co.uk page 5/15



MOT #13 2018-08-03 13:20

MOT test number 202430781810

**Result** X Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge wearing slightly on edges (5.2.3 (e))

Advice Rear Brake pad(s) wearing thin both pads low needs inspection as cannot determine inner ones clearly (1.1.13 (a) (ii))

Minor Windscreen damaged but not adversely affecting driver's view small chip in windscreen (3.2 (a) (i))

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both worn with lip at top of discs (1.1.14 (a) (ii))

**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords cut exposing cords (5.2.3 (d) (i))

Minor Front Brake hose slightly damaged both perishing (1.1.12 (b) (i))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge wearing on inside edge (5.2.3 (e))

**Advice** Oil level on minimum strong advise

**Advice** Front Inner Brake pad(s) wearing thin very low but as disc is lipped cant be 100% sure strong advise to have an inspection done to find out (1.1.13 (a) (ii))

**Advice** Nearside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i))

**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources reg bulb not working (4.7.1 (b) (i))

**MOT #12** 2017-08-02 12:03

**MOT test number** 265158547429

Result / Passed

**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)

**Advice** Offside front brake fluctuating, but not excessively (3.7.B.3)

Advice Front brake disc worn, pitted or scored, but not seriously weakened ns/os (3.5.1i)

**Advice** Nearside Rear Road wheel with a slightly distorted bead rim inner rim (4.2.A.1a)

CarCheck.co.uk page 6/15



**MOT #11** 2017-08-01 14:38

**MOT test number** 785724616565

Result × Failed

Advice Front brake disc worn, pitted or scored, but not seriously weakened ns/os (3.5.1i)

**Advice** Nearside Rear Road wheel with a slightly distorted bead rim inner rim (4.2.A.1a)

**Advice** Offside front brake fluctuating, but not excessively (3.7.B.3)

Fail Offside Front Windscreen wiper does not clear the windscreen effectively WBFM0020 (8.2.2)

**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)

**Fail** Nearside Rear Tyre has ply or cords exposed \*\*\*inner edge\*\*\*205/50R17-89V-RSC\*\*\* (4.1.D.1b)

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively WBFM0020 (8.2.2)

**MOT #10** 2016-08-04 07:11

**MOT test number** 494198232932

**Result** ✓ Passed

MOT #9 2016-08-02 07:52

**MOT test number** 300520121673

**Result** X Failed

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #8 2015-07-29 16:33

**MOT test number** 519910315277

**Result** ✓ Passed

CarCheck.co.uk page 7/15



MOT #7 2015-07-29 08:48

**MOT test number** 315850815282

Result × Failed

**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

MOT #6 2014-07-28 09:51

**MOT test number** 318449904244

MOT #5 2013-06-07 11:08

**MOT test number** 807498653187

**Result** ✓ Passed

MOT #4 2012-06-11 12:31

MOT test number 847923962123

**Result** ✓ Passed

MOT #3 2011-07-12 13:03

MOT test number 776003091191

Result \rightarrow Passed

MOT #2 2010-06-30 16:02

**MOT test number** 551811480126

**Result** ✓ Passed

MOT #1 2010-05-10 16:44

**MOT test number** 912030630176

CarCheck.co.uk page 8/15



#### Tax & MOT check



**Х** мот

Expired: 5 May 2022

Tax status

Days left

MOT expiry date

Full MOT history

Expired at 1 December 2021

881 days too late

5 May 2022

See MOT history

#### Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 9/15



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <a href="here">here</a> for the results.

# Damage 1 Date

Category

**Type** 

Damage 2

**Date** 

Category

**Type** 



#### Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



#### Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 11/15



Owner history

Owner history		
For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report I		ve?
**************************************		
***************************************		
THE PROPERTY OF THE PROPERTY O		
********		
***************************************		
	More info	>
Plate changes		
See in this check if this BMW had different number plates.		
Number of plates		9
Current registration	UK NE	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 12/15



#### Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 13/15



## Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-05-21
Last registration	2021-05-06
Complete history	See info



Registration #1	2007-05-21	18 mi
Registration #2	2010-05-10	43.342 mi
Registration #3	2010-06-30	43.870 mi
Registration #4	2011-07-12	52.589 mi
Registration #5	2012-06-11	60.038 mi
Registration #6	2013-06-07	68.830 mi
Registration #7	2014-07-28	77.439 mi
Registration #8	2015-07-29	86.366 mi
Registration #9	2015-07-29	86.386 mi
Registration #10	2016-08-02	96.748 mi
Registration #11	2016-08-04	96.795 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 mi

More info >

CarCheck.co.uk page 14/15



## Car features

50225	Air conditioning
50295	
60482	
60501	
60566	
60567	
50569	

## Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	1748 mm
Height	1421 mm
Length	4239 mm
Wheel base	2660 mm
Kerb weight	1375 kg
Max. allowed weight	1880 kg

## Additional information

Fuel tank capacity	51	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 15/15

Number of axles 2

Engine number 93406534