



Mercedes-Benz




report date: 2024-03-29

General information

Make	MERCEDES
Model	C C180K SE
Colour	Silver
Year of manufacture	2007
Top speed	137 mph
0 - 60 mph	9.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption



Power	141 BHP
Max. torque	220 Nm at 2.500 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	23.7 mpg
Consumption extra urban	45.6 mpg
Consumption combined	33.6 mpg
CO2 emission	200 g/km
CO2 label	J





Internet history

Entry 1	
Date	2021-05-28
Pictures	27
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-05-26
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	21
Total items failed	13

MOT #20	2023-05-02 08:59
MOT test number	729761438933
Result	✓ Passed
Next expiry date	2024-05-26

MOT #19	2023-04-24 10:30
MOT test number	936342581803
Result	✗ Failed
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

MOT #18	2022-05-04 11:14
MOT test number	683005127736
Result	✓ Passed

**MOT #17** 2022-05-04 08:35**MOT test number** 519706706247**Result** ✗ Failed**Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #16** 2021-05-27 14:43**MOT test number** 201002405897**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing cracking in tread (5.2.3 (d) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #15** 2021-05-27 12:30**MOT test number** 568427675897**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Windscreen wiper not working (3.4 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

**MOT #14** 2020-07-27 14:02**MOT test number** 448339944505**Result** ✓ Passed**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge shoulder worn - 225/45/17 (5.2.3 (e))**Advice** Front Registration plate deteriorated but not likely to be misread damaged (0.1 (b))**Advice** Nearside Rear Nail in tyre 2 x punctures**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge close to legal limit - 245/40/17 (5.2.3 (e))**MOT #13** 2019-07-22 12:57**MOT test number** 783915377398**Result** ✓ Passed**MOT #12** 2018-07-25 07:49**MOT test number** 228151176164**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge ON LIMIT 245/40/17 (5.2.3 (e))**MOT #11** 2018-07-25 07:49**MOT test number** 208734155128**Result** ✗ Failed**Pass with rectification** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge ON LIMIT 245/40/17 (5.2.3 (e))**MOT #10** 2017-07-28 12:39**MOT test number** 493226132967**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #9** 2016-07-19 15:48**MOT test number** 166412424776**Result** ✓ Passed**Advice** Nearside Front tyre cracking on tread**MOT #8** 2015-07-16 09:42**MOT test number** 105267695160**Result** ✓ Passed**MOT #7** 2014-07-19 12:46**MOT test number** 239700604214**Result** ✓ Passed**MOT #6** 2014-07-19 12:00**MOT test number** 386510204256**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2013-07-29 13:04**MOT test number** 959290513274**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Nearside rear body works damaged

**MOT #4** 2013-07-29 13:04**MOT test number** 325130313209**Result** ✗ Failed

Pass with rectification Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Notice Nearside rear body works damaged

Pass with rectification Nearside Headlamp aim aimed so that it dazzles other road users (1.8.A.1a)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #3 2012-07-16 13:10**MOT test number** 989778992190**Result** ✓ Passed**MOT #2** 2011-07-14 08:47**MOT test number** 325125891130**Result** ✓ Passed**MOT #1** 2010-05-20 13:04**MOT test number** 261670640440**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
26 May 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	26 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history


Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-03-05
Last registration	2023-05-02
Complete history	See info



Registration #1	2007-03-05	16 mi
Registration #2	2010-05-20	52.101 mi
Registration #3	2011-07-14	53.920 mi
Registration #4	2012-07-16	54.281 mi
Registration #5	2013-07-29	55.467 mi
Registration #6	2014-07-19	56.834 mi
Registration #7	2014-07-19	56.843 mi
Registration #8	2015-07-16	60.031 mi
Registration #9	2016-07-19	65.948 mi
Registration #10	2017-07-28	74.454 mi
Registration #11	2018-07-25	82.739 mi
Registration #12	2019-05-20	85.000 mi
Registration #13	2019-05-20	85.000 mi
Registration #14	2019-05-20	85.000 mi
Registration #15	2019-05-20	85.000 mi
Registration #16	2019-05-20	85.000 mi
Registration #17	2019-05-20	85.000 mi
Registration #18	2019-05-20	85.000 mi
Registration #19	2019-05-20	85.000 mi
Registration #20	2019-05-20	85.000 mi
Registration #21	2019-05-20	85.000 mi

More info >



Dimensions & weight

Width	1957 mm
Height	1406 mm
Length	4343 mm
Wheel base	2715 mm
Kerb weight	1465 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	27194630876940