



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES-BENZ
Model	V V 250 D AMG LINE XL
Colour	Black
Year of manufacture	2017
Top speed	129 mph
0 - 60 mph	9.1 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	188 BHP
Max. torque	440 Nm at 2.400 rpm
Engine capacity	2.143 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	44.8 mpg
CO2 emission	166 g/km
CO2 label	H






## Internet history

### Entry 3


Date	2021-12-16
Pictures	32
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

### Entry 2


Date	2021-10-15
Pictures	32
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

### Entry 1

Date	2021-08-02
Pictures	20
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2025-02-05
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	6
Total items failed	9

MOT #7	2024-01-10 16:00
MOT test number	645775376970
Result	✓ Passed
Next expiry date	2025-02-05
Minor	Offside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))

MOT #6	2024-01-09 12:31
MOT test number	337927221561
Result	✗ Failed
Fail	Offside Front Tyre has ply or cords exposed Inner shoulder worn through ply. (5.2.3 (d) (ii))
Fail	Nearside Front Tyre has ply or cords exposed Inner shoulder worn through ply. (5.2.3 (d) (ii))
Minor	Offside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))

MOT #5	2023-02-06 14:32
MOT test number	407485188584
Result	✓ Passed
Advice	Driver's view Items removed from driver's view prior to test pendant removed from rear view mirror (3.1 (a) (ii))

**MOT #4**

2023-01-23 15:45

**MOT test number**

545569779939

**Result****✗ Failed****Fail** Electronic parking brake control defective so that it cannot be satisfactorily operated (1.1.6 (d))**Advice** Driver's view Items removed from driver's view prior to test pendant removed from rear view mirror (3.1 (a) (ii))**Fail** Nearside Rear Tyre not fitted in accordance with side wall instructions (5.2.3 (i))**Fail** Nearside Front Shock absorbers damaged to the extent that it does not function lower spring mounting cup severely distorted due to broken spring (5.3.2 (b))**Fail** Electronic parking brake warning indicates a malfunction (1.1.6 (e))**Fail** Driver's view of the road through the swept area of the windscreen significantly affected by an obstruction unable to remove phone cradle from center of windscreen prior to test (3.1 (a) (ii))**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #3**

2022-02-23 12:25

**MOT test number**

653431279268

**Result****✓ Passed****Advice** Offside Front Tyre worn close to legal limit/worn on edge 2.6mm and worn on edge (5.2.3 (e))**Advice** Rear Anti-roll bar pin or bush worn but not resulting in excessive movement d bushes slight play (5.3.4 (a) (i))**MOT #2**

2021-02-22 14:13

**MOT test number**

499793900123

**Result****✓ Passed****MOT #1**

2020-03-02 10:23

**MOT test number**

143784479250

**Result****✓ Passed**



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
5 February 2025

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	248
<b>MOT expiry date</b>	5 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

Number of plates	1
Current registration	 <b>YT170XK</b>
Plate since	2019-06-29
Current registration	 <b>YT170XK</b>
Plate since	2019-06-29

More info >





Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2017-03-15
Last registration	2024-01-10
Complete history	<a href="#">See info</a>



Registration #1	2017-03-15	18 mi
Registration #2	2020-03-02	61.033 mi
Registration #3	2021-02-22	78.545 mi
Registration #4	2022-03-02	79.277 mi
Registration #5	2023-03-02	80.009 mi
Registration #6	2024-01-10	80.741 mi
Registration #7	2024-01-10	81.473 mi
Registration #8	2024-01-10	82.205 mi
Registration #9	2024-01-10	82.937 mi
Registration #10	2024-01-10	83.669 mi
Registration #11	2024-01-10	84.401 mi

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1928 mm
Height	1928 mm
Length	5370 mm
Wheel base	3430 mm
Kerb weight	2255 kg
Max. allowed weight	3100 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	8
Number of axles	2
Engine number	65195034470226