

Ford



### General information

Make	FORD
Model	KA ZETEC
Colour	White
Year of manufacture	2009
Top speed	99 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	68 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.8 mpg
Consumption extra urban	64.2 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	С





# MOT history

MOT expiry date	2020-11-19
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	12
Total items failed	5

MOT #12	2019-10-23 12:40
MOT test number	874411456734
Result	✓ Passed
Next expiry date	2020-11-19
<b>Advice</b> Nearside Front Upper Macpherson strut mounting corroded but not seriously work nut and flange washer (5.3.3 (b) (i))	veakened mounting
Advice Offside Rear bump stop insecure	
Advice Offside Front Upper Macpherson strut mounting corroded but not seriously weakened mounting nut and flange washer (5.3.3 (b) (i))	
Advice Nearside Rear bump stop insecure	

MOT #11	2019-10-23 10:11
MOT test number	485930549478
Result	🗙 Failed
Advice Offside Rear bump stop insecure	
Advice Nearside Front Upper Macpherson strut mounting corroded but not seriously w nut and flange washer (5.3.3 (b) (i))	reakened mounting
Fail Offside Rear Hydraulic brake calliper leaking Brake nipple leaking (1.1.16 (b) (i))	
Advice Nearside Rear bump stop insecure	
Fail Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))	
<b>Advice</b> Offside Front Upper Macpherson strut mounting corroded but not seriously wearnut and flange washer (5.3.3 (b) (i))	akened mounting





MOT #10	2018-11-08 10:26
MOT test number	112362083457
Result	Passed
<b>Minor</b> Offside Front Windscreen damaged but not adversely affecting driver's view wind small crack [at time of testing ] (3.2 (a) (i))	d screen has a
MOT #9	2018-11-07 14:52
MOT test number	409430681775
Result	🗙 Failed
Minor Offside Front Windscreen damaged but not adversely affecting driver's view wind small crack [at time of testing ] (3.2 (a) (i))	d screen has a
Fail Rear Exhaust silencer insecure exhaust silencer fouling rear shock absorber (8.1.1	(b) (i))
Fail Front Brake pad(s) less than 1.5 mm thick both n/s o/s (1.1.13 (a) (ii))	

МОТ #8	2017-11-20 14:28
MOT test number	833298538100
Result	✓ Passed

МОТ #7	2017-04-28 14:00
MOT test number	178893394370
Result	✓ Passed

МОТ #6		2017-04-28 14:00
MOT test number		700110484245
Result		🗙 Failed
Pass with rectification	Nearside Headlamp aim too high and too far to the right. (1.8)	

MOT #5	2016-04-27 08:18
MOT test number	479937060119
Result	✓ Passed
Advice Rear exhaust corroded	





MOT #4	2015-05-01 10:45
MOT test number	845521125171
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (3.5.1g)	
MOT #3	2014-05-01 09:52
MOT test number	617521924159
Result	✓ Passed
MOT #2	2013-03-26 10:49
MOT test number	368865183042
Result	✓ Passed
MOT #1	2012-03-23 09:59
MOT test number	286033082060
Result	✓ Passed



YR09HVY report date: 2024-03-28

Tax & MOT check

X Untaxed	Х МОТ
<b>Tax expired:</b> 29 September 2020	<b>Expired:</b> 19 November 2020
Tax status	Expired at 29 September
Days left	1308 days too late
MOT expiry date	19 November 2020
Full MOT history	See MOT history
Tax calculation	
Vehicle class	48

	40
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date		
Category		ARMP
Туре		
Damage 2		AMPLE
	E E	AT I
Date		*
Category	AMA	
Туре	No. Contraction of the second s	

#### Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





### Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
************	
*******	
******	
***********	
********	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2009-03-21
Last registration	2019-10-23
Complete history	<u>See info</u>



Registration #1	2009-03-21	12 mi
Registration #2	2012-03-23	25.552 mi
Registration #3	2013-03-26	33.936 mi
Registration #4	2014-05-01	40.035 mi
Registration #5	2015-05-01	45.836 mi
Registration #6	2016-04-27	55.045 mi
Registration #7	2017-04-28	68.227 mi
Registration #8		11.777 esi
Registration #9		10.300 est
Registration #10		11.777 est
Registration #10 Registration #11		11.577 es
-		01.000 est 01.000 est 01.000 est





### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

**NCAP** rating

Video

\*\*\*\* see crash video



Dimensions & weight	
Width	1702 mm
Height	1505 mm
Length	3620 mm
Wheel base	2300 mm
Kerb weight	940 kg
Max. allowed weight	1320 kg
Additional information	
Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 11/11

Number of axles	2
Engine number	5187434