



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	POLO SEL TSI
Colour	Grey
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	9.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	175 Nm at 1.500 rpm
Engine capacity	1.198 cc
Cylinders	4
Fuel type	Petrol
Consumption city	41.5 mpg
Consumption extra urban	62.8 mpg
Consumption combined	53.3 mpg
CO2 emission	124 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-06-05
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-10
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	21
Total items failed	11

MOT #18	2023-07-06 11:57
MOT test number	254732560327
Result	✓ Passed
Next expiry date	2024-07-10
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #17	2023-06-27 08:18
MOT test number	589874807530
Result	✗ Failed
Fail	Nearside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Fail	Offside Headlamp levelling device inoperative (4.1.5 (a))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #16	2022-07-11 11:29
MOT test number	353341954575
Result	✓ Passed
Minor	Offside Windscreen wiper blade defective (3.4 (b) (i))

**MOT #15**

2022-06-29 08:17

MOT test number

875165261274

Result**✗ Failed****Fail** Offside Front Headlamp not working on main beam (4.1.1 (a) (ii))**Fail** Offside Rear Outer Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced sill (6.1.1 (c) (i))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))**Fail** Nearside Front Suspension arm pin or bush excessively worn rear one (5.3.4 (a) (i))**Fail** Offside Front Direction indicator not working (4.4.1 (a) (ii))**MOT #14**

2021-06-09 12:23

MOT test number

456011484333

Result**✓ Passed****MOT #13**

2021-06-09 12:23

MOT test number

933372033908

Result**✗ Failed****Pass with rectification** Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))**MOT #12**

2020-07-03 14:17

MOT test number

603787572010

Result**✓ Passed****Advice** Child seat fitted in rear so both rear seat belts not checked**Advice** Front two tyres are getting low**MOT #11**

2019-07-26 12:55

MOT test number

839825952351

Result**✓ Passed**

**MOT #10** 2019-07-24 11:14**MOT test number** 255666142364**Result** ✗ Failed**Fail** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Offside Front Headlamp aim too high (4.1.2 (a))**MOT #9** 2018-07-30 09:34**MOT test number** 141456434156**Result** ✓ Passed**MOT #8** 2017-07-25 12:42**MOT test number** 258556431403**Result** ✓ Passed**MOT #7** 2016-08-04 15:31**MOT test number** 709668411125**Result** ✓ Passed**MOT #6** 2016-08-04 08:03**MOT test number** 178742221253**Result** ✓ Passed**Advice** Offside Front front brake fluctuating, but not excessively (3.7.B.3)**Advice** Nearside Rear front parking (secondary) brake grabbing slightly (3.7.B.6b)**Advice** Nearside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)**Advice** Nearside Front front brake fluctuating, but not excessively (3.7.B.3)**Advice** Centre Rear exhaust system corroded**Advice** Offside Rear front parking (secondary) brake grabbing slightly (3.7.B.6b)**Advice** Offside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)

**MOT #5** 2016-08-03 15:26**MOT test number** 189551230451**Result** ✗ Failed**Advice** Centre Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Centre Rear exhaust system corroded**Advice** Offside Front front brake fluctuating, but not excessively (3.7.B.3)**Advice** Nearside Rear front parking (secondary) brake grabbing slightly (3.7.B.6b)**Advice** Nearside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)**Advice** Nearside Front front brake fluctuating, but not excessively (3.7.B.3)**Advice** Offside Rear front parking (secondary) brake grabbing slightly (3.7.B.6b)**Advice** Offside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)**MOT #4** 2015-10-01 09:42**MOT test number** 418226380088**Result** ✓ Passed**MOT #3** 2014-10-01 11:58**MOT test number** 835404474267**Result** ✓ Passed**MOT #2** 2013-10-07 15:03**MOT test number** 619660783233**Result** ✓ Passed**MOT #1** 2013-03-04 16:31**MOT test number** 105823963483**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
27 September 2023

✓

MOT

Expires:
10 July 2024

Tax status	Expired at 27 September
Days left	216 days too late
MOT expiry date	10 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 YY100JM
Plate since	2024-03-29
Current registration	 YY100JM
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-06-16
Last registration	2023-07-06
Complete history	See info



Registration #1	2010-06-16	17 mi
Registration #2	2013-03-04	27.462 mi
Registration #3	2013-10-07	33.554 mi
Registration #4	2014-10-01	37.796 mi
Registration #5	2015-10-01	43.382 mi
Registration #6	2016-08-03	48.233 mi
Registration #7	2016-08-04	48.233 mi
Registration #8	2016-08-04	48.233 mi
Registration #9	2017-07-25	52.793 mi
Registration #10	2018-07-30	56.311 mi
Registration #11	2019-06-20	59.377 mi
Registration #12	2019-06-20	59.377 mi
Registration #13	2019-06-20	59.377 mi
Registration #14	2019-06-20	59.377 mi
Registration #15	2019-06-20	59.377 mi
Registration #16	2019-06-20	59.377 mi
Registration #17	2019-06-20	59.377 mi
Registration #18	2019-06-20	59.377 mi
Registration #19	2019-06-20	59.377 mi
Registration #20	2019-06-20	59.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1682 mm
Height	1485 mm
Length	3970 mm
Wheel base	2470 mm
Kerb weight	1088 kg
Max. allowed weight	1570 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	CBZ 024368