



report date: 2024-03-29

General information

Make	VAUXHALL
Model	VIVA SE AC
Colour	Red
Year of manufacture	2016
Top speed	106 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	95 Nm at 4.500 rpm
Engine capacity	999 cc
Cylinders	3
Fuel type	Petrol
Consumption city	50.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	104 g/km
CO2 label	B





Internet history

Entry 3

Date	2023-08-22
Pictures	0
Listing price	View report

source: carcraft.co.uk

Entry 2



Date	2023-08-06
Pictures	1
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-01-21
Pictures	19
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2024-09-11
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	9
Total items failed	3

MOT #7	2023-09-12 09:07
MOT test number	754258421198
Result	✓ Passed
Next expiry date	2024-09-11

MOT #6	2023-09-08 12:25
MOT test number	669799665207
Result	✗ Failed
Fail	Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Fail	Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

MOT #5	2022-11-29 12:18
MOT test number	225666509575
Result	✓ Passed

MOT #4	2021-12-02 14:38
MOT test number	246910243742
Result	✓ Passed

**MOT #3** 2020-12-02 14:26**MOT test number** 270878564894**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #2** 2019-12-27 12:37**MOT test number** 820433219688**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Lower Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Front Lower Windscreen damaged but not adversely affecting driver's view Zone A area (3.2 (a) (i))**Advice** Front Tyre worn close to legal limit/worn on edge Both Tyres. Replace ASAP (5.2.3 (e))**MOT #1** 2019-12-27 09:24**MOT test number** 419061980055**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Front Lower Windscreen damaged but not adversely affecting driver's view Zone A area (3.2 (a) (i))**Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Front Tyre worn close to legal limit/worn on edge Both Tyres. Replace ASAP (5.2.3 (e))**Advice** Front Lower Oil leak, but not excessive (8.4.1 (a) (i))



Tax & MOT check

X

Untaxed

Tax expired:
4 April 2024

✓

MOT

Expires:
11 September 2024

Tax status	Expired at 4 April 2024
Days left	26 days too late
MOT expiry date	11 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	VO66WZA
Plate since	2019-06-29
Current registration	VO66WZA
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-09-28
Last registration	2023-09-12
Complete history	See info



Registration #1	2016-09-28	11 mi
Registration #2	2019-12-27	34.084 mi
Registration #3	2019-12-27	34.102 mi
Registration #4	2020-12-02	41.209 mi
Registration #5	2021-12-02	55.889 mi
Registration #6		
Registration #7		
Registration #8		
Registration #9		
Registration #10		
Registration #11		

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	52%
Children	91%
Pedestrian	53%
Safety systems	57%
Overall rating	61%
Video	see crash video



Dimensions & weight

Width	1876 mm
Height	1485 mm
Length	3675 mm
Wheel base	2385 mm
Kerb weight	864 kg
Max. allowed weight	1353 kg

Additional information

Fuel tank capacity	32 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	L5Q 162040084L5Q