



YPIOHYJ

report date: 2024-03-28

General information

Make	FORD
Model	TRANSIT 260 LR P/V
Colour	White
Year of manufacture	-
Gearbox	5 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	250 Nm at 2.200 rpm
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN

**MOT history**

MOT #14	2023-07-14 17:47
MOT test number	319917910501
Result	✓ Passed
Next expiry date	2024-07-13

MOT #13	2022-05-19 09:35
MOT test number	177904065067
Result	✓ Passed

MOT #12	2021-03-30 16:43
MOT test number	754418654976
Result	✓ Passed

MOT #11	2020-01-30 08:44
MOT test number	515230609946
Result	✓ Passed

MOT #10	2019-01-30 08:15
MOT test number	290690581774
Result	✓ Passed

Advice Offside Rear inner wheel arch corroded non prescribed area

MOT #9	2019-01-29 15:17
MOT test number	507216208292
Result	✗ Failed

MAJOR Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

MAJOR Offside Rear Direction indicator incorrect colour (4.4.3 (a))

Advice Offside Rear inner wheel arch corroded non prescribed area

MAJOR Nearside Rear Direction indicator incorrect colour (4.4.3 (a))

MAJOR Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**MOT #8**

2018-02-08 10:25

MOT test number

918415250728

Result

✓ Passed

Advice Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt both sides (2.4.G.2)

Advice Nearside Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Advice Front Suspension arm has slight play in a pin/bush both sides, lower arm rear bushes (2.4.G.2)

Advice Rear brake disc worn, pitted or scored, but not seriously weakened both sides (3.5.1i)

Advice Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

MOT #7

2018-02-08 10:25

MOT test number

969471401401

Result

✗ Failed

Advice Nearside Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Advice Front Suspension arm has slight play in a pin/bush both sides, lower arm rear bushes (2.4.G.2)

Advice Rear brake disc worn, pitted or scored, but not seriously weakened both sides (3.5.1i)

Advice Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

Advice Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt both sides (2.4.G.2)

Pass with rectification Front Windscreen washer provides insufficient washer liquid both sides, topped up washer bottle (8.2.3)

MOT #6

2016-11-03 09:42

MOT test number

302110621462

Result

✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #5

2015-09-16 09:38

MOT test number

203231053090

Result

✓ Passed



MOT #4	2015-09-16 09:38
MOT test number	397565855773
Result	✗ Failed
Pass with rectification	Nearside Stop lamp not working (1.2.1b)

MOT #3	2014-09-25 08:56
MOT test number	158598464217
Result	✓ Passed

MOT #2	2013-07-30 13:10
MOT test number	307581413293
Result	✓ Passed
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #1

2013-07-30 13:10

MOT test number

647891313206

Result

✖ Failed

Pass with rectification

Nearside Registration plate lamp not working (1.1.C.1d)

Advice

Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Advice

Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice

Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Pass with rectification

Offside Stop lamp not working (1.2.1b)

Pass with rectification

Nearside Headlamp aim too high (1.8)

Advice

Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-06-07
Last registration	2023-07-14
Complete history	See info



Registration #1	2010-06-07	17 mi
Registration #2	2013-07-30	80.510 mi
Registration #3	2014-09-25	100.174 mi
Registration #4	2015-09-16	118.238 mi
Registration #5	2015-09-16	118.238 mi
Registration #6	2016-11-03	126.211 mi
Registration #7	2018-02-08	142.309 mi
Registration #8	2019-05-29	151.277 mi
Registration #9	2019-05-29	151.277 mi
Registration #10	2019-05-29	151.277 mi
Registration #11	2019-05-29	151.277 mi
Registration #12	2019-05-29	151.277 mi
Registration #13	2019-05-29	151.277 mi
Registration #14	2019-05-29	151.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1974 mm
Height	1989 mm
Length	4863 mm
Wheel base	3300 mm
Kerb weight	1699 kg
Max. allowed weight	2600 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of seats	3
Number of axles	2
Engine number	AU65513