




report date: 2024-03-28

General information

Make	CITROEN
Model	RELAY 35 L2H2 ENTERPRISE BLUEHDI
Colour	White
Year of manufacture	2019
Top speed	92 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	350 Nm at 1.750 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	47.9 mpg
Consumption combined	45.6 mpg
CO2 emission	163 g/km
CO2 label	G






Internet history

Entry 1

Date	2022-08-04
Pictures	6
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-06
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	9
Total items failed	10

MOT #5	2023-09-07 14:27
MOT test number	450101898307
Result	✓ Passed
Next expiry date	2024-09-06

MOT #4	2023-09-02 09:49
MOT test number	759928503293

Result	✗ Failed
Fail	Offside Rear Parking (secondary brake) on a single line braking system has inadequate effort at a wheel (1.3.1 (a) (i))
Fail	Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Fail	Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
Fail	Nearside Rear Parking (secondary brake) on a single line braking system has inadequate effort at a wheel (1.3.1 (a) (i))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Fail	Horn not working (7.7 (a))
Fail	Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
Fail	Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

**MOT #3** 2022-09-05 13:12**MOT test number** 104119360281**Result** ✓ Passed**Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**MOT #2** 2022-06-20 08:18**MOT test number** 573181496556**Result** ✓ Passed**Minor** Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Lower Suspension arm ball joint has slight play swivel (5.3.4 (a) (i))**MOT #1** 2022-06-06 08:29**MOT test number** 945726538308**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear tyre stepped tread**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))



Tax & MOT check

✓
Taxed

Tax due:
1 November 2024

✓
MOT

Expires:
6 September 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	6 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2019-02-08
Last registration	2023-09-07
Complete history	See info



Registration #1	2019-02-08	18 mi
Registration #2	2022-06-06	40.840 mi
Registration #3	2022-06-20	40.846 mi
Registration #4	2023-09-07	40.846 mi
Registration #5	2023-09-07	40.846 mi
Registration #6	2023-09-07	40.846 mi
Registration #7	2023-09-07	40.846 mi

More info >



Safety ratings

NCAP rating	★★★★
Adult	59%
Children	86%
Pedestrian	26%
Safety systems	26%
Overall rating	54%
Video	see crash video



Dimensions & weight

Width	2508 mm
Height	2524 mm
Length	5413 mm
Kerb weight	1925 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Number of axles	2
Engine number	DY2Z4002019