



report date: 2024-03-29

General information

Make	VAUXHALL
Model	TIGRA 16V EXCLUSIV
Colour	Blue
Year of manufacture	2006
Top speed	112 mph
0 - 60 mph	12.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	125 Nm at 4.000 rpm
Engine capacity	1.364 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.9 mpg
Consumption extra urban	56.5 mpg
Consumption combined	46.3 mpg
CO2 emission	146 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-07-23
Pictures	20
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-07-31
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	15
Total items failed	11

MOT #19	2023-08-01 14:26
MOT test number	318385729945
Result	✓ Passed
Next expiry date	2024-07-31
Advice	Rear exhurst box brackets corroded

MOT #18	2023-07-25 13:00
MOT test number	523644298047
Result	✗ Failed
Fail	Nearside Front Inner Tyre has a cut in excess of the requirements deep enough to reach the ply or cords splits on inner sidewall (5.2.3 (d) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))
Fail	Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Advice	Rear exhurst box brackets corroded
Advice	Offside Front Tyre has a cut but not deep enough to reach the ply or cords splits on inner sidewall (5.2.3 (d) (i))
Fail	Exhaust fumes causing a danger to health of persons on board center box blowing (6.1.2 (b) (ii))
Fail	Fuel system component leaking fuel filter corroded and leaking (6.1.3 (b) (i))

MOT #17	2022-07-26 14:23
MOT test number	851752893914
Result	✓ Passed

**MOT #16** 2022-07-26 12:35**MOT test number** 119050491101**Result** ✗ Failed**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt INSECURE (6.1.7 (g) (ii))**Fail** Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt INSECURE (6.1.7 (g) (ii))**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #15** 2021-07-27 13:11**MOT test number** 943231721497**Result** ✓ Passed**MOT #14** 2020-09-22 09:39**MOT test number** 158851509411**Result** ✓ Passed**MOT #13** 2019-09-03 10:26**MOT test number** 527662141871**Result** ✓ Passed**Advice** REAR HANDBRAKE CABLES STARTING TO FRAY**Advice** Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #12** 2018-09-12 13:17**MOT test number** 610150105883**Result** ✓ Passed

**MOT #11** 2017-09-23 09:25**MOT test number** 967007782839**Result** ✓ Passed**MOT #10** 2016-08-16 10:39**MOT test number** 387759461983**Result** ✓ Passed**MOT #9** 2015-08-17 00:00**MOT test number** 650871680762**Result** ✓ Passed**MOT #8** 2014-08-21 16:10**MOT test number** 395653534454**Result** ✓ Passed**Notice** Offside rear tyre worn slightly uneven**MOT #7** 2013-07-08 10:55**MOT test number** 148339583192**Result** ✓ Passed**MOT #6** 2012-07-23 10:35**MOT test number** 337395902225**Result** ✓ Passed**MOT #5** 2012-07-23 10:35**MOT test number** 818445102221**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (1.8)**Pass with rectification** Offside Headlamp aim too low (1.8)

**MOT #4** 2011-08-16 10:46**MOT test number** 308878821230**Result** ✓ Passed**Advice** Offside Rear Rear wheel bearing has slight play (2.6.2)**Advice** Nearside Rear wheel bearing has slight play (2.6.2)**MOT #3** 2010-08-17 11:49**MOT test number** 904509020243**Result** ✓ Passed**MOT #2** 2009-08-13 16:29**MOT test number** 534895229254**Result** ✓ Passed**Notice** Nail in offside rear tyre**Notice** OSF Tyre on 1.6mm may be seen as illegal by police**MOT #1** 2009-08-13 12:40**MOT test number** 721645329205**Result** ✗ Failed**Advice** Nearside Rear wheel bearing has slight play (2.6.2)**Notice** Nail in offside rear tyre**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** OSF Tyre on 1.6mm may be seen as illegal by police



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
31 July 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	31 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	YD56DJX
Plate since	2024-03-29
Current registration	YD56DJX
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-09-01
Last registration	2023-08-01
Complete history	See info



Registration #1	2006-09-01	18 mi
Registration #2	2009-08-13	16.592 mi
Registration #3	2009-08-13	16.592 mi
Registration #4	2010-08-17	19.924 mi
Registration #5	2011-08-16	21.473 mi
Registration #6	2012-07-23	22.307 mi
Registration #7	2013-07-08	23.625 mi
Registration #8	2014-08-21	24.941 mi
Registration #9	2015-08-17	25.853 mi
Registration #10	2016-08-16	27.055 mi
Registration #11	2016-08-16	27.055 mi
Registration #12	2016-08-16	27.055 mi
Registration #13	2016-08-16	27.055 mi
Registration #14	2016-08-16	27.055 mi
Registration #15	2016-08-16	27.055 mi
Registration #16	2016-08-16	27.055 mi
Registration #17	2016-08-16	27.055 mi
Registration #18	2016-08-16	27.055 mi
Registration #19	2016-08-16	27.055 mi
Registration #20	2016-08-16	27.055 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1905 mm
Height	1364 mm
Length	3921 mm
Wheel base	2491 mm
Kerb weight	1185 kg
Max. allowed weight	1475 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Engine number	19GK2653