





report date: 2024-03-28

General information

Make	MINI
Model	MINI (R60) COOPER D ALL4
Colour	White
Year of manufacture	2011
Top speed	112 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.600 cc
Cylinders	4
Fuel type	Diesel
Consumption combined	64.2 mpg
CO2 emission	129 g/km
CO2 label	D



CarCheck.co.uk page 1/12



ND61EKF report date: 2024-03-28

Internet history

Entry 1


Date 2021-07-06

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



ND61EKF report date: 2024-03-28

2021-05-29 11:41

MOT history

MOT #11

MOT expiry date	2024-06-29
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	11
Total items failed	9

MOT #13	2023-06-30 13:43
MOT test number	184790032352
Result	✓ Passed
Next expiry date	2024-06-29
Advice Offside Rear Tyre worn close to legal limit/worn on edge 3.5 mm (5.2.3 (e))	

MOT #12		2022-06-08 14:32
MOT test	number	544153747066
Result		✓ Passed
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	

MOT test	number	359457641172
Result		✓ Passed
MOT #10		2020-06-04 13:47
MOT test	number	372455966388
Result		✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/12



Result

ND61EKF

report date: 2024-03-28

✓ Passed

MOT #9	2020-06-02 11:13
MOT test number	569436220371
Result	× Failed
Fail Nearside Front Windscreen wiper does not clear the windscreen effectively	/ (3.4 (b) (ii))
Fail Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #8	2019-07-08 13:35
MOT test number	669257585566
Result	✓ Passed
MOT #7	2018-07-05 12:00
MOT test number	245157565358
Result	✓ Passed
MOT #6	2017-06-24 11:47
MOT test number	256107177448
Result	✓ Passed
MOT #5	2016-06-30 12:03
MOT test number	558908233931
Result	✓ Passed
MOT #4	2015-07-22 13:43
MOT test number	386183405299

CarCheck.co.uk page 4/12



report date: 2024-03-28



MOT #2	2014-12-09 13:38
MOT test number	216103744341
Result	✓ Passed
Notice Engine covers fitted obscuring some components in the engine bay	
Notice Under-trays fitted obscuring some underside components	

MOT #1	2014-12-09 12:16
MOT test number	808573544305
Result	X Failed
Pass with rectification Offside Headlamp aim too high (1.8)	
Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Pass with rectification Nearside Headlamp aim too high (1.8)	
Notice Engine covers fitted obscuring some components in the engine bay	
Fail Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Fail Offside Front front brake excessively fluctuating (3.7.B.3)	
Notice Under-trays fitted obscuring some underside components	

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check

Tax expired: 1 March 2024





Tax status	Expired at 1 March 2024
Days left	59 days too late
MOT expiry date	29 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner	hictor,
UWNEI	nisioiv
OWINCE	THISCOLY

e when miscory		
For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report I		e?
THE PARTY OF THE P		

THE PROPERTY OF THE PROPERTY O		
	More info	>
Plate changes		
See in this check if this MINI had different number plates.		
Number of plates		,
Current registration	UK NEZ	
Plate since		
Current registration	OK SIES	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-12-30
Last registration	2023-06-30
Complete history	See info



Registration #1	2011-12-30	6 mi
Registration #2	2014-12-09	35.338 mi
Registration #3	2014-12-09	35.338 mi
Registration #4	2015-07-22	39.176 mi
Registration #5	2016-06-30	48.839 mi
Registration #6	2017-06-24	59.250 mi
Registration #7	2018-07-05	69.564 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.177 es
Registration #13		11.777 es

7075.75.75

More info >

77.777 86

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1577 mm
Length	4097 mm
Kerb weight	1380 kg
Max. allowed weight	1850 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	71247709

CarCheck.co.uk page 12/12