



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	FOX
Colour	Black
Year of manufacture	2006
Top speed	92 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	146 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-10-12
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-12-14
MOT pass rate	63 %
MOT passed	15
Failed MOT tests	9
Total advice items	60
Total items failed	14

MOT #24	2023-11-29 11:04
MOT test number	880965838980
Result	✓ Passed
Next expiry date	2024-12-14
Minor	Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Items removed from driver's view prior to test

MOT #23	2023-11-28 14:38
MOT test number	983033711957
Result	✗ Failed
Advice	Items removed from driver's view prior to test
Fail	Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Minor	Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #22**

2022-11-30 10:49

**MOT test number**

820465113356

**Result**

✓ Passed

- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement axle bush (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))
- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement axle bush (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #21**

2022-11-28 12:45

**MOT test number**

410541930720

**Result**

✗ Failed

- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement axle bush (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement axle bush (5.3.4 (a) (i))
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #20**

2021-12-15 14:56

**MOT test number**

885272161002

**Result**

✓ Passed

- Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Minor** Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Front passenger door hinge deteriorated but the door can still be readily opened and closed (6.2.3 (c) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Play in steering rack inner joint(s)

**MOT #19**

2021-12-08 16:58

**MOT test number**

831121466556

**Result**

✗ Failed

- Minor** Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Fail** Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Advice** Nearside Front Front passenger door hinge deteriorated but the door can still be readily opened and closed (6.2.3 (c) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Nearside Front Play in steering rack inner joint(s)

**MOT #18** 2020-11-30 18:20**MOT test number** 101475546313**Result** ✓ Passed

- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Rear Coil spring corroded both rear springs corroded (5.3.1 (b) (i))
- Advice** Rear hand brake lever has little travel
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Rear Suspension component pin or bush slightly worn both bonded bushes perishing (5.3.4 (a) (i))

**MOT #17** 2019-06-11 17:26**MOT test number** 512742902950**Result** ✓ Passed

- Advice** Rear Coil spring corroded both rear corroded (5.3.1 (b) (i))
- Advice** Nearside Play in steering rack inner joint(s)

**MOT #16** 2019-06-11 10:40**MOT test number** 336996006691**Result** ✗ Failed

- Advice** Nearside Play in steering rack inner joint(s)
- Fail** Offside Front Brake hose leaking on an air braking system (1.1.12 (c) (i))
- Advice** Rear Coil spring corroded both rear corroded (5.3.1 (b) (i))

**MOT #15**

2019-05-23 16:39

**MOT test number**

238987333183

**Result****✗ Failed****Fail** Offside Front Brake hose connection leaking on an air braking system (1.1.12 (c) (i))**Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))**Advice** Nearside Front Play in steering rack inner joint(s)**Advice** Rear Coil spring corroded both rear coil springs corroded (5.3.1 (b) (i))**MOT #14**

2018-03-22 17:10

**MOT test number**

223437657092

**Result****✓ Passed****Advice** Offside Rear Shock absorber has slight external damage to the casing shrouds loose and shock body corroded (2.7.2a)**Advice** Offside Front Brake hose slightly deteriorated slight cracking (3.6.B.4d)**Advice** Nearside Rear Bonded suspension unit attachment corroded but not seriously weakened front bush separating (2.4.F.1c)**Advice** Nearside Rear Shock absorber has slight external damage to the casing shrouds loose (2.7.2a)**Advice** Central Exhaust has a minor leak of exhaust gases slight blow from middle pipe (7.1.2)**Advice** Offside Rear Bonded suspension unit attachment corroded but not seriously weakened (2.4.F.1c)**Advice** Nearside steering rack end has slight play

**MOT #13**

2018-03-22 17:10

**MOT test number**

949716283272

**Result**

✗ Failed

**Advice** Nearside Rear Shock absorber has slight external damage to the casing shrouds loose (2.7.2a)**Pass with rectification** Offside Headlamp aim too low (1.8)**Advice** Central Exhaust has a minor leak of exhaust gases slight blow from middle pipe (7.1.2)**Advice** Nearside steering rack end has slight play**Advice** Offside Rear Bonded suspension unit attachment corroded but not seriously weakened (2.4.F.1c)**Advice** Offside Rear Shock absorber has slight external damage to the casing shrouds loose and shock body corroded (2.7.2a)**Pass with rectification** Nearside Headlamp aim too low (1.8)**Advice** Offside Front Brake hose slightly deteriorated slight cracking (3.6.B.4d)**Advice** Nearside Rear Bonded suspension unit attachment corroded but not seriously weakened front bush separating (2.4.F.1c)**MOT #12**

2017-03-15 16:40

**MOT test number**

277676056475

**Result**

✓ Passed

**MOT #11**

2017-03-15 15:42

**MOT test number**

551193855312

**Result**

✗ Failed

**Fail** Offside Front Front position lamp(s) not working side light (1.1.A.3b)**Fail** Nearside Rear rear brake binding (3.7.B.1)**Fail** Nearside Front Front position lamp(s) incorrect colour side light (1.1.A.3e)**MOT #10**

2016-03-23 15:48

**MOT test number**

869838428594

**Result**

✓ Passed



**MOT #9** 2015-05-14 13:56**MOT test number** 365594435154**Result** ✓ Passed**MOT #8** 2014-05-21 14:41**MOT test number** 277321744144**Result** ✓ Passed**Advice** Nearside Front Suspension arm has slight play in a pin/bush (2.4.G.2)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Rear exhaust deteriorated.**Advice** Offside Front Suspension arm has slight play in a pin/bush (2.4.G.2)**MOT #7** 2013-05-15 16:30**MOT test number** 567575133178**Result** ✓ Passed**MOT #6** 2012-05-10 11:13**MOT test number** 238221232120**Result** ✓ Passed**MOT #5** 2011-04-18 15:50**MOT test number** 589728201158**Result** ✓ Passed**MOT #4** 2011-04-18 13:51**MOT test number** 545438401145**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Front constant velocity joint gaiter split (2.5.C.1a)



MOT #3	2010-04-20 11:23
MOT test number	830440810172
Result	✓ Passed

MOT #2	2010-04-19 12:03
MOT test number	971949300149
Result	✗ Failed
Fail	Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)
Fail	Nearside Front constant velocity joint gaiter split (2.5.C.1a)

MOT #1	2009-03-11 11:48
MOT test number	680570079060
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
14 December 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	125
<b>MOT expiry date</b>	14 December 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history


For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>CX06ZTT</b>
Plate since	2024-03-28
Current registration	 <b>CX06ZTT</b>
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2006-06-19
Last registration	2023-11-29
Complete history	<a href="#">See info</a>



Registration #1	2006-06-19	16 mi
Registration #2	2009-03-11	25.193 mi
Registration #3	2010-04-19	47.506 mi
Registration #4	2010-04-20	47.507 mi
Registration #5	2011-04-18	60.225 mi
Registration #6	2011-04-18	60.226 mi
Registration #7	2012-05-10	67.576 mi
Registration #8	2013-05-15	74.990 mi
Registration #9	2014-05-21	78.878 mi
Registration #10	2015-05-14	90.580 mi
Registration #11	2016-03-23	100.562 mi
Registration #12	2017-03-15	112.359 mi
Registration #13	2018-03-20	125.277 mi
Registration #14	2019-03-20	135.277 mi
Registration #15	2020-03-20	145.277 mi
Registration #16	2021-03-20	155.277 mi
Registration #17	2022-03-20	165.277 mi
Registration #18	2023-03-20	175.277 mi
Registration #19	2024-03-20	185.277 mi
Registration #20	2025-03-20	195.277 mi
Registration #21	2026-03-20	205.277 mi
Registration #22	2027-03-20	215.277 mi
Registration #23	2028-03-20	225.277 mi
Registration #24	2029-03-20	235.277 mi

More info >





Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BMD 255340